List of Classified Structures



Thomas Stone
National Historic Site

List of Classified Structures
Thomas Stone National Historic Site
Park Index

	LCS ID	Park	Preferred Structure Name	Structure Number▲	Structure Condition	Year Condition Assessed	Last Updated
1.	080059	THST	Thomas Stone House	01	Good	2002	09/23/2002 09:16am
2.	251741	THST	Thomas Stone Formal Garden Terraces	01.1	Good	2002	09/30/2002 04:25pm
3.	251183	THST	Thomas Stone Entrance Road A	01.A	Good	2002	09/30/2002 04:25pm
4.	251297	THST	Thomas Stone Formal Entance Lane Trace	01.AA	Fair	2002	09/30/2002 04:25pm
5.	251200	THST	Thomas Stone Entrance Road B	01.B	Good	2002	09/30/2002 04:25pm
6.	251265	THST	Hitching Post	01.C	Good	2002	09/30/2002 04:25pm
7.	251286	THST	Sheep Barn Farm Lane	01.D	Fair	2002	09/30/2002 04:25pm
8.	080060	THST	Tobacco Barn	02	Good	2002	09/23/2002 09:16am
9.	251230	THST	Old Glymont Road	02.A	Unknown	2002	09/30/2002 04:25pm
10.	251244	THST	Lane to Glymont Road	02.B	Good	2002	09/30/2002 04:25pm
11.	251272	THST	Tenant House Lane	02.C	Fair	2002	09/30/2002 04:25pm
12.	080061	THST	Corn Crib	03	Poor	2002	09/23/2002 09:16am
13.	080063	THST	Tenant House	04	Poor	2002	09/23/2002 09:16am
14.	080064	THST	Horse Barn	05	Poor	2002	09/23/2002 09:16am
15.	251322	THST	Sheep Barn Ruin	07	Poor	2002	09/30/2002 04:25pm
16.	251146	THST	Thomas Stone Burial Ground Fence	12.A	Good	2002	09/30/2002 04:25pm
17.	080071	THST	Thomas Stone Burial Ground Markers	12.B	Good	2002	09/23/2002 09:16am

LIST OF CLASSIFIED STRUCTURES (LCS)
PARK/STRUCTURE INDEX

ALPHA CODE	STRC NUM	IDLCS	STRUCTURE NAME
THST	01	80059	THOMAS STONE HOUSE
THST	02	80060	TOBACCO BARN
THST	03	80061	CORN CRIB
THST	04	80063	TENANT HOUSE
THST	05	80064	HORSE BARN
THST	10	80069	CATTLE BARN
THST	12	80071	BURIAL GROUND

TOTAL FOR PARK: 7

GEWA/THST LCS UPDATE SUMMARY

GEWA

Existing Listings	7		
New Listings	12		
Delisted Structures	2		
TOTAL LCS UPDATE LISTINGS	17	TOTAL DOEs	24

THST

Existing Listings	13		
New Listings	0		
Delisted Structures	6		
TOTAL LCS UPDATE LISTINGS	7	TOTAL DOEs	7

THST

LCS STRUCTURES

80059	01	Thomas Stone House	
80060	02	Tobacco Barn	
80061	03	Corn Crib	
80063	04	Tenant's House	
80064	05	Horse Barn	
80069	10	Cattle Barn	
80071	12	Stone Family Burial Ground	

DOEs

		Chicken House Complex (Maintenance Facility)	"Probable RM" in GMP
		Farm Shed	"Further Doc Needed" in GMP
80066	07	Feeding Station (aka Sheep Shed in old LCS-error)	"Probable RM" in GMP
		Hog Shed (Hog Barn)	"Probable RM" in GMP
		Modern Swimming Pool	RM recommendation in GMP
		Sheep Shed Ruin	Collapsed (Loss of Integrity)
		20th C. Field Fences	RM recommendation in GMP
DOE done		Formal Garden	
DOE done		Garden House	
DOE done		Apartment/Garage (Contact Station)	
DOE done		Stock Pond	

DELISTED STRUCTURES

80065	06	Carriage Shed (Removed)
80066	07	Feeding Station
80067	08	Garden House (Removed)
80068	09	Apartment/Garage (DOE)
80070	11	Formal Garden (DOE)
80072	13	Stock Pond (DOE)

Maryland Comprehensive Historic Preservation Plan Data

Thomas Stone National Historic Site

Geographic Organization
- Western Shore (Charles County)

Chronological/Developmental Periods
- Late Archaic (4000-2000 B.C.)
- Contact and Settlement Period (A.D. 1570-1750)
- Rural Agrarian Intensification (A.D. 1680-1815)
- Agricultural-Industrial Transition (A.D. 1815-1870)
- Industrial-Urban Dominance (A.D. 1870-1930)

Prehistoric Period Themes
- Subsistence

Historic Period Themes
- Agriculture
- Architecture/Landscape Architecture/Community Planning
- Government/Law

Resource Type:
- Category: District
- Historic Environment: Rural

Historic Function(s) and Use(s):
- Domestic/Single Dwelling
- Funerary/Cemetery
- Agriculture/Subsistence/Agricultural Field
- Agricultural/Subsistence/Animal Facility

Known Design Source: unknown

OMB Approval No. 1024-0018

United States Department of the Interior
National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines for Completing National Register Forms* (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

1. Name of Property

historic name Thomas Stone National Historic Site (THST)

other names / site number Haberdeventure; Stone, Thomas, House; Habre-de-Venture; Habre de Venture; Habberdeventure

2. Location

street & number Rose Hill Road, between State Routes 6 and 225 [ ] not for publication

city, town Port Tobacco [NA] vicinity

state Maryland **code** MD **county** Charles **code** 017 **zip code** 20667

Site inventory number CH5

3. Classification

Ownership of Property	Category of Property	Number of Resources within Property		
		Contributing	Noncontributing	
[X] private	[ ] building(s)			
[ ] public-local	[X] district	005	005	buildings
[ ] public-State	[ ] site	003	001	sites
[X] public-Federal	[ ] structure	006	005	structures
	[ ] object	001	000	objects
		015	011	Total

Name of related multiple property listing:

Number of contributing resources previously listed in the National Register 7

4. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act of 1966, as amended, I hereby certify that this [ ] nomination
[ ] request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic
Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property [ ] meets [ ] does not meet the National Register criteria. [ ] See continuation sheet.

Signature of certifying official Date

Signature or Federal agency and bureau

In my opinion, the property [ ] meets [ ] does not meet the National Register criteria. [ ] See continuation sheet.

Signature of commenting or other official Date

Signature or Federal agency and bureau

5. National Park Service Certification

I, hereby, certify that this property is:

[ ] entered in the National Register.
[ ] See continuation sheet.

[ ] determined eligible for the National Register.
[ ] See continuation sheet.

[ ] determined not eligible for the National Register.

[ ] removed from the National Register.

[ ] other, (explain:) _____

_____

_____ _____

_____ _____

_____ _____

_____ _____

Signature of the Keeper Date

6. Function or Use

Historic Functions (enter categories from instructions)

Domestic: single dwelling
Funerary: cemetery
Agriculture/Subsistence: agricultural field
Agriculture/Subsistence: animal facility

Current Functions (enter categories from instructions)

Recreation and Culture: museum
Recreation and Culture: outdoor recreation
Agriculture/Subsistence: agricultural field
Agriculture/Subsistence: animal facility

7. Description

Architectural Classification (enter categories from instructions)

Colonial/ Georgian

Materials (enter categories from instructions)

foundation Brick
walls Brick
wood/weatherboard
roof wood
other

Describe present and historic physical appearance.

Description Summary

Thomas Stone National Historic Site is situated on 328.25 acres (321.97 NPS; 6.28 private) at the junction of two of Charles County's former principal thoroughfares, the old Port Tobacco-Piscataway Road (Rose Hill Road), and the Port Tobacco-Old Mattawoman Road (Glymont Road). The property, historically called Haberdeventure, was the home of Thomas Stone, one of Maryland's signers of the Declaration of Independence. Although he only lived at Haberdeventure for slightly over a decade, these were the most important years of his political career.

The site's contributing resources include historic buildings and structures, and landscape features, such as the terraces south of the main house, the interrelated agricultural fields and forests, and the circulation system. Its most notable feature is the mansion built by Thomas Stone between 1771 and 1773. The building, a National Historic Landmark, is made up of five sections: the main house, the kitchen wing, the porch, and two hyphens. Built in an arc with the concave side (front) facing generally southward, the mansion was gutted by fire on January 1, 1977. The adjoining hyphens and end buildings were also damaged in varying degrees by fire, smoke, and water. Haberdeventure was partially reconstructed during the 1990s.

The site also includes several outlying historic structures dating from the nineteenth century. These buildings, as well as the mansion and the surrounding landscape, are strongly associated with the Stone family and reflect the nature of agricultural enterprises in late eighteenth and nineteenth century Maryland.

General Description

Topographic features, such as Hoghole Run, which provides the western boundary for the site, and Spring Branch Run, which separates the mansion from the tenant house, are representative of the ravines and swales that characterize the southwestern portion of the site. The northeastern section is relatively flat with broad open fields typical of

[X] See continuation sheet

the formal, public space of the site, and of the agricultural activities that took place in Haberdeventure through the end of the nineteenth century. The terraces located south of the mansion are another important feature. Archeological evidence and design style appear to indicate that they date from the late eighteenth century. Aerial photography (1937) suggests the existence of a formal landscape setting with a broad approach drive which directly linked the mansion with the junction of the two main regional roads: the old Port Tobacco-Piscataway Road and the Port Tobacco-Mattawoman Road.

Archeological Resources

Archeological investigations at Thomas Stone National Historic Site have identified foundations and construction trenches from the original Thomas Stone House structure, and features dating to Stone's occupation. There are also archeological resources associated with the William Briscoe Stone occupation. Most prehistoric sites which have been identified do not meet National Register criteria for significance. Major portions of the property have not been surveyed for archeological resources.

Cultural Landscape

Spatial organization. Although some of the integrity of the individual landscape features surrounding the main house have been lost, land use and circulation patterns remain largely intact. Character-defining features, such as circulation, fields and forests, property boundaries, and surrounding land uses provide a rich context for the interpretation of general farming practices conducted at Haberdeventure through its several periods of occupation.

Designed landscape features include the formal garden terraces possibly dating from the Thomas Stone period, and the cemetery, which retains a great deal of integrity. The ornamental plantings spanning various periods are severely degraded and fragmented and the ponds and swimming pool date from the Vischer era (post-1945).

The site is organized into a hierarchy of four areas: 1) the formal/public entrance area and main house; 2) the working areas north and west of the main house; 3) the outlying fields to the east and south of the main house,

and 4) the natural forested areas around the perimeter of the site.

Historically the formal/public entrance functioned much like it does today, with the entrance roads and farm fields surrounding the main house. The broad, flat, open field which encompasses the main house serves as the formal, public space of the property. It is fully visible from both the entrance to the site, and the main house, and all of the other functional and natural areas of the site relate directly to this central core.

Access to the working areas of the farm located west and north of the main house is physically separated from the main house by a drainage swale which becomes the head of Spring Branch Run. The working areas to the west of the house include the corn crib, the tobacco barn, the tenant house and barns, and the surrounding open fields. Evidence indicates that the fields to the south and east of the main house were cultivated at various times since the area was settled.

The natural forested areas along the perimeter spatially enclose the site. Many of these areas have been farmed during the last two centuries, but vegetation encroachment has produced some visual changes to this portion of the landscape.

Circulation. Conclusive documentary evidence linking the existing layers of access and circulation to certain periods of occupation of the site is not available. However, with the exception of the new access road built in 1992, the remaining entrances drives and lane remnants can be dated conclusively to pre-1911 based on their proximity to pre-existing outbuildings. Therefore the historical location of the access roads and lanes appears to be largely intact. With the loss of some of these outbuildings, the reason for the existence of some of the internal lanes is no longer clear.

Terraces. The terraces located to the south of the main house are a highly significant landscape feature, dating from as early as the late eighteenth century. Conclusive documentary evidence of construction is not available; however, archeological evidence and period style strongly indicate that they may date from the Thomas Stone era.

Field Patterns. The core areas of the property, and the fields surrounding the main house and outbuildings have remained fairly constant over the years. Forest stand analysis indicates that the forest cover in the areas of

the north, east, and southern boundaries of the site have been in forest cover the longest period of time. Forest stands to the east, particularly along Hoghole Run are the youngest stands, indicating that these areas were probably cleared during the late eighteenth century and early nineteenth centuries.

Property Boundaries. The property boundaries date from the Thomas Stone period through the nineteenth century. With minor changes they follow the boundaries set in Thomas Stone's original purchase and those from the William Briscoe Stone period. Although the property boundary markers have long since disappeared, the property retains its integrity in terms of land area.

Cemetery. This is a highly significant feature dating from the late eighteenth century. The tombstones of Thomas Stone, William Briscoe Stone, and their wives remain intact. The wrought iron fence surrounding the burial ground was the work of Stewart Iron Works from Cincinnati, Ohio.

Contributing Resources

1. **Haberdeventure (Thomas Stone House)** LCS 80059 01 (building). The inscription "D. Stone Aug. 1772" in a header near the southeast corner 1 ½" above ground level establishes the construction date for the mansion. D. Stone may has been Thomas Stone's father, David, or more likely his older half-brother, David, of Poynton Manor, who may have overseen the masonry work or the manufacture of bricks for Haberdeventure.

This five-part building complex prior to the devastating 1977 fire could have been described as one of the most picturesque Colonial houses in this section of Maryland. The sequence of the construction of the five components remains conjectural with only the hyphens appearing to be near the age of the central block.

The 1772 brick work on the mansion remains in surprisingly good condition in spite of the great heat of the 1977 fire. Nearly all of it is original, mostly laid in Flemish bond. The exterior walls are exposed to view up to the eaves. Brick work in the end walls, beginning at eave height, becomes common bond up to the roof peak. The chimney brick work also is laid in common bond. In the west end wall, the common bond begins a few courses below the north eave and a few courses of English bond separate the Flemish

from the common. The chimneys in both ends are laid in common bond, with a header course every fourth course below the water table and an average of every sixth course above. Most existing pointing remains in good condition, requiring no replacement.

The central block is a 1 ½ story English raised-over-elevated-basement, brick structure, 24 x 45 feet in size, with a gambrel roof that has three dormered windows on the front and rear elevations. There is an exterior chimney at both ends. The north and south elevations (front and back) are each five bays wide, have center doors and one-story porches extended across both facades. The front porch floor is elevated by brick piers to first-floor level. The back porch floor was a brick structure constructed directly on the ground. Both reconstructed porches were sheltered by hipped roofs running the length of the north and south walls.

A center hall with a stairway against the west wall extends through the house. There is a room on the east side of the hall from which the paneling was removed in 1928 that measures 22' x 18 ½' with a 10'4" high ceiling. The hallway partition on the west side is positioned so that it deprives the first floor west room of about four feet of space in its east-west dimension. The paneling from the east downstairs room was removed by the City of Baltimore for the Baltimore Museum of Art and reconstructed there as the "Haberdeventure room."

By the early years of this century, the second floor plan of the main dwelling portion consisted of three rooms in addition to the hallway. The east room probably measured about 18 ½' x 18 ½', the west room probably 14 ½' x 18 ½'. At the south end of the upstairs hallway was a very small room often used as a guest room or servant's quarters during the early years of this century.

The room in the west hyphen has a fireplace in its east end with flue slanting back to the west wall of the main building and into the chimney at that end at ceiling level. It has a gently vaulted ceiling. The west hyphen floor is about 3 ½' below that of the central mass. Margaret G. Stone used this room as her kitchen while she was the mistress of Haberdeventure from 1872 to 1913. At that time a second floor was added to accommodate modern bathroom facilities and a south-side hallway to the kitchen wing second floor. The hyphen was then given a gambrel roof and dormers somewhat in the style of the principal center structure. The roof was covered by wood

shingles.

The kitchen wing (18' x 33'), built ca. 1830-1840, is a brick-end, gable-roof structure with centered end chimneys. The sides are framed with overlapping horizontal wood siding. This structure is brick nogged, including the center hallway partitions. It is built at a right angle to the west hyphen. The quality of design and construction indicate that at least the second story was meant for family, not servant, use. The first-floor fireplaces were designed, at least in part, for kitchen use. Design, materials, and construction details strongly suggest mid-Federal period origin. The roof is covered with wood shingles.

The east wing is joined to the main center structure by a partly enclosed walk-through brick hyphen constructed around 1775. Only the roof of this hyphen connects directly with the east wing. Under this is a walk-through 6' wide. Entrance to the hyphen enclosure is through what appears to be an original, 6' x 5' wooden doorway that opens to a concrete ramp inside that leads down to a basement entrance partly below grade at the southeast corner of the main house. The east hyphen is 9'6" wide, 18'9" long on the north side and 16'9" long on the south side. The roof is also covered with wood shingles.

The frame, gambrel-roofed east wing, ca. 1775, may not always have been located on this site since it does not fit squarely on its brick foundation, as disclosed by an archeological excavation in 1986. This wing, often called "Thomas Stone's law office," which measures 18'5" x 16'6", is a two-room building (one up, one down). It has a soft orange brick-exterior chimney centered on its southeast-facing end. The chimney has been removed to allow stabilization and reconstruction. Inside, a small enclosed stairway on the west wall leads to the second-floor room. The wooden floors in both of these rooms are not original. The roof is covered with wood shingles.

2. The **tobacco barn**, LCS 80060 02 (building), was erected around 1830 to 1840. The original building measured 20' x 44', and the roof ridge was nearly 30' above grade. The tobacco barn is a five-bay, gable-roof structure with vertical wood siding. The roof ridge is oriented on an east-west axis. The building was apparently re-sided and enlarged early in this century and was restored in 1989-1990. A forebay, added to the south side, still has half a dozen cattle stanchions. Some of the framing timbers in the original barn were pit sawn and hand hewn. For many years the forebay covered the

original wood siding and roofing on the south side. Several pine boards, measuring 15" to 18" in width, in excellent condition are still in place on the original building. There is only an earthen floor. The barn now rests on a mix of solid poured concrete foundation and cinder block-concrete piers. The roof is presently sheathed with galvanized steel.

3. The **corn crib**, LCS 80061 03 (structure), dating from the same period as the tobacco barn, is a frame structure constructed on combination brick-stone piers. It is covered by a gable roof also sheathed with galvanized steel. It is supported underneath on an east-west axis by four original brick piers, which are in addition to the peripheral pier supports. The wooden floor is raised an average of three feet above grade. Each pier is insulated from the wood construction by a soft, thin metal shield. The roof extends a little over a foot beyond the four walls. Along three sides are covered exterior stock feeding troughs, probably added within the past 40-50 years. The corn crib measures 15'7" x 26'11". The two ends rooms of the corn crib are entered by two original, but altered, wooden doors from a central hall-like room. One of these doors appears to have an original, wooden lock still in place.

4. The **tenant house**, LCS 80063 04 (building), was built between 1840 and 1859 and was enlarged between 1949 and 1959. This extremely modest frame structure, a story and a half, with three small rooms on the first floor was enlarged with two one-room additions. The southern one measures 13'6" x 13'3" and the west one 10'4" x 10'4". The original main part of the house measures 14'3" x 13'3". Across the east side of the old structure is a 10' x 26' screened porch, probably of mid-20th century construction. The tenant house rests nearly at grade on a 20th century concrete footing. It appears to have been moved here from a nearby site during this century. The steeply pitched (18th century style) roof is sheathed with galvanized steel.

5. The **horse barn**, LCS 80064 05 (building), dates from the same period as the tenant house. It is an all-frame (sheathed random width clapboard siding) structure with gable roof (covered with galvanized metal) oriented roughly on a north-south axis. The north half is by far the older and rests on a fieldstone-mortar foundation. It measures 30' x 24'. The floor is earthen throughout.

6. The **cattle barn/equipment shed**, LCS 80069 10 (building). Its oldest portion was originally a tobacco barn dating from 1869-79 and ca. 1925-59.

The cattle shed forebay is constructed along the entire original south side of the barn and appears to have been built early in this century. The original tobacco barn portion of this structure measures about 28' x 108'. There is an earthen floor throughout. The structure has a galvanized metal roof. The building rests on a variety of brick, stone, and wood materials. The gable roof ridge is oriented along an east-west axis.

7. The **burial ground**, LCS 80071 12 (site), which was used between 1787 and 1913 is another important contributing resource. It is located in the field east of the main house and is bounded on the south and east by a wooded area and a branch of Hoghole Run. To the north and west, it is bounded by a grassy field. It contains primarily Stone family grave sites, but includes a few of distant relatives. The latest Stone family burial was that of Miss Margaret Graham Stone who died in 1913. The burial ground includes 13 east-facing grave markers in three rows. Several of the cut stone monuments are the work of sculptor A. Gaddes of Baltimore.

This burial ground lies about 300' southeast of the Haberdeventure manor house. Immediately east of the fence-in Stone cemetery is an unfenced wooded section of ground about the same size as the fenced area in which black servants and employees were interred, at least during the twentieth century. Documentation for the location and use of the black cemetery has been based primarily on an early 1988 taped interview with Charles Jones Woodland, of Ripley, Maryland. He has testified that his grandfather Cornelius Woodland, who was an employee of Margaret G. Stone, is buried at the Stone cemetery. Members of the Stone family who still reside in the area remember this as the cemetery for African Americans. Whether it ever served as a burial place for slaves remains to be determined.

8. The cemetery is surrounded by a wrought **iron fence** (object, not listed separately in the LCS) dating from the 1860s which measures 32' x 32'. It was the work of Stewart Iron Works of Cincinnati, Ohio.

9. The **terraces** (sites), not yet on the LCS, located to the south of the mansion are an important contributing resource. Although there is no conclusive documentation, archeological evidence and style suggest that they may date from the Thomas Stone era. They are composed of three flat areas, broken by two falls which are connected by earthen ramps. There has been some erosion and settling over the last two centuries; however, the terraces conform well to the typical design and proportions of the period.

Archeological evidence suggests that the upper terrace was designed as a bowling green, or a simple expanse of lawn. The middle terrace, however, was composed of formally designed planting beds, although the types and placements of the plants cannot be established. It is also not known how the lower terrace was planted. Plowing of the garden in the late 19th or early 20th century destroyed most of the evidence of the plantings, particularly in the lower terraces where tobacco was grown during the 1930s.

10-14. The four **roads** and **traces of lanes** (structures), not yet in the LCS, that provide access to Haberdeventure and those within the site are important landscape elements. The existing formal entrance drive off Rose Hill Road (labeled A in the sketch map) which makes a right turn toward the mansion, has been in use throughout the 20th century. It is not possible to establish if this was the main access road prior to 1911.

The drive south of the existing formal drive (labeled B in the sketch map) was also used concurrently during the first half of the 20th century until the construction of the stock pond near the junction of the two drives.

Another access road approaches Haberdeventure from the north (labeled C in the sketch map) starting at the old Glymont Road. This road was utilized during the early decades of the 20th century, but it is not possible to establish the period of its earliest use.

It is not clear, when and if, the other northern access road (labeled D in the sketch map) was in use. Its location and design are consistent with late eighteenth century design principles. Some physical evidence suggests that this might have been a formal entrance drive which aligned itself with the center point of the mansion and with the terrace ramps. Its location at the junction of two of the principal roads in Charles County would help to call attention to Haberdeventure and increase its status, an important factor in landscape design during the late eighteenth century.

Circulation within the site has not been altered substantially. A lane leading to a stable or corn crib next to the east hyphen and another one running to a small pond north-west of the tenant house have been lost. Others lanes can be dated to the nineteenth century based on their proximity to the existing buildings.

15. The **field patterns and forest stands** (site) also bear testimony to the

history and agricultural management of the Haberdeventure estate. Farming practices during the seventeenth and eighteenth centuries involved the clearing of land and the planting of crops for a period of one to three years. This was followed by a long period in which the land was left uncultivated, sometimes as much as twenty years. Documents suggest that the fields around the mansion and the tenant house were cleared during Thomas Stone's occupation as were the bottomlands along Hoghole Run. Analysis of the existing forest stands to the north and south of the property reveals that they are as much as 250 years old. The stands along the western perimeter of the property are 150 to 200 years old.

There is also indication that a certain amount of timbering was done on the properties Thomas Stone owned. The timber was harvested primarily for cordwood to make charcoal for the operation of a forge at Stone's mill in Port Tobacco.

Non-contributing resources at Thomas Stone National Historic Site, which will eventually be removed, include the following:

1. Two-story brick garage (building) is near the west end of the main house. It has three automobile bays on the first floor and a five-room apartment upstairs, ca. 1958.
2. The formal garden (site) is located about 100 feet southeast of the main house, ca. 1950.
3. The horse barn (building) is parallel and to the east of the historic horse barn, ca. 1940.
4. The hog shed, aka hog barn (building), is a half-masonry, half-frame structure located about 100 feet southwest of the corn crib, ca. 1930-1950.
5. Feeding station (structure) is a frame structure made of wooden boards and a corrugated metal roof, ca. 1900-1930.
6. Farm shed (building) is log-frame building located on west side of south farm road between the stock pond and the sheep shed ruin, construction date not known, ca. 1950.
7. A cinder block building (building) used as chicken coop and poultry processing house is located a few hundred feet north of the inholder's residence, ca. 1950s.
8. The stock pond (structure) is east of main entrance road, ca. 1960.
9. The concrete-lined swimming pool (structure) which is west of the mansion has been filled with dirt and is barely visible, ca. 1955.
10. Lemko property. In 1974 the Vischers gave Andrij and Nadiya Lemko,

the estate's farm managers, a 6.3-acre tract running into the north-central part of the site. The following year the Lemkos received 22 additional acres on the southern edge of the property.

8. Statement of Significance

Certifying official has considered the significance of this property in relation to other properties:

[X] nationally [ ] statewide [ ] locally

Applicable National Register Criteria [X] A [X] B [X] C [X] D

Criteria Considerations (Exceptions) [ ] A [ ] B [ ] C [X] D [ ] E [ ] F [ ] G

Areas of Significance (enter categories from instructions)

Politics/Government (N)
Agriculture (L)
Archeology: Historic Non-Aboriginal (N & L)
Architecture (S & L)

Period of Significance

1770-1900

Significant Dates

1771-1787

Cultural Affiliation

n/a

Significant Person

Stone, Thomas
Stone, William Briscoe

Architect/Builder

n/a

State significance of property, and justify criteria, criteria considerations, and areas & periods of significance noted above.

Significance Summary

The Thomas Stone National Historic Site is nationally significant for politics/government because it was the home of one of the signers of the Declaration of Independence. Haberdeventure, the historic name of the property, includes the mansion and terraces Stone had built as well as the cemetery where Stone and other members of his family were buried. The archeological resources associated with the Thomas Stone House are nationally significant under criteria B for their association with Thomas Stone; and criteria D because they contain potential information on activities and trends important to the understanding of eighteenth century life during the Thomas Stone era. The house is significant at the state and local level for architecture, and the farm structures comprise an assemblage of local significance. Haberdeventure is also significant at the local level as a fine example of a nineteenth century agricultural landscape and of the agricultural operations that were common in the Chesapeake in the century following the Declaration of Independence. Resources associated with the William Briscoe Stone occupation are significant at the local level for their potential to provide information on activities and trends important to the understanding of mid-nineteenth century life.

Resource History and Historic Context

Thomas Stone, the youngest signer of the Declaration of Independence from Maryland, purchased Haberdeventure in 1770 and began constructing a new house on the property during the following year. The mansion was probably completed at the end of 1773. Thomas and Margaret Stone and their three children lived at Haberdeventure until they moved to Annapolis about the middle of 1783. After Mrs. Stone's death in June 1787, Thomas returned to Haberdeventure where he apparently lived until his death in October of the same year (Stone's Annapolis townshouse, the "Peggy Stewart House," which was also the residence of Daniel St. Thomas Jenifer, another signer of the Constitution, is another National Historic Landmark property).

Even while calling Haberdeventure home from 1770 to 1783, Stone spent much time away from Charles County. After leaving the Continental Congress early in 1777, Stone began to practice law at Port Tobacco in Charles County and in Annapolis. From 1777 until the year of his death Stone served in the Upper House of the Maryland Assembly, and this state government service took him away from his Haberdeventure home. Extant records do not indicate the depth of Stone's involvement in managing the Haberdeventure property. Its condition as a producing plantation seems not to have occupied much of his attention. The administration of Haberdeventure was left very much in the hands of other members of the family, including Stone's wife Margaret and his brother Michael Jenifer Stone, who managed all aspects of the agricultural activities until 1798.

Stone lived at Haberdeventure a relatively short time but these were the most significant years of his political life. Shortly after the signing of the Declaration of Independence, Congress selected Stone to represent Maryland as a member of a small, elite group instructed by Congress to create the framework for a new central political authority that would guide the affairs of state for the new nation.

For over four years Maryland refused to ratify the Articles of Confederation, but by 1781 Stone was able to play a decisive role in reversing Maryland's stand on ratification. By this time some of the major stumbling blocks, such as the question of dealing with the western lands had been resolved.

In March 1784 Stone returned to Philadelphia to represent Maryland in the Congress of the Confederation. Stone was elected chairman and served temporarily as President of the United States in Congress Assembled. During the congressional sessions of 1784 Stone served in committees with some of the most capable and distinguished leaders of Congress.

Although Maryland did not officially participate in the Annapolis Convention, Stone apparently represented Maryland in a rather unofficial capacity at this meeting. Stone was also intimately involved in preparing to participate in the Philadelphia Convention.

After the death of Thomas Stone, Haberdeventure continued to be managed by his brother Michael Jenifer Stone, who had already been in charge of the daily operation of the estate and who continued to do so until 1798. Michael J. Stone is likely to have made additions and improvements to the mansion which in 1798 was ranked among the most valuable residential properties in Charles County.

Michael J. Stone's son William Briscoe Stone, and William's daughter, Margaret Graham Stone were the members of the family who owned and managed the property through most of the nineteenth century.

William Briscoe Stone established residency at the mansion sometime in the early 1820s. When he moved in, the house had been vacant for some time or had been occupied by

careless tenants. Stone apparently made an agreement with his cousin Mildred Stone Daniels, one of Thomas Stone's daughters, and then owner of the property, whereby he would pay for his occupancy and use of the house and land by representing his cousin in her local business affairs and acting as Haberdeventure manager.

By 1831 William B. Stone finally purchased Haberdeventure from his cousin Mildred and started rehabilitation work on the house and then-existing outbuildings. He also initiated the construction of most of the structures that give the property its present character.

William B. Stone practiced law until the 1850s, but relocated his office from Port Tobacco to Haberdeventure by the mid 1830s. His writings and his career indicate that he was more concerned with his house and family than with achieving public recognition in law and politics. His brief and sporadic public service included attending the Whig party convention in Baltimore in 1840, a brief appointment as Chief Judge of Maryland's First Judicial District, and one term in the Maryland Legislature.

Stone's greatest interest, however, appears to have been in the area of agricultural technology. The conventional agricultural methods used in Maryland during the seventeenth and eighteenth centuries wore out land productivity as a result of successive plantings of wheat and tobacco. The introduction of the plow also impacted the sustainability of farming in the area, since plowing was conducted without taking into account erosion potential. William Briscoe Stone's farming notes describe his multi-year experiments in fertilizing and crop rotation. He persisted in his efforts to enhance the productivity of his land at least until the end of the Civil War. The end of slavery created a labor shortage which he addressed through the purchase of mechanized farm equipment. He acquired a gleaner in 1862, a thrasher in 1863, and by the time of his death in 1873 his inventory included additional evidence of labor-saving farm implements.

Margaret Graham Stone, Stone's daughter, assumed the management of the property well before her parents' deaths in 1872 and 1873. Little specific information exists about the management of the property, except for consistent reliance on tenants. Although she might have been quite a capable manager, her declining health as the century progressed led to the physical deterioration of the property. By 1900 she was living only in the main part of the house and the west hyphen, which she had earlier converted into a kitchen. She died at 88 years of age having lived at Haberdeventure from her birth in 1825 until her death in 1913.

Her nephew, Michael Robertson Stone, inherited the property and moved to Haberdeventure with his family that same year (1913). Although Michael Stone was an educator by profession, he continued the agricultural activities of his ancestors. With the assistance of tenant farmers, he grew tobacco which remained the main cash crop. Michael Stone died in 1934, and couple of years after his death the property was sold outside

the Stone family for the first time: to Charles Stevenson Smith. Smith occupied Haberdeventure for nine years and eventually sold it to Peter and Ruth Vischer in 1945.

The Vischers attempted to revive intensive farming on the site. Initially they attempted to raise cattle, but eventually they switched to horses. They made several changes to the site, adding various outbuildings and extensive ornamental gardens surrounding the mansion. After Peter Vischer's death in 1967, farming activities diminished and ceased altogether in the 1970s. On occasion the Vischers would open their home to the public during special Charles County historic tours. On July 4, 1973, the home was designated a Registered National Historic Landmark. In 1977 fire gutted the main block of the house and extensively damaged the west hyphen and wing. The park was authorized as a National Historic Site in 1978, but the property was not actually purchased until 1981.

In accordance with the General Management Plan developed by the National Park Service in 1988, a phased restoration of the exterior of the mansion was begun in December 1991. Haberdeventure was restored to its circa 1900 appearance, the earliest date for which there is documentable appearance. The restoration was based on historical photographs and extensive research of the extant structure.

The Stones were members of an important Maryland family, but great economic prosperity never accrued the owners of Haberdeventure. They did not share in the success of the planter gentry of the eighteenth-century Chesapeake. Thomas Stone's financial situation began to deteriorate in 1783. His land holdings in Charles County were substantial as they amounted to over 2,000 acres. However, as his debts increased his slaves became a disposable asset and he hired out and eventually sold a number of them.

Tobacco was supposed to have been the principal cash crop, but records indicate that relatively little was produced at Haberdeventure while Thomas Stone was the owner. Purchases of oats and corn surpassed the profits made from the sale of these crops. There were also significant purchases of sheep, chickens, turkeys, and potatoes. Other agricultural activities included the production of wool, cotton, and flax. Stone had been less interested in Haberdeventure as an income-producing investment than as its suitability as the site for his home. Its strategic location at the junction of two of the most important regional roads linking Port Tobacco to Alexandria and all points north, facilitated the shipments of agricultural products, but most of his income came from his properties in the more productive lowlands and from his Great Mill at Port Tobacco.

William B. Stone became genuinely interested in agricultural activities, particularly technological advances in agricultural implements and fertilizers which would increase productivity. His application of the principles of scientific agriculture at Haberdeventure support the inclusion of the property in the area of agricultural significance. Stone raised livestock and crops such as tobacco, corn and wheat which he sold to commission merchants in Baltimore. Although he was apparently uncomfortable

being a slave owner, he farmed his land with the help of slaves until the time of the Civil War. He also relied on the labor of his tenants as did his daughter Margaret.

The history of Haberdeventure from 1770 to 1900 reveals some of the trends that characterized the economic development of small plantations in the Chesapeake in the century following the birth of our nation. The growth of tenancy, the continued dependence on slave labor, the diminishing return from worn-out soils, the declining role of tobacco as the principal income-producing crop, and the diversification of economic activities that became essential for the survival of agricultural enterprises are all represented in this site.

The **road and lane remnants** within the site and those providing access to Haberdeventure exhibit a great deal of integrity. They not only link the mansion and the contributing structures, but also provide evidence of the operation of the estate and its link to commercial centers, such as Port Tobacco and Alexandria. They are suggestive of the social relationships between the Stones, owners and managers of Haberdeventure, and the tenants and slaves who worked the fields and participated in the diverse agricultural activities. The road provided an essential link to the commission merchants in Baltimore and elsewhere who purchased the products grown at the site.

The **field patterns and forest stands** also bear testimony to the agricultural practices and management of the Haberdeventure estate. Although some forested areas have encroached on some of the fields, the integrity of the fields patterns remains quite high and provide much of the rural feeling of the site.

9. Major Bibliographical References

Andrews, Matthew Page. *History of Maryland: Province and State*. Hatboro, Pennsylvania, Tradition Press, 1965, 395.

asalik, Kenneth J., and Thomas R. Lewis. Archeological Investigations at the Thomas Stone National Historic Site, Charles County, Maryland. Report submitted [ca. 1988] to the USDI-NPS, Mid-Atlantic Region, by Cultural Heritage Research Services, Inc., Chester, Pennsylvania, n. d.

Biographical Directory of the American Congress, 1774-1961. Washington, D.C.: U.S. Government Printing Office, 1961.

Charles County, Maryland Clerk of the Court *Test Book, 1817-1818* (Actually goes through 1850). Contains signature of William Briscoe Stone, attorney at law, 7th Nov. 1820, which admitted W. B. Stone to practice as an attorney at law before the Charles County Bar.

Cheek, Charles D., Jeanne A. Ward, and Joseph Balicki. Archeological Studies of the Garden and House at the Thomas Stone National Historic Site (18CH331), Charles County, Maryland. Report submitted to USDI-NPS, Mid-Atlantic Region, by John Milner Associates, Inc., West Chester, Pennsylvania, 1992.

Crowl, Philip A. *Maryland During and After the Revolution--A Political and Economic Study*. Baltimore: The Johns Hopkins Press, 1943, 165-66.

Deiss, Ronald W. Archeological Excavations at the Thomas Stone National Historic Site, Port Tobacco, Maryland. USDI-NPS, Mid-Atlantic Region, 1986.

Gales, Sr., Joseph. compiler. *The Debates and Proceedings in the Congress of the United States*, Vols. I & II. Washington: Gales and Seaton, 1834.

Inventory of Historic Sites in Calvert County, Charles County, and St. Mary's County. Revised Edition. Annapolis, August 1980, 58.

Klapthor, Margaret and Paul Dennis Brown, *The History of Charles County, Maryland*, La Plata, Maryland: Charles County Tercentenary Inc., 1958.

Land, Aubrey C. "Economic Base and Social Structure: The Northern Chesapeake in the Eighteenth Century." *Journal of Economic History* XXV (December 1975), 639-54.

e, Jean B. *The Social Order of a Revolutionary People: Charles County, Maryland, 1733-1786*, PhD. Dissertation, University of Virginia, 1984.

Maryland Period Rooms. The Baltimore Museum of Art, 1989, 12-15.

Papenfuse, Edward C. et. al. *A Bibliographical Dictionary of the Maryland Legislature, 1635-1789*. Volume II, I-Z. Baltimore and London: The Johns Hopkins University Press, 1985.

Pousson, John F. and Matthew R. Virta. Management Report, Archeological Testing, Porch Pier Footings at the Thomas Stone House, Package 110, Thomas Stone National Historic Site, Charles County, Maryland. USDI-NPS-DSC-EAA, Silver Spring, Maryland, 1992.

Pousson, John F. Management Report, Site Utilities Archeological Survey, Thomas Stone National Historic Site (18CH331), Charles County, Maryland. USDI-NPS-DSC-EAA, Silver Spring, Maryland], 1996.

Public Law 95-625, The National Parks and Recreation Act of 1987 (November 12, 1978, 92 Stat. 3510).

Reports of Cases Argued and Adjudged in the Court of Appeals of Maryland and in the High Court of Chancery of Maryland. William T. Brantly, annotator, Volume XXVII. Baltimore: M. Curlander, Law Bookseller, Publisher and Importer, 1885.

Rivoire, J. Richard et. al. *Draft Cultural Landscape Report. Thomas Stone National Historic Site*. John Milner Architects, Chadds Ford, Pennsylvania, 1994.

Rivoire, J. Richard. "Thomas Stone National Historic Site: A Summary Report of Additional Research Findings," 1993.

Sams, Conway W. and Riley, Elihu S. *The Bench and Bar of Maryland: A History, 1634-1901*. Volume I. Chicago: Lewis Publishing Co., 1901.

[ ] See continuation sheet

Sheehan, Glenn W.Tests at the Thomas Stone National Historic Site. Report submitted to the USDI-NPS, Mid-Atlantic Region, by SJS Archaeological Services, Inc., 1990.

Snell, Charles W. *National Register of Historic Places*. Inventory--Nomination Form 10-300, "Habre-de-Venture (Thomas Stone House)." Washington, D.C., May 27, 1971.

Stiverson, Gregory A. *Poverty in a Land of Plenty: Tenancy in Eighteenth-Century Maryland*. Baltimore: The Johns Hopkins University Press, 1977.

Stone Family of Maryland Collection. Library of Congress, Washington, D.C.

Stone Family Papers, Maryland Historical Society, Baltimore.

Stone, Michael Jenifer and William Briscoe Stone Papers. William R. Perkins Library, Duke University, Durham, North Carolina.

Wallon, Jr., James Thomas, A.I.A. *Habre de Venture near Port Tobacco, Charles County Maryland. Historic Structure Report to National Park Service*, July 31, 1987 (revised December 18, 1987).

Wearmouth, John M. *Charles County Helps Shape the Nation*. La Plata, Maryland: Charles County Board of Education, November 1986.

Wearmouth, John M. *Final Draft, Thomas Stone national Historic Site--Historic Resource Study: Biographical Sketch, Property History and Land Use History--Habre de Venture, Port Tobacco, Md.*, May 11, 1988. Contract #CX 4000-7-0029.

[ ] See continuation sheet

Previous documentation on file (NPS):

[ ] preliminary determination of individual listing (36 CFR 67) has been requested
[X] previously listed in the National Register
[ ] previously determined eligible by the National Register
[X] designated a National Historic Landmark
[X] recorded by Historic American Buildings
Survey # MD 470
[ ] recorded by Historic American Engineering
Record # _____

Primary location of additional data:

[ ] State historic preservation office
[ ] Other State agency
[X] Federal agency
[ ] Local government
[ ] University
[ ] Other

Specify repository: Chesapeake/Allegheny System Support Office, National Park Service, Philadelphia, PA.

10. Geographical Data

Acreage of property 328.25 acres

UTM References

	Zone	Easting	Northing		Zone	Easting	Northing
A	18	322700	4267160	B	18	323340	4265500
C	18	322000	4265400	D	18	391540	4267060

Verbal Boundary Description

The Thomas Stone National Historic Site contains 328.25 acres (321.97 NPS; 6.28 private). The site includes the Haberdeventure mansion, several 19th-century dependencies, several 20th-century structures, and the graves of Thomas Stone, his wife Margaret and other members of the family. The boundary starts at the northeast corner on the west edge of Rose Hill Road at latitude 38 32' 22" N-longitude 77 02' 21" W, then proceeds southeasterly for about 5880' along the road to the southeast corner on the west side of the road. Then westerly on course S 04-43-W for 1258 feet, then N 67-57-16-W for about 440 feet, then S 02-18-27-W for about 592 feet, then west again N 87-41-33-W for about 607 feet, then northwest about 322 feet, then continuing northwestward for about 3600 feet to a point across Hog Hole Run (west side), then in a northeasterly direction for about 2030 feet to the northwest corner at latitude 30 32' 10" N-longitude 77 02' 41" W, then eastward returning to the northeast corner at the Rose Hill Road starting point.

Boundary Justification

11. Form Prepared By

name/title Susan Calafate Boyle, Historian

organization Nat'l Park Service, Denver Service Center **date** 8/97

street & number 12795 W. Alameda Pkwy, PO Box 25287 **telephone** (303) 969-2319


city or town Denver **state** Colorado **zip code** 80225-0287

*U.S.GPO:1988-0-223-918 (NPS-RMR-PR-NPP;KOHEN;10-91)

Thomas Stone National Historic Site

Haberdeventure

Port Tobacco, Maryland



Thomas Stone House



Identification:

Preferred Structure Name:	Thomas Stone House
Structure Number:	01
Other Structure Name(s):	

	Other Structure Name(s)
1.	Habre-De-Venture

Park:	Thomas Stone National Historic Site
Historic District:	

	Historic District
No records.	

Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	080059
UTM:	

	Zone	Easting	Northing	Source	Datum
No records.					

Historical Significance:

National Register Status:	Entered - Documented
National Register Date:	10/31/1972
National Historic	Yes

Landmark?:

National Historic Landmark Date: 11/11/1971

Significance Level: National

Long Significance Description: Originally owned by Thomas Stone who served in Continental Congress 1775-1778. Stone voted for and signed Declarationn of Independence. Served as his Primary residence during his political career. Structure embodies 3 major architectural styles present in 18th C. MD. Burned & stabilized in 1977. Fully restored in 1994.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1771	AD	1780	AD		
2.	Altered	1840	AD	1850	AD		
3.	Restored	1945	AD	1955	AD		
4.	Rehabilitated	1991	AD	1992	AD	John Milner Architects, Inc.	Architect
5.	Restored	1992	AD	1994	AD		

Function and Use:

Primary Historic Function: Single Family Dwelling

Primary Current Use: Visitor Contact (Visitor Center)

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Historic Furnished Interior	Current

Physical Description:

Structure Type: Building

Volume: 20,000 - 2,000,000 cubic feet

Square Feet: 5050

Material(s):

	Structural Component(s)	Material(s)
1.	Walls	Brick
2.	Foundation	Stone
3.	Roof	Wood

Long Physical 1-1/2 story 45'-1"x24'-1", central hall & entry plan main section with English gambrel roof,

Description: brick walls & exposed chimneys. 1 story full length rear porche12' wide by 45' deep supported 6 brick piers. Front full length projecting entry cover over central stairs. Coverway is supported by 6 piers & 6 wood columns.

2 story 33' x18'-5" frame West (kitchen) wing, brick endwalls & fully recessed chimneys offset from gable roof , 1 story 12'x13'5" porch, & 1-1/2 story 25'2"x14'2" hyphen to house.

East of main house is 1-1/2 story 16'-7"x18'-8" frame english gambrel roof with single, offset end chimney on SE (Stone's office) wing. Connected to main house by 1 story 10'-3"x18'-3" hyphen.

Condition and Impacts:

Structure Condition: Good

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Visitation

Other Impacts:

	Other Impact Type
1.	Weather
2.	Structural Deterioration

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 05/14/1992

Management - Treatment:

Ultimate Structure Treatment: Restoration

Ultimate Treatment Document: General Management Plan

Ultimate Treatment Document Date: 03/06/1990

Was Ultimate No

Treatment Approved?:	
Was Ultimate Treatment Completed?:	Yes
Ultimate Treatment Responsibility:	National Park Service
Interim Treatment Responsibility:	National Park Service
Interim Treatment Cost:	0
Routine Maintenance Responsibility:	National Park Service
Cyclic Maintenance Responsibility:	National Park Service

Management - Description:

Short Management Text: Restoration/reconstruction completed. No changes in condition noted.

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	National Register Information System	71000372		1
2.	HABS	MD-470		2
3.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	3
4.	Cultural Landscape Report	402199		4
5.	National Register Information System	72001595	NHL nomation (1 of 2 known)	5

Documentation Level:	Good
Last Updated By:	Clark, Steve
Last Updated:	09/23/2002 09:16am

Treatment Approved?:	
Was Ultimate Treatment Completed?:	Yes
Ultimate Treatment Responsibility:	National Park Service
Interim Treatment Responsibility:	National Park Service
Interim Treatment Cost:	0
Routine Maintenance Responsibility:	National Park Service
Cyclic Maintenance Responsibility:	National Park Service

Management - Description:

Short Management Text: Restoration/reconstruction completed. No changes in condition noted.

Documentation:

References:


	Source	Reference Number	Other Information	Sequence
1.	National Register Information System	71000372		1
2.	HABS	MD-470		2
3.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	3
4.	Cultural Landscape Report	402199		4
5.	National Register Information System	72001595	NHL nomation (1 of 2 known)	5

Documentation Level:	Good
Last Updated By:	Clark, Steve
Last Updated:	09/23/2002 09:16am

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Main house, view from North	July 2002	1
2.			1994	1
3.				2
4.		West (Kitchen) Wing, view from NW	July 2002	2

				
5.				3
6.		Office Wing w/ hyphen, View from NE	July 2002	3
7.		Complex from rear, View from SE	July 2002	4







Certified By:

Certified By:

	Month	Year
1.	August	2002

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT

Identification

IDLCS: 80059 Structure Number: 01

Structure Name 1: THOMAS STONE HOUSE
Structure Name 2: HABRE DE VENTRE
Structure Name 3:

Park Alpha Code: THST Name: THOMAS STONE NATIONAL HISTORIC SITE
ORGCODE: 4850 County: CHARLES State: MD
Regional Office: MID-ATLANTIC
Subunit ORGCODE: Name:
Alpha Code: County: CHARLES State: MD

Number of UTM's: 0 Zone/Easting/Northing

Significance

NR Status: ENTERED - DOCUMENTED Date: 11/11/71
Significance: NATIONAL
NHL: YES Date: 11/11/71

Significance

Orig. owned by Thos. Stone who served in Continental Congress 1775-1778. Voted for & signed Declratn of Indep. Primary residence during politicl career. Structure embodies 3 major architectrl styles present in 18th C. MD. Burned & stabilized in 1977.

Historical Information

Period of Construction: HISTORIC

Date: 1771-1780 (BU) Designer: ( )
Date: 1840-1850 (AL) Designer: ( )
Date: 1945-1955 (RR) Designer: ( )
Date: 1991-1992 (RH) Designer: John Milner Architects, Inc. (A)

Functions, Uses, Materials, Impacts, and Condition

Historic Functions
SINGLE FAMILY DWELLING

Current Uses
VISITOR CONTACT (VISTOR CNTR)
HISTORIC FURNISHED INTERIOR

Buildings — Materials — Structures

Foundation: STONE Sub-structure:
Framing:
Walls: BRICK
Roof: WOOD Super-structure:
Other:
Volume: 20,001 - 2,000,000 CUBIC FT

Description

1-1/2 story 45'1"x24'1" main sectn. 2 story 33'x18'5" frame W (kitchn) wing w/ brick ends, 1 story 12'x13'5" porch, & 1-1/2 story 25'2"x14'2" hyphn to house. 1-1/2 story 16'7"x18'8" hip-roof frame E (Stone's office) wing w/ 1 story 10'3"x18'3" hyphn.

Impact Level: SEVERE Impact Types: FIRE
STRUCTURAL DETERIORATION
WEATHER

Condition: FAIR

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT
Continued

IDLCS	Park	Structure Name	Number
80059	THST	THOMAS STONE HOUSE	01

Management Information

NPS Legal Interest: FEE
Life: Exp. Date: / /
Federal Owner:
Local Owner:

Management Category: MUST BE PRES. & MAINT
Management Agreement: NONE
Management Date: 05/14/92
Agrmt. Exp. Date: / /

Proposed Ultimate Treat: Doc: Date: / /
Approved Ultimate Treat: RESTORATION Doc: GMP Date: 03/06/90

Treatment Responsibilities

Interim Treatment: NPS
Ultimate Treatment: NPS
Routine Maintenance: NPS
Cyclic Maintenance: NPS

Treatment Costs

Interim: $0 Date: /
Ultimate: $2,221,001 Date: 03/90
Level of Estimate: SIMILAR FACILITIES
Estimator: DSC

Approved Ultimate Treatment Completed: NO

Management Text

Restoration/reconstruction is presently underway.

Major Bibliographical References

Nat. Reg.: 71000372 CSI: Nat. Cat: NO

HABS: MD-470
HAER:

BRIDGES:
DAMS:
QTRS:

CLI		CRBIB		Other
1.	HRS	1.		1.
2.	HS ASSESS	2.	10/88	2.
3.	HSR	3.		3.
4.	CLR	4.		4.
5.		5.		

Documentation Level: GOOD

Date Entered/Updated: 03/17/94 Logger: SMC


Date of Report: 03/21/94


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from N
May 1994



THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from E
May 1994

66.92.9

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from N
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NW
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NW
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NW
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from SW
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from SW
May 1994


4 26 '94

THST
80059


NEG #
LCS THST 006

Thomas Stone House
View from W
May 1994

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NE
May 1994


4'26'94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from N
May 1994


4 26 94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NE
May 1994


4-26'94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from SE
May 1994



THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from S
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from S
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from S
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from SW
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from S
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from SE
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NE
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from N
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from NW
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from S
May 1994


4 26 '94

THST
80059

NEG #
LCS THST 006

Thomas Stone House
View from S
May 1994



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from south
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from south
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from west
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from southwest
May 1992



THST
80059

NEG #
LCS-THST-001


Thomas Stone House
View from south
May 1992



THST
80059

NEG #
LCS-THST-001


Thomas Stone House
View from southwest
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from east
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from south
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from northwest
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from northwest
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from northeast
May 1992



THST
80059

NEG #
LCS-THST-001

Thomas Stone House
View from north
May 1992

LIST [illegible]IFIED STRUCTURES

THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

--IDENTIFICATION----------

IDLCS: 80059 STRC#: 01

STRUCTURE NAME 1: STONE, THOMAS, HOUSE

STRUCTURE NAME 2: HABRE DE VENTURE

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322220 /NORTHING 4266490

--SIGNIFICANCE----------

SIGNIFICANCE: N NR STATUS: 1 DATE: 111171 NHL: YES DATE: 111171

--HISTORICAL INFORMATION----------

PER.CONSTRUCTION: HI

DATE: 1771-1780 CODE: BU DESIGNER: CODE:

DATE: 1840-1850 CODE: AL DESIGNER: CODE:

DATE: 1945-1955 CODE: RR DESIGNER: CODE:

DATE: 1970-1977 CODE: NG DESIGNER: CODE:

FUNCTION CODES: HISTORIC 01A CURRENT 98

MATERIALS: (FOR BUILDINGS) FOUNDATION 30 WALLS 30 ROOF 22 OTHER 03

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) C

TEXT: Prime point of historical interest is association with Thomas Stone, signer of the Declaration of Independence, and continuing association with Stone's heirs over following 170 years.

--MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: A MGT.AGREEMENT:

(DATE): 111078 (OTHER):

CONDITION: F IMPACT LEVEL: S IMPACT TYPE: WEA PIN FIR

(PROPOSED) TREAT: RP (PROPOSED) DOC: E APPROV.ULT.TREAT: APPROVAL DOC:

(DATE): 011088 (DATE):

TREATMENT RESPONSIBILITY: INTERIM TREATMENT NPS NPS or OTH

APPROVED ULTIMATE TREATMENT NPS NPS or OTH

ROUTINE MAINTENANCE NPS NPS or OTH

CYCLIC MAINTENANCE NPS NPS or OTH

INTERIM TREATMENT COST: 450,000 APPROVED TREATMENT COST:

(DATE): 0286 (DATE):

LEVEL OF ESTIMATE: C ESTIMATOR:

INTERIM TREATMENT COMPLETED ?: N APPROV.ULT.TREAT. COMPLETED ?:

TEXT:

--MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: G

--DESCRIPTION/TEXT----------

Major center hall, brick block with flanking dependencies; significant regional variation on English Palladian design.

DATE ENTERED/UPDATED: / /

THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

--IDENTIFICATION----------

IDLCS: 80059 STRC#: 01

STRUCTURE NAME 1: STONE, THOMAS, HOUSE

STRUCTURE NAME 2: HABRE DE VENTURE

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322220 /NORTHING 4266490

--SIGNIFICANCE----------

SIGNIFICANCE: N NR STATUS: 1 DATE: 111171 NHL: YES DATE: 111171

--HISTORICAL INFORMATION----------

PER.CONSTRUCTION: HI

DATE: 1771-1780 CODE: BU DESIGNER: CODE:

DATE: 1840-1850 CODE: AL DESIGNER: CODE:

DATE: 1945-1955 CODE: RR DESIGNER: CODE:

DATE: 1970-1977 CODE: NG DESIGNER: CODE:

FUNCTION CODES: HISTORIC 01A CURRENT 98

MATERIALS: (FOR BUILDINGS) FOUNDATION 30 WALLS 30 ROOF 22 OTHER 03

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) C

TEXT: Prime point of historical interest is association with Thomas Stone, signer of the Declaration of Independence, and continuing association with Stone's heirs over following 170 years.

--MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

CATEGORY: A MGT.AGREEMENT:

E): 111078 (OTHER):

CONDITION: F IMPACT LEVEL: S IMPACT TYPE: WEA PIN FIR

(PROPOSED) TREAT: RR (PROPOSED) DOC: E APPROV.ULT.TREAT: APPROVAL DOC:

(DATE): 011088 (DATE):

TREATMENT RESPONSIBILITY: INTERIM TREATMENT NPS NPS or OTH

APPROVED ULTIMATE TREATMENT NPS NPS or OTH

ROUTINE MAINTENANCE NPS NPS or OTH

CYCLIC MAINTENANCE NPS NPS or OTH

INTERIM TREATMENT COST: 450,000 APPROVED TREATMENT COST:

(DATE): 0286 (DATE):

LEVEL OF ESTIMATE: C ESTIMATOR:

INTERIM TREATMENT COMPLETED ?: N APPROV.ULT.TREAT. COMPLETED ?:

TEXT:

--MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER(1): (2):

(3): (4):

DOCUMENTATION LEVEL: G

--DESCRIPTION/TEXT----------

Major center hall, brick block with flanking dependencies; significant regional variation on English Palladian design.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): THOMAS STONE RESIDENCE

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322220	426690

8. ESTIMATED DATE(S) OF CONSTRUCTION: 1771-1777/1977ff.

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

THE STONE HOUSE IS A MAJOR CENTER BRICK BLOCK WITH FLANKING DEPENDENCIES MARKING A SIGNIFICANT REGIONAL VARIATION OF ENGILISH PALLADIAN DESIGN. ITS ASSOCIATION WITH THOMAS STONE, SIGNER OF THE DECLARATION OF INDEPENDANCE SEEMS TO BE ITS PRINCIPLE POINT OF HISTORIC SIGNIFICANCE. IT HAS ADDED INTEREST IN HAVING BEEN IN THE STONE FAMILY FOR THE LAST 170 YEARS. DESPITE THE FIRE WHICH BURNED THE INTERIOR IN 1977, MAJOR ROOM SURVIVES IN MUSEUM IN BALTIMORE.

10. RELATION TO SCENE:

CENTERPIECE OF ESTATE FOCUS OF GARDENS AND LAND ORGANIZATION.

WORKSHEET 2 PARK: HABRE DE VENTURE STRUCTURE: THOMAS STONE HOUSE

11. STRUCTURE'S PRESENT CONDITION:

THE STURCTURE WAS DEVASTATED BY FIRE IN 1977, BUT HAD BEEN EXPOSED TO WOOD BEETLES AND ROT FOR 2 CENTURIES. MUCH DECAYED, IT IS BEING SHORED UP AND STABILIZED AT PRESENT.

12. TREATMENT RECOMMENDED:

EXTERIOR		INTERIOR	
[ ]	STABILIZATION	[ ]	STABILIZATION
[ ]	PRESERVATION	[ ]	PRESERVATION
[ ]	RESTORATION	[ ]	RESTORATION
[X]	TOTAL RECONSTRUCTION	[ ]	TOTAL RECONSTRUCTION
[ ]	PARTIAL RECONSTRUCTION	[ ]	PARTIAL RECONSTRUCTION
[ ]	ADAPTIVE RESTORATION	[X]	ADAPTIVE RESTORATION
[ ]	NO WORK REQUIRED	[ ]	NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: . . . . . .

. . . . . .

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

SEE OVERALL PLAN OF SITE FOR LOCATION OF THE BUILDING. THIS BUILDING IS ALREADY DOCUMENTED GRAPHICALLY BY THE HABS.

WORKSHEET 3 PARK: HABRE DE VENTURE STRUCTURE: THOMAS STONE HOUSE

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ . . . . . .

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: GEORGE E. THOMAS DATE: 12-22-87























THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

IDENTIFICATION----------

IDLCS: 80.059 STRC#: 01

STRUCTURE NAME 1: STONE, THOMAS, HOUSE

STRUCTURE NAME 2: HABRE-DE-VENTURE

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322220 /NORTHING 4266490

SIGNIFICANCE----------

SIGNIFICANCE: N NR STATUS: 1 DATE: 111171 NHL: YES DATE: 111171

HISTORICAL INFORMATION----------

PER.CONSTRUCTION: HI

DATE: 1771 - 1780 CODE: BU DESIGNER: CODE:

DATE: 1800 - 1824 CODE: AL DESIGNER: CODE:

DATE: 1945 - 1955 CODE: RR DESIGNER: CODE:

DATE: 1970 - 1977 CODE: NG DESIGNER: CODE:

FUNCTION CODES: HISTORIC 01A. CURRENT 98

MATERIALS:(FOR BUILDINGS) FOUNDATION 30 WALLS 30 ROOF 22 OTHER 03

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) C

TEXT: Prime point of historical interest is association with Thomas Stone, signer of the Declaration of Independence, and continuing association with Stone's heirs over following 170 years.

MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NCF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: A MGT.AGREEMENT:

(DATE): (OTHER):

CONDITION: F IMPACT LEVEL: IMPACT TYPE:

(PROPOSED) TREAT: (PROPOSED) DOC: APPROV.ULT.TREAT: APPROVAL DOC:

DATE: DATE:

TREATMENT RESPONSIBILITY:

INTERIM TREATMENT	NPS	NPS or OTH
APPROVED ULTIMATE TREATMENT	NPS	NPS or OTH
ROUTINE MAINTENANCE	NPS	NPS or OTH
CYCLIC MAINTENANCE	NPS	NPS or OTH

INTERIM TREATMENT COST: APPROVED TREATMENT COST:

(DATE): (DATE):

LEVEL OF ESTIMATE: ESTIMATOR:

INTERIM TREATMENT COMPLETED? : APPROV.ULT.TREAT. COMPLETED? :

TEXT:

MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: G

DESCRIPTION/TEXT----------

Major center hall, brick block with flanking dependencies; significant regional variation on English Palladian design.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): THOMAS STONE RESIDENCE

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322210	426649 0

8. ESTIMATED DATE(S) OF CONSTRUCTION: 1771-1777/1977ff.

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:
THE STONE HOUSE IS A MAJOR CENTER BRICK BLOCK WITH FLANKING DEPENDENCIES MARKING A SIGNIFICANT REGIONAL VARIATION OF ENGILISH PALLADIAN DESIGN. ITS ASSOCIATION WITH THOMAS STONE, SIGNER OF THE DECLARATION OF INDEPENDANCE SEEMS TO BE ITS PRINCIPLE POINT OF HISTORIC SIGNIFICANCE. IT HAS ADDED INTEREST IN HAVING BEEN IN THE STONE FAMILY FOR THE LAST 170 YEARS. DESPITE THE FIRE WHICH BURNED THE INTERIOR IN 1977, MAJOR ROOM SURVIVES IN MUSEUM IN BALTIMORE.

10. RELATION TO SCENE:
CENTERPIECE OF ESTATE FOCUS OF GARDENS AND LAND ORGANIZATION.

WORKSHEET 2 PARK: HABRE DE VENTURE STRUCTURE: THOMAS STONE HOUSE

11. STRUCTURE'S PRESENT CONDITION:

THE STURCTURE WAS DEVASTATED BY FIRE IN 1977, BUT HAD BEEN EXPOSED TO WOOD BEETLES AND ROT FOR 2 CENTURIES. MUCH DECAYED, IT IS BEING SHORED UP AND STABILIZED AT PRESENT.

12. TREATMENT RECOMMENDED:

EXTERIOR		INTERIOR	
	STABILIZATION		STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
X	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION	X	ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION:

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

SEE OVERALL PLAN OF SITE FOR LOCATION OF THE BUILDING. THIS BUILDING IS ALREADY DOCUMENTED GRAPHICALLY BY THE HABS.

WORKSHEET 3 PARK: HABRE DE VENTURE STRUCTURE: THOMAS STONE HOUSE

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ . . . . . .

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: GEORGE E. THOMAS DATE: 12-22-87
















1 24 '9 1




1 24 '9 1





1 24 '9 1


1 24 '9 1


1'24'91

Thomas Stone Formal Garden Terraces



Identification:

Preferred Structure Name:	Thomas Stone Formal Garden Terraces
Structure Number:	01.1
Other Structure Name(s):	

	Other Structure Name(s)
No records.	

Park:	Thomas Stone National Historic Site
Historic District:	

	Historic District
No records.	

Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251741
UTM:	

	Zone	Easting	Northing	Source	Datum
No records.					

Historical Significance:

National Register Status:	Entered - Undocumented
National Register Date:	10/31/1972
National Historic Landmark?:	Yes
National Historic Landmark Date:	10/31/1972
Significance Level:	National
Short Significance Description:	Part of the Thomas Stone Plantation, home of one of four signers of Declaration of Independence from Maryland. Garden Terraces were integral part of 18th C. design patterns and while the formal gardens & pathways are no longer extant, the terracing & ramps are still visible.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1770	AD	1780	AD		
2.	Abandoned	1798	AD	1913	AD		
3.	Altered	1934	AD				

Function and Use:

Primary Historic Function: Formal Garden

Primary Current Use: Landscape

Structure Contains Museum Collections?: No

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
No records.		

Physical Description:

Structure Type: Grounds/Landscape

Material(s):

	Structural Component(s)	Material(s)

No records.

Long Physical Description: Formal Garden consists of two terrace levels, upper and lower, and two ramps. The upper terrace is approximately 210' wide by 40' deep and is divided by the ramp as it progresses from the house down to the lower terrace. Upper ramp is 18' wide by 65' long, approximately. Lower terrace is approximately 105' wide by 70' deep. The lower ramp begins at outer edge of the lower terrace and is 18' wide x 10' long.

Condition and Impacts:

Structure Condition: Good

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Consumptive Use

Other Impacts:

	Other Impact Type
1.	Visitation

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 02/01/1996

Management - Treatment:

Ultimate Structure Treatment: Preservation

Ultimate Treatment Document: Cultural Landscape Report

Ultimate Treatment Document Date: 02/01/1996

Was Ultimate Treatment Approved?: Yes

Was Ultimate Treatment No

Completed?:

Ultimate Treatment Responsibility: National Park Service

Interim Treatment Responsibility: National Park Service

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	National Register Information System	72001595	NHL listing	1
2.	HABS	MD-470		2
3.	Cultural Landscape Report	402199		3
4.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	4

Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Formal Garden Terrace from CLR, 02/01/1996	August 2002	1


				
2.		Formal Garden Terraces, view from South	August 2002	2
3.		Formal Garden Terraces, view from SE	August 2002	3

Certified By:

Certified By:

	Month	Year
1.	August	2002

Thomas Stone Entrance Road A



Identification:

Preferred Structure Name:	Thomas Stone Entrance Road A
Structure Number:	01.A
Other Structure Name(s):	Other Structure Name(s): No records.
Park:	Thomas Stone National Historic Site
Historic District:	Historic District: No records.
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251183
UTM:	Zone, Easting, Northing, Source, Datum: No records.

Historical Significance:

National Register Status:	Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: One of two entrance roads off of Rose Hill Road. Entrance Road is currently used to enter home of Thomas Stone and is present in 1911 USGS maps. It is believed to have been in service during Stones' ownership.(1770-1900)

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1770	AD	1820	AD		

Function and Use:

Primary Historic Function: Vehicular Circulation

Primary Current Use: NPS Class I Principal Road

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Pedestrian Circulation	Historic
2.	Vehicular Circulation	Current

Physical Description:

Structure Type: Road

Material(s):

	Structural Component(s)	Material(s)
1.	Superstructure	Earth
2.	Superstructure	Stone

Short Physical Description: 10' to 12' varying width primary entrance road, approximately 1400' long. Gravel, clay and sand composition.

Condition and Impacts:

Structure Condition: Good

Year Condition 2002

Assessed:

Impact Level: Moderate

Primary Impact: Consumptive Use

Other Impacts:

	Other Impact Type
No records.	

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 02/01/1996

Management - Treatment:

Ultimate Structure Treatment: Preservation

Ultimate Treatment Document: Cultural Landscape Report

Ultimate Treatment Document Date: 02/01/1996

Was Ultimate Treatment Approved?: No

Was Ultimate Treatment Completed?: No

Ultimate Treatment Responsibility: National Park Service

Interim Treatment Responsibility: National Park Service

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural Landscape Report	402199		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	2
3.	Other		Draft National Register Nomination	3


Documentation Level: Good

Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Entrance Road A	2002	1
2.		1937 Aerial with roads & lanes	August 2002	2


				
3.		Thomas Stone Entrance Rd A, view from NE	August 2002	3

Certified By:

Certified By:

	Month	Year
1.	August	2002

Thomas Stone Formal Entance Lane Trace



Identification:

Preferred Structure Name:	Thomas Stone Formal Entance Lane Trace
Structure Number:	01.AA
Other Structure Name(s):	Other Structure Name(s): No records.
Park:	Thomas Stone National Historic Site
Historic District:	Historic District: No records.
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251297
UTM:	Zone | Easting | Northing | Source | Datum: No records.

Historical Significance:

National Register Status:	Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: National

Long Significance Description: Location and design of this feature is consistent with late eighteenth design principles. Some phsyical evidence suggests that that this might been a formal entrance drive, aligning itself with center of the mansion and the terrace ramps. It also is at the juncture of the Port Tobacco-Mattawoman and Port Tobacco-Piscataway Roads, increasing status of Habre-da-venture as a visual node to mansion; which is an important factor in eighteenth century landscape design.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1770	AD	1771	AD		
2.	Abandoned	1900	AD	1911	AD		

Function and Use:

Primary Historic Function: Vehicular Circulation

Primary Current Use: Abandoned/Unmaintained

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
No records.		

Physical Description:

Structure Type: Ruin

Material(s):

	Structural Component(s)	Material(s)
1.	Superstructure	Earth

Short Physical Description: Two lane formal entrance road divided by an allee of trees in center. Approximately 10' to 12' varying width by 200' long from Old Glymont Road to Lemko inholding. Rest lost to agriculture operations..

Condition and Impacts:

Structure Condition:	Fair
Year Condition Assessed:	2002
Impact Level:	Moderate
Primary Impact:	Neglect

Other Impacts:

	Other Impact Type
1.	Vegetation

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category:	Must Be Preserved and Maintained
Management Category Date:	02/01/1996

Management - Treatment:

Ultimate Structure Treatment:	Preservation
Ultimate Treatment Document:	Cultural Landscape Report
Ultimate Treatment Document Date:	02/01/1996
Was Ultimate Treatment Approved?:	Yes
Was Ultimate Treatment Completed?:	No
Ultimate Treatment Responsibility:	National Park Service
Interim Treatment Responsibility:	National Park Service
Routine Maintenance Responsibility:	National Park Service

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural Landscape Report	402199		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	2
3.	Other		Draft National Register Nomination	3


Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Map taken from CLR, 2/1/96	August 2002	1
2.		Formal Entrance Trace, view from South	August 2002	2


				
3.		1937 Aerial, Formal Road @ Top (north)	Sept 2002	3

Certified By:

Certified By:

	Month	Year
1.	August	2002

Thomas Stone Entrance Road B



Identification:

Preferred Structure Name:	Thomas Stone Entrance Road B
Structure Number:	01.B
Other Structure Name(s):	Other Structure Name(s) No records.
Park:	Thomas Stone National Historic Site
Historic District:	Historic District No records.
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251200
UTM:	Zone | Easting | Northing | Source | Datum No records.

Historical Significance:

National Register Status: Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: One of two entrance roads off of Rose Hill Road. Entrance Road is secondary road used to enter home of Thomas Stone and is present in 1911 USGS maps. It is believed to have been in service during Stones' ownership.(1770-1900)

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1770	AD	1820	AD		
2.	Altered	2001	AD	2002	AD		

Function and Use:

Primary Historic Function: Vehicular Circulation

Primary Current Use: NPS Class III Special Purpose Road

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Pedestrian Circulation	Historic
2.	Vehicular Circulation	Current

Physical Description:

Structure Type: Road

Material(s):

	Structural Component(s)	Material(s)
1.	Superstructure	Earth
2.	Superstructure	Stone

Short Physical Description: 10' to 12' varying width primary entrance road, approximately 800' long to juncture with Entrance Road A. Gravel, clay and sand composition.

Condition and Impacts:

Structure Condition: Good

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Consumptive Use

Other Impacts:

	Other Impact Type
1.	Park Operations

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 02/01/1996

Management - Treatment:

Ultimate Structure Treatment: Preservation

Ultimate Treatment Document: Cultural Landscape Report

Ultimate Treatment Document Date: 02/01/1996

Was Ultimate Treatment Approved?: Yes

Was Ultimate No

Treatment Completed?:

Ultimate Treatment Responsibility: National Park Service

Interim Treatment Responsibility: National Park Service

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Management - Description:

Short Management Text: Entrance Road B impacted by construction of new Visitor Center parking lot which uses portion of historic road.

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural Landscape Report	402199		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS HIstoric Resource STudy	2
3.	Other		Draft NR Nomination	3

Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Entrance Road B	August 2002	1

				
2.		1937 Aerial Survey, note road@center right (East)	August 2002	2
3.		Thomas Stone Entrance Rd B (trace), view from E	August 2002	3



Certified By:

Certified By:

	Month	Year
1.	August	2002





Hitching Post

Identification:

Preferred Structure Name:	Hitching Post
Structure Number:	01.C
Other Structure Name(s):	Other Structure Name(s): No records.
Park:	Thomas Stone National Historic Site
Historic District:	Historic District: No records.
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251265
UTM:	Zone, Easting, Northing, Source, Datum

No records.

Historical Significance:

National Register Status: Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: Original hitching post erected at front of Habre-da-venture during Stones' ownership.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1860	AD	1880	AD		

Function and Use:

Primary Historic Function: Livestock

Primary Current Use: OTHER - NO OTHER CATEGORY EXISTS

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Vacant/Maintained (Mothballed)	Current

Physical Description:

Structure Type: Grounds/Landscape

Material(s):

	Structural Component(s)	Material(s)
1.	Superstructure	Cast Iron

Short Physical Description: Hitching post imbedded in ground north of Kitchen Wing at mansion. 6" in diameter by 3' - 4' High with embossed design at base, center emboss with flour-de-lis, top emboss with single ring for horse tethering, apex of conical base culminating to embossed ball.

Condition and Impacts:

Structure Condition:	Good
Year Condition Assessed:	2002
Impact Level:	Low
Primary Impact:	Weather

Other Impacts:

	Other Impact Type
No records.	

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category:	Should Be Preserved and Maintained
Management Category Date:	09/01/2002

Management - Treatment:

Ultimate Structure Treatment:	No Treatment Documented
Ultimate Treatment Document:	No Documentation Available
Was Ultimate Treatment Approved?:	No
Was Ultimate Treatment Completed?:	No
Ultimate Treatment Responsibility:	National Park Service
Interim Treatment Responsibility:	National Park Service
Routine Maintenance Responsibility:	National Park Service
Cyclic Maintenance Responsibility:	National Park Service

Management - Description:

Short Management Text: Feature never addressed before.

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
No records.				

Documentation Level: Poor

Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:


	Graphic	Caption	Graphic Date/Year	Sequence
1.		Hitching Post, view from North	August 2002	1

Certified By:

Certified By:

	Month	Year
1.	August	2002

Sheep Barn Farm Lane



Identification:

Preferred Structure Name:	Sheep Barn Farm Lane
Structure Number:	01.D
Other Structure Name(s):	Other Structure Name(s): No records.
Park:	Thomas Stone National Historic Site
Historic District:	Historic District: No records.
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251286
UTM:	Zone, Easting, Northing, Source, Datum: No records.

Historical Significance:

National Register Status:	Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: Original farm lane within Thomas Stone Plantation that existed during Stones' ownership. Used to access barn where sheep were kept.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1770	AD	1820	AD		
2.	Altered	2001	AD	2002	AD	NPS	

Function and Use:

Primary Historic Function: Vehicular Circulation

Primary Current Use: NPS Class III Special Purpose Road

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Pedestrian Circulation	Historic
2.	Vehicular Circulation	Current

Physical Description:

Structure Type: Road

Material(s):

	Structural Component(s)	Material(s)
No records.		

Short Physical Description: 10' to 12' varying width farm lane, approximately 800' - 840' long from juncture with Entrance Road B to Sheep Barn Ruin. Gravel, clay and sand composition. Altered with construction of new Visitor Center parking lot, but majority of resouce still intact.

Condition and Impacts:

Structure Condition: Fair

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Park Operations

Other Impacts:

	Other Impact Type
No records.	

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 02/01/1996

Management - Treatment:

Ultimate Structure Treatment: Preservation

Ultimate Treatment Document: Cultural Landscape Report

Ultimate Treatment Document Date: 02/01/1996

Was Ultimate Treatment Approved?: Yes

Was Ultimate Treatment Completed?: No

Ultimate Treatment Responsibility: National Park Service

Interim Treatment Responsibility: National Park Service

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural	402199		1

	Landscape Report			
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	2
3.	Other		Draft National Register Nomination	3


Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Sheep Barn Farm Lane	August 2002	1
2.		1937 aerial, road @ E, lower right of Photo	August 2002	2


	 Figure 27: 1937 aerial photograph. (National Archives)			
3.		Sheep Barn Road, view from S	August 2002	3
4.		Sheep Barn Road, view from N	August 2002	4

Certified By:

Certified By:

	Month	Year
1.	August	2002

Tobacco Barn



Identification:

Preferred Structure Name: Tobacco Barn

Structure Number: 02

Other Structure Name(s):

	Other Structure Name(s)
1.	English Barn

Park: Thomas Stone National Historic Site

Historic District:

	Historic District
No records.	

Structure State: Maryland

Structure County: Charles

Region: Northeast

Cluster: Chesapeake

Administrative Unit: George Washington Birthplace National Monument

LCS ID: 080060

UTM:

	Zone	Easting	Northing	Source	Datum
No records.					

Historical Significance:

National Register Status: Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?:	Yes
National Historic Landmark Date:	11/11/1971
Significance Level:	National
Short Significance Description:	Contributes to the historic continuum of land use at Haber de Venture. Fine example of modest Maryland tobacco barn.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1840	AD	1849	AD		
2.	Altered	1930	AD	1940	AD		
3.	Restored	1989	AD	1990	AD	NPS, WPTC	Other

Function and Use:

Primary Historic Function: Barn

Primary Current Use: Storage (Granary/Silo)

Structure Contains Museum Collections?: No

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
No records.		

Physical Description:

Structure Type: Building

Volume: 2,000 - 20,000 cubic feet

Square Feet: 1760

Material(s):

	Structural Component(s)	Material(s)
1.	Foundation	Concrete
2.	Walls	Wood
3.	Roof	Metal

Long Physical Description: 1-story, 20' wide x 44' long x 35' +/- high to roof crest. High pitch roof. 5-bay long, vertical laid siding with air interstices for air flow, gabled roof. Roof ridge is oriented E-W. Two doors on both N & S elev. Frame timbers were pit sawn & hand hewn. Restored with cedar vertical placed siding, beginning graying cycle of wood.

Condition and Impacts:

Structure Condition: Good

Year Condition Assessed: 2002

Impact Level: Low

Primary Impact: Animal/Pest Infestation

Other Impacts:

	Other Impact Type
1.	Weather

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 05/14/1992

Management - Treatment:

Ultimate Structure Treatment: Restoration

Ultimate Treatment Document: General Management Plan

Ultimate Treatment Document Date: 03/06/1990

Was Ultimate Treatment Approved?: No

Was Ultimate Treatment Completed?: Yes

Ultimate Treatment: National Park Service

Responsibility:

Ultimate Treatment Cost: 0

Interim Treatment Responsibility: National Park Service

Interim Treatment Cost: 0

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Management - Description:

Short Management Text: Updated in FY 1997, no changes in condition since update. Assessed in FY02, Condition stable.

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	National Register Information System	71000372		1

Documentation Level: Good




Last Updated By: Clark, Steve

Last Updated: 09/23/2002 09:16am

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.				1

				
2.		Tobacco Barn, view from Southeast	July 2002	1
3.		Tobacco Barn, View from Northwest	July 2002	2

Certified By:

Certified By:

	Month	Year
1.	August	2002

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT

Identification

IDLCS: 80060 Structure Number: 02

Structure Name 1: TOBACCO BARN
Structure Name 2: ENGLISH BARN
Structure Name 3:

Park Alpha Code: THST Name: THOMAS STONE NATIONAL HISTORIC SITE
ORGCODE: 4850 County: CHARLES State: MD
Regional Office: MID-ATLANTIC
Subunit ORGCODE: Name:
Alpha Code: County: CHARLES State: MD

Number of UTM's: 0 Zone/Easting/Northing

Significance

NR Status: ENTERED - UNDOCUMENTED Date: 10/15/66
Significance: LOCAL
NHL: YES Date: 11/11/71

Significance

Contributes to the historic continuum of land use at Haber de Venture. Fine example of modest Maryland tobacco barn.

Historical Information

Period of Construction: HISTORIC

Date: 1840-1849	(BU)	Designer:	( )
Date: 1930-1940	(AL)	Designer:	( )
Date: 1989-1990	(RR)	Designer: Williamsport Preservation Ct, NPS	(O)
Date: -	( )	Designer:	( )

Functions, Uses, Materials, Impacts, and Condition

Historic Functions
BARN

Current Uses
STORAGE (GRANARY/SILO)

Buildings — Materials — Structures

Foundation: CONCRETE Sub-structure:
Framing:
Walls: WOOD
Roof: METAL Super-structure:
Other:
Volume: 2,001 - 20,000 CUBIC FT

Description

2-story, 20'x44', 5-bay, w/ vertical siding, gabled roof. Roof ridge is oriented E-W. Doors on N & S elev. Frame timbers were pit sawn & hand hewn.

Impact Level: LOW Impact Types: ANIMAL/PEST INFESTATION
WEATHER

Condition: GOOD

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT
Continued

IDLCS	Park	Structure Name	Number
80060	THST	TOBACCO BARN	02

Management Information

NPS Legal Interest: FEE
Life: Exp. Date: / /
Federal Owner:
Local Owner:

Management Category: MUST BE PRES. & MAINT
Management Agreement: NONE
Management Date: 05/14/92
Agrmt. Exp. Date: / /

Proposed Ultimate Treat: Doc: Date: / /
Approved Ultimate Treat: RESTORATION Doc: GMP Date: 03/06/90

Treatment Responsibilities

Interim Treatment: NPS
Ultimate Treatment: NPS
Routine Maintenance: NPS
Cyclic Maintenance: NPS

Treatment Costs

Interim: $0 Date: /
Ultimate: $0 Date: /
Level of Estimate:
Estimator:

Approved Ultimate Treatment Completed: YES

Management Text

Major Bibliographical References

Nat. Reg.: 71000372 CSI: Nat. Cat: NO

HABS:
HAER:

BRIDGES:
DAMS:
QTRS:

CLI		CRBIB	Other
1.	HRS	1.	1.
2.	HS ASSESS	2.	2.
3.	HSR	3.	3.
4.	CLR	4.	4.
5.		5.	

Documentation Level: GOOD

Date Entered/Updated: 03/17/94 Logger: MCL

Date of Report: 03/21/94



THST
80060

NEG #
LCS THST 001

Tobacco Barn
View from southeast
May 1992



THST
80060

NEG #
LCS THST 001

Tobacco Barn
View from southeast
May 1992



THST
80060

NEG #
LCS THST 001

Tobacco Barn
View from southeast
May 1992



THST
80060

NEG #
LCS THST 001


Tobacco Barn
View from northwest
May 1992



THST
80060

NEG #
LCS THST 001

Tobacco Barn
View from southwest
May 1992



THST
80060

NEG #
LCS THST 001

Tobacco Barn
View from northwest
May 1992

LIST OF CLASSIFIED STRUCTURES

THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE

--IDENTIFICATION----------

IDLCS: 80060 STRC#: 02

STRUCTURE NAME 1: TOBACCO BARN

STRUCTURE NAME 2: ENGLISH BARN

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322100 /NORTHING 4266680

--SIGNIFICANCE----------

SIGNIFICANCE: C NR STATUS: 2 DATE: 111078 NHL: YES DATE: 11

--HISTORICAL INFORMATION----------

PER.CONSTRUCTION: HI

DATE: 1840-1849 CODE: BU DESIGNER: CODE:

DATE: 1930-1940 CODE: AL DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

FUNCTION CODES: HISTORIC 09B CURRENT 96

MATERIALS: (FOR BUILDINGS) FOUNDATION 65 WALLS 03 21 ROOF 50 OTHER 01

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) B

TEXT:

--MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: A MGT.AGREEMENT:

(DATE): 111078 (OTHER):

CONDITION: P IMPACT LEVEL: S IMPACT TYPE: PIN DET

(PROPOSED) TREAT: RR (PROPOSED) DOC: B APPROV.ULT.TREAT: APPROVAL DOC:

(DATE): 110887 (DATE):

TREATMENT RESPONSIBILITY: INTERIM TREATMENT NPS NPS or OTH

APPROVED ULTIMATE TREATMENT NPS NPS or OTH

ROUTINE MAINTENANCE NPS NPS or OTH

CYCLIC MAINTENANCE NPS NPS or OTH

INTERIM TREATMENT COST: 50,000 APPROVED TREATMENT COST:

(DATE): 0588 (DATE):

LEVEL OF ESTIMATE: C ESTIMATOR: R

INTERIM TREATMENT COMPLETED ?: N APPROV.ULT.TREAT. COMPLETED ?: N

TEXT:

--MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: P

--DESCRIPTION/TEXT----------

A handsome 5-bay wood-sided, and gable-roofed, barn, with an added early 20th forebay. Some pit sawn wood framing timber.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): ~~ENGLISH~~ TOBACCO BARN

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322100	426680

8. ESTIMATED DATE(S) OF CONSTRUCTION: c.1860/1920

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

HANDSOME 5 BAY WOOD SIDED GABLE ROOFED BARN WITH ADDED EARLY 20th CENTURY FOREBAY. SOME PIT SAWN WOOD FRAMING TIMBER. GOOD EXAMPLE OF MODEST MARYLAND BARN.

10. RELATION TO SCENE:

PART OF THE FARM COMPLEX, REMOVED FROM HOUSE-TO ALLEVIATE SIGHT-AND SMELL WITH CORNCRIB, SHEDS, MAKES A CONVINCING BARN COMPLEX.

WORKSHEET 2 PARK: HABRE DE VENTURE STRUCTURE: ENGLISH BARN

11. STRUCTURE'S PRESENT CONDITION:

MAJOR ROT DAMAGE TO SILLS AND FRAMING. SOME POSTS COMPLETELY HANGING FROM FRAME. SIGNIFICANT TIMBERS REMOVED FOR STORAGE OF FARM MACHINERY NEEDS ENGINEERING EVALUATION FOR STABILIZATION.

12. TREATMENT RECOMMENDED:

EXTERIOR		INTERIOR	
X	STABILIZATION	X	STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION		ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: SILLS AND FRAME NEED REPAIR/SHEATHING NEEDS REPAIR.

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

SEE OVERALL PLAN OF SITE FOR LOCATION OF THE BUILDING. THIS BUILDING IS ALREADY DOCUMENTED GRAPHICALLY BY THE HABS.

WORKSHEET 3 PARK: HABRE DE VENTURE STRUCTURE: ENGLISH BARN

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ . . . . . .

WOULD BE MAJOR COMPONENT OF FARM STORY IF FARM IS PART OF SIGNIFICANCE.

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: GEORGE E. THOMAS DATE: 12-22-87













THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

IDENTIFICATION

IDLCS: 80.060 STRC#: 02

STRUCTURE NAME 1: ENGLISH BARN

STRUCTURE NAME 2:

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322100 /NORTHING 4266680

SIGNIFICANCE

SIGNIFICANCE: C NR STATUS: 2 DATE: 111078 NHL: YES DATE: 111171

HISTORICAL INFORMATION

PER.CONSTRUCTION: HI

DATE: 1840 - 1849 CODE: BU DESIGNER: CODE:

DATE: 1910 - 1919 CODE: AL DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

FUNCTION CODES: HISTORIC 09FA. CURRENT 96

MATERIALS:(FOR BUILDINGS) FOUNDATION 65 WALLS 03 21 ROOF 50 OTHER 01

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) B

TEXT:

MANAGEMENT INFORMATION

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: MGT.AGREEMENT:

(DATE): (OTHER):

CONDITION: P IMPACT LEVEL: IMPACT TYPE:

(PROPOSED) TREAT: (PROPOSED) DOC: APPROV.ULT.TREAT: APPROVAL DOC:

DATE: DATE:

TREATMENT RESPONSIBILITY:

INTERIM TREATMENT	NPS	NPS or OTH
APPROVED ULTIMATE TREATMENT	NPS	NPS or OTH
ROUTINE MAINTENANCE	NPS	NPS or OTH
CYCLIC MAINTENANCE	NPS	NPS or OTH

INTERIM TREATMENT COST: APPROVED TREATMENT COST:

(DATE): (DATE):

LEVEL OF ESTIMATE: ESTIMATOR:

INTERIM TREATMENT COMPLETED? : APPROV.ULT.TREAT. COMPLETED? :

TEXT:

MAJOR BIBLIOGRAPHICAL REFERENCES

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: P

DESCRIPTION/TEXT

A handsome 5-bay wood-sided, and gable-roofed, barn, with an added early 20th forebay. Some pit sawn wood framing timber.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): ENGLISH BARN

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322100	426680

8. ESTIMATED DATE(S) OF CONSTRUCTION: c.1860/1920

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

HANDSOME 5 BAY WOOD SIDED GABLE ROOFED BARN WITH ADDED EARLY 20th CENTURY FOREBAY. SOME PIT SAWN WOOD FRAMING TIMBER. GOOD EXAMPLE OF MODEST MARYLAND BARN.

10. RELATION TO SCENE:

PART OF THE FARM COMPLEX, REMOVED FROM HOUSE-TO ALLEVIATE SIGHT-AND SMELL WITH CORNCRIB, SHEDS, MAKES A CONVINCING BARN COMPLEX.

WORKSHEET 2 PARK: HABRE DE VENTURE STRUCTURE: ENGLISH BARN

11. STRUCTURE'S PRESENT CONDITION:

MAJOR ROT DAMAGE TO SILLS AND FRAMING. SOME POSTS COMPLETELY HANGING FROM FRAME. SIGNIFICANT TIMBERS REMOVED FOR STORAGE OF FARM MACHINERY NEEDS ENGINEERING EVALUATION FOR STABILIZATION.

12. TREATMENT RECOMMENDED:

EXTERIOR		INTERIOR	
X	STABILIZATION	X	STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION		ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: SILLS AND FRAME NEED REPAIR/SHEATHING NEEDS REPAIR.

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

SEE OVERALL PLAN OF SITE FOR LOCATION OF THE BUILDING. THIS BUILDING IS ALREADY DOCUMENTED GRAPHICALLY BY THE HABS.

WORKSHEET 3 PARK: HABRE DE VENTURE . . . . . STRUCTURE: ENGLISH BARN . . . . . .

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ . . . . . .

WOULD BE MAJOR COMPONENT OF FARM STORY IF FARM IS PART OF SIGNIFICANCE.

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: GEORGE E. THOMAS . . . . . DATE: 12-22-87 . . . . . .












Old Glymont Road



Identification:

Preferred Structure Name:	Old Glymont Road
Structure Number:	02.A

Other Structure Name(s):

	Other Structure Name(s)
1.	Port Tobacco-Mattawoman Road

Park:	Thomas Stone National Historic Site

Historic District:

	Historic District
No records.	

Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251230

UTM:

	Zone	Easting	Northing	Source	Datum
No records.					

Historical Significance:

National Register Status: Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: Historic road trace that led between Port Tobacco and Mattawoman, MD that intersected with the Port Tobacco-Piscataway Road (Rose Hill Road)

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1690	AD	1760	AD		
2.	Abandoned	1820	AD	1850	AD		

Function and Use:

Primary Historic Function: Cave

Primary Current Use: Abandoned/Unmaintained

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
No records.		

Physical Description:

Structure Type: Road

Material(s):

	Structural Component(s)	Material(s)
No records.		

Short Physical Description: 10' to 12' varying width road trace, approximately 150'-200' long portion wihtin park boundaries. Gravel, clay and sand composition.

Condition and Impacts:

Structure Condition:	Unknown
Year Condition Assessed:	2002
Impact Level:	Severe
Primary Impact:	Vegetation

Other Impacts:

	Other Impact Type
1.	Erosion

Management - Legal:

Legal Interest:	Fee Simple

Management - Category:

Management Category:	Must Be Preserved and Maintained
Management Category Date:	02/01/1996

Management - Treatment:

Ultimate Structure Treatment:	Preservation
Ultimate Treatment Document:	Cultural Landscape Report
Ultimate Treatment Document Date:	02/01/1996
Was Ultimate Treatment Approved?:	Yes
Was Ultimate Treatment Completed?:	No
Ultimate Treatment Responsibility:	National Park Service
Interim Treatment Responsibility:	National Park Service
Routine Maintenance	National Park Service

Responsibility:

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural Landscape Report	402199		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	2
3.	Other		Draft National Register Nomination	3


Documentation Level: Good

Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:


	Graphic	Caption	Graphic Date/Year	Sequence
1.		Glymont Road within park boundaries	August 2002	1

Certified By:

Certified By:

	Month	Year
1.	August	2002

Lane to Glymont Road



Identification:

Preferred Structure Name: Lane to Glymont Road

Structure Number: 02.B

Other Structure Name(s):

	Other Structure Name(s)
1.	Thomas Stone Farm Lane

Park: Thomas Stone National Historic Site

Historic District:

	Historic District
No records.	

Structure State: Maryland

Structure County: Charles

Region: Northeast

Cluster: Chesapeake

Administrative Unit: George Washington Birthplace National Monument

LCS ID: 251244

UTM:

	Zone	Easting	Northing	Source	Datum
No records.					

Historical Significance:

National Register Status: Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: Original farm road within boundaries of Thomas Stone estate, providing circulation from main house to core complex and out to Old Glymont Road.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1770	AD	1772	AD		

Function and Use:

Primary Historic Function: Vehicular Circulation

Primary Current Use: NPS Class III Special Purpose Road

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Road-Related	Current
2.	Pedestrian Circulation	Historic

Physical Description:

Structure Type: Road

Material(s):

	Structural Component(s)	Material(s)
No records.		

Short Physical Description: 10' to 12' varying width farm road, approximately 2200' long to juncture with Entrance Road A. Road passes through agriculture buildings through ravine, by horse barn and connects to entrance road near house. Gravel, clay and sand composition.

Condition and Impacts:

Structure Condition: Good

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Consumptive Use

Other Impacts:

	Other Impact Type
1.	Park Operations

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 02/01/1996

Management - Treatment:

Ultimate Structure Treatment: Preservation

Ultimate Treatment Document: Cultural Landscape Report

Ultimate Treatment Document Date: 02/01/1996

Was Ultimate Treatment Approved?: Yes

Was Ultimate Treatment Completed?: No

Ultimate Treatment Responsibility: National Park Service

Interim Treatment Responsibility: National Park Service

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural Landscape Report	402199		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	2
3.	Other		Draft National Register Nomination	3


Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Farm Lane	August 2002	1
2.		Note Farm Lane to right of Barn, vw frm east	August 2002	2


3.	 Figure 27: 1937 aerial photograph. (National Archives)	1937 Aerial of Farm Roads & Entrance Lanes	August 2002	3

Certified By:

Certified By:

	Month	Year
1.	August	2002

Tenant House Lane



Identification:

Preferred Structure Name:	Tenant House Lane
Structure Number:	02.C
Other Structure Name(s):	Other Structure Name(s): No records.
Park:	Thomas Stone National Historic Site
Historic District:	Historic District: No records.
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	251272
UTM:	Zone | Easting | Northing | Source | Datum: No records.

Historical Significance:

National Register Status:	Entered - Undocumented

National Register Date: 10/15/1966

National Historic Landmark?: No

Significance Level: Not Evaluated

Short Significance Description: Original road within Thomas Stone Plantation that leads to tenant house on estate.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1780	AD	1870	AD		

Function and Use:

Primary Historic Function: Cave

Primary Current Use: NPS Class V Administrative Access Road

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
No records.		

Physical Description:

Structure Type: Road

Material(s):

	Structural Component(s)	Material(s)
No records.		

Short Physical Description: 10' to 12' varying width farm lane, approximately 720' long from juncture with Lane to Glymont Road. Gravel, clay, sand composition with grass cover towards house end.

Condition and Impacts:

Structure Condition: Fair

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Consumptive Use

Other Impacts:

	Other Impact Type
1.	Erosion

2.	Weather

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 02/01/1996

Management - Treatment:

Ultimate Structure Treatment: Preservation

Ultimate Treatment Document: Cultural Landscape Report

Ultimate Treatment Document Date: 02/01/1996

Was Ultimate Treatment Approved?: Yes

Was Ultimate Treatment Completed?: No

Ultimate Treatment Responsibility: National Park Service

Interim Treatment Responsibility: National Park Service

Routine Maintenance Responsibility: National Park Service

Cyclic Maintenance Responsibility: National Park Service

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	Cultural Landscape Report	402199		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource	2

			Study	
3.	Other		Draft National Register Nomination	3


Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/30/2002 04:25pm

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.		Tenant House Lane	August 2002	1
2.		1937 Aerial, Tenant Rd @ left lower in N-S dir.	August 2002	2


				
3.		Tenant Road, view from N	August 2002	3
4.		Tenant Farm Road, middle portion, view from N	August 2002	4
5.		Tenant House	August 2002	4

		Road, view from N to house		


Certified By:

Certified By:

	Month	Year
1.	August	2002



Corn Crib



Identification:

Preferred Structure Name:	Corn Crib
Structure Number:	03
Other Structure Name(s):	| | Other Structure Name(s) | | No records. |
Park:	Thomas Stone National Historic Site
Historic District:	| | Historic District | | No records. |
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	080061
UTM:	| | Zone | Easting | Northing | Source | Datum | | No records. |

Historical Significance:

National Register Status:	Entered - Documented
National Register Date:	11/11/1971
National Historic	Yes

Landmark?:

National Historic Landmark Date: 11/11/1971

Significance Level: Contributing

Short Significance Description: Good example of an agricultural outbuilding typical of a Maryland farm. Demonstrates the historic continuum of land use at Habre de Ventre.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1865	AD	1875	AD		
2.	Altered	1940	AD	1950	AD		

Function and Use:

Primary Historic Function: Secondary Structure (Garage)

Primary Current Use: Secondary Structure (Garage)

Structure Contains Museum Collections?: No

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
1.	Agricultural Outbuilding	Historic
2.	VACANT (NOT IN USE)	Current

Physical Description:

Structure Type: Building

Volume: 1 - 2,000 cubic feet

Square Feet: 432

Material(s):

	Structural Component(s)	Material(s)
1.	Roof	Metal
2.	Walls	Wood
3.	Foundation	Brick

Long Physical Description: 1 story, 15'-7"x26'-11" timber frame with vertical interior slats. Set on brick & stone piers, floor of crib approx 3' above grade. Masonry piers & wood frame separatd w/ thin metal sheets. Gable roof is raised seam galvanized steel. Covered exterior stock-feeding troughs probably. added 40-50 years ago

Condition and Impacts:

Structure Condition: Poor

Year Condition Assessed: 2002

Impact Level: Moderate

Primary Impact: Weather

Other Impacts:

	Other Impact Type
1.	Animal/Pest Infestation

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Should Be Preserved and Maintained

Management Category Date: 05/14/1992

Management - Treatment:

Ultimate Structure Treatment: Restoration

Ultimate Treatment Document: General Management Plan

Ultimate Treatment Document Date: 03/06/1990

Was Ultimate Treatment Approved?: No

Was Ultimate Treatment Completed?: No

Ultimate Treatment Responsibility: National Park Service

Ultimate Treatment Cost: 5000

Ultimate Treatment Cost Estimate Date: 03/01/1990

Estimate Level: Similar Facilities

Estimator:	Denver Service Center
Interim Treatment Responsibility:	National Park Service
Interim Treatment Cost:	0
Routine Maintenance Responsibility:	National Park Service
Cyclic Maintenance Responsibility:	National Park Service

Management - Description:

Short Management Text: Roof has suffered wind damage from Tornado in late April 2002. Needs replacement. Remainder of structure in good condition excluding missing slats. Paint stable, foundation appears sound.

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	National Register Information System	71000372		1
2.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	2
3.	Cultural Landscape Report	402199		3

Documentation Level: Good


Last Updated By: Clark, Steve

Last Updated: 09/23/2002 09:16am

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.				1

				
2.		Corn Crib, view from SE	July 2002	1
3.		Corn Crib, view from NW, Note roof damage	July 2002	2

Certified By:

Certified By:

	Month	Year
1.	August	2002

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT

Identification

IDLCS: 80061 Structure Number: 03

Structure Name 1: CORN CRIB
Structure Name 2:
Structure Name 3:

Park Alpha Code: THST Name: THOMAS STONE NATIONAL HISTORIC SITE
ORGCODE: 4850 County: CHARLES State: MD
Regional Office: MID-ATLANTIC
Subunit ORGCODE: Name:
Alpha Code: County: CHARLES State: MD

Number of UTM's: 0 Zone/Easting/Northing

Significance

NR Status: ENTERED - DOCUMENTED Date: 11/11/71
Significance: CONTRIBUTING
NHL: YES Date: 11/11/71

Significance

Good example of an agricultural outbuilding typical of a Maryland farm. Demonstrates the historic continuum of land use at Habre de Ventre.

Historical Information

Period of Construction: HISTORIC

Date: 1865-1875 (BU) Designer: ( )
Date: 1940-1950 (AL) Designer: ( )
Date: - ( ) Designer: ( )
Date: - ( ) Designer: ( )

Functions, Uses, Materials, Impacts, and Condition

Historic Functions	Current Uses
SECONDARY STRUCTURE (GARAGE)	SECONDARY STRUCTURE (GARAGE)
AGRICULTURAL OUTBUILDING	VACANT (NOT IN USE)

Buildings — Materials — Structures

Foundation: BRICK Sub-structure:
Framing:
Walls: WOOD
Roof: METAL Super-structure:
Other:
Volume: 1 - 2,000 CUBIC FT

Description

1 story, 15'7"x26'11" on brick & stone piers. Floor of crib approx 3' above grade. Masnry piers & wood frame separatd w/ thin metal sheets. Gable roof is raised seam galvanized steel. Covered exterior stock-feeding troughs prob. added 40-50 years ago

Impact Level: MODERATE Impact Types: WEATHER
ANIMAL/PEST INFESTATION

Condition: FAIR

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT
Continued

IDLCS	Park	Structure Name	Number
80061	THST	CORN CRIB	03

Management Information

NPS Legal Interest: FEE
Life: Exp. Date: / /
Federal Owner:
Local Owner:

Management Category: SHOULD BE PRES. & MAINT Management Date: 05/14/92
Management Agreement: NONE Agrmt. Exp. Date: / /

Proposed Ultimate Treat: Doc: Date: / /
Approved Ultimate Treat: RESTORATION Doc: GMP Date: 03/06/90

Treatment Responsibilities

Interim Treatment: NPS
Ultimate Treatment: NPS
Routine Maintenance: NPS
Cyclic Maintenance: NPS

Treatment Costs

Interim: $0 Date: /
Ultimate: $5,000 Date: 03/90
Level of Estimate: SIMILAR FACILITIES
Estimator: DSC

Approved Ultimate Treatment Completed: NO

Management Text

Major Bibliographical References

Nat. Reg.: 71000372 CSI: Nat. Cat: NO

HABS:
HAER:

BRIDGES:
DAMS:
QTRS:

CLI		CRBIB		Other
1.	HRS	1.		1.
2.	HS ASSESS	2.	10/88	2.
3.	HSR	3.		3.
4.	CLR	4.		4.
5.		5.		

Documentation Level: FAIR

Date Entered/Updated: 03/17/94 Logger: SMC

Date of Report: 03/21/94



THST
80061

NEG #
LCS-THST-003

Corn Crib
West and North Elevations
May 1992



THST
80061

NEG #
LCS-THST-003

Corn Crib
West and South Elevations
May 1992



THST
80061

NEG #
LCS-THST-003

Corn Crib
East Elevation
May 1992



THST
80061

NEG #
LCS-THST-003

Corn Crib
North and East Elevations
May 1992



THST
80061

NEG #
LCS-THST-003

Corn Crib
South Elevation
May 1992

LIST OF CLASSIFIED STRUCTURES

THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

--IDENTIFICATION----------

IDLCS: 80061 STRC#: 03

STRUCTURE NAME 1: CORN CRIB

STRUCTURE NAME 2:

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322090 /NORTHING 4266690

--SIGNIFICANCE----------

SIGNIFICANCE: U NR STATUS: 2 DATE: 111078 NHL: YES DATE: 111171

--HISTORICAL INFORMATION----------

PER.CONSTRUCTION: HI

DATE: 1865-1875 CODE: BU DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

FUNCTION CODES: HISTORIC 09B CURRENT

MATERIALS: (FOR BUILDINGS) FOUNDATION 30 WALLS 03 21 ROOF 50 OTHER 01

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) A

TEXT:

--MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: A MGT.AGREEMENT:

(DATE): 111078 (OTHER):

CONDITION: F IMPACT LEVEL: M IMPACT TYPE: PIN DET

(PROPOSED) TREAT: RR (PROPOSED) DOC: B APPROV.ULT.TREAT: APPROVAL DOC:

(DATE): 110887 (DATE):

TREATMENT RESPONSIBILITY: NPS NPS or OTH

INTERIM TREATMENT

NPS NPS or OTH

APPROVED ULTIMATE TREATMENT

NPS NPS or OTH

ROUTINE MAINTENANCE

NPS NPS or OTH

CYCLIC MAINTENANCE

INTERIM TREATMENT COST: 40,000 APPROVED TREATMENT COST:

(DATE): 0388 (DATE):

LEVEL OF ESTIMATE: C ESTIMATOR: R

INTERIM TREATMENT COMPLETED ?: N APPROV.ULT.TREAT. COMPLETED ?:

TEXT:

--MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER(1): (2):

(3): (4):

DOCUMENTATION LEVEL: P

--DESCRIPTION/TEXT----------

EXPRESSED FRAME CORN CRIB ON BRICK PIERS WITH SOFT LIME MORTAR, CAPPED BY GABLE ROOF.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): CORN CRIB

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322090	426690

8. ESTIMATED DATE(S) OF CONSTRUCTION: 1870-80

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

Handsome expressed frame corn crib on brick piers with soft lime mortar- gable roof on top of wood frame. Good example of its type that marks the evolution of the Stone estate into the family farm.

10. RELATION TO SCENE:

Part of farm complex and integral to sequence of barns.

WORKSHEET 2 PARK: HAVRE DE VENTURE STRUCTURE: CORN CRIB

11. STRUCTURE'S PRESENT CONDITION:

SOME WOOD ROT AT BASE OF BUILDING, EVIDENCE OF TERMITES AND WOOD WASP INFESTATION.

12. TREATMENT RECOMMENDED:

EXTERIOR		INTERIOR	
X	STABILIZATION	X	STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION		ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: SILLS AND BASE OF FRAME.

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

SEE OVERALL PLAN OF SITE FOR LOCATION OF THE BUILDING. THIS BUILDING IS ALREADY DOCUMENTED GRAPHICALLY BY THE HABS.

WORKSHEET 3 PARK: HABRE DE VENTURE . . . STRUCTURE: . . CORN CRIB . . . . . .

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ . . . . . .

RESTORATION DEPENDS ON FUTURE INTERPRETATION OF SITE.

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: . . GEORGE E. THOMAS . . . . . DATE: . . 12-22-87 . . . . .













THOMAS STONE NATIONAL HISTORIC ORG CODE 4850 CITY CODE 017 REG CODE MA

IDENTIFICATION----------

IDLCS: 80.061 STRC#: 03

STRUCTURE NAME 1: CORN CRIB

STRUCTURE NAME 2:

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322090 /NORTHING 4266690

SIGNIFICANCE----------

SIGNIFICANCE: U NR STATUS: 2 DATE: 111078 NHL: YES DATE: 111171

HISTORICAL INFORMATION----------

PER.CONSTRUCTION: HI

DATE: 1870 - 1879 CODE: BU DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

FUNCTION CODES: HISTORIC 09F. CURRENT 96

MATERIALS:(FOR BUILDINGS) FOUNDATION 30 WALLS 03 21 ROOF 50 OTHER 01

FRAMING 03

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) A

TEXT:

MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: MGT.AGREEMENT:

(DATE): (OTHER):

CONDITION: F IMPACT LEVEL: IMPACT TYPE:

(PROPOSED) TREAT: (PROPOSED) DOC: APPROV.ULT.TREAT: APPROVAL DOC:

DATE: DATE:

TREATMENT RESPONSIBILITY:

INTERIM TREATMENT	NPS	NPS or OTH
APPROVED ULTIMATE TREATMENT	NPS	NPS or OTH
ROUTINE MAINTENANCE	NPS	NPS or OTH
CYCLIC MAINTENANCE	NPS	NPS or OTH

INTERIM TREATMENT COST: APPROVED TREATMENT COST:

(DATE): (DATE):

LEVEL OF ESTIMATE: ESTIMATOR:

INTERIM TREATMENT COMPLETED? : APPROV.ULT.TREAT. COMPLETED? :

TEXT:

MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: P

DESCRIPTION/TEXT----------

EXPRESSED FRAME CORN CRIB ON BRICK PIERS WITH SOFT LIME MORTAR, CAPPED BY GABLE ROOF.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): CORN CRIB

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322090	426690

8. ESTIMATED DATE(S) OF CONSTRUCTION: 1870-80

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

Handsome expressed frame corn crib on brick piers with soft lime mortar- gable roof on top of wood frame. Good example of its type that marks the evolution of the Stone estate into the family farm.

10. RELATION TO SCENE:

Part of farm complex and integral to sequence of barns.

WORKSHEET 2 PARK: HAVRE DE VENTURE STRUCTURE: CORN CRIB

11. STRUCTURE'S PRESENT CONDITION:

SOME WOOD ROT AT BASE OF BUILDING, EVIDENCE OF TERMITES AND WOOD WASP INFESTATION.

12. TREATMENT RECOMMENDED:

EXTERIOR		INTERIOR	
X	STABILIZATION	X	STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION		ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: SILLS AND BASE OF FRAME.

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

SEE OVERALL PLAN OF SITE FOR LOCATION OF THE BUILDING. THIS BUILDING IS ALREADY DOCUMENTED GRAPHICALLY BY THE HABS.

WORKSHEET 3 PARK: HABRE DE VENTURE . . . STRUCTURE: . . CORN CRIB . . . . . .

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ . . . . . .

RESTORATION DEPENDS ON FUTURE INTERPRETATION OF SITE.


For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: . . GEORGE E. THOMAS . . . . . DATE: . . 12-22-87 . . . . .














Tenant House



Identification:

Preferred Structure Name:	Tenant House
Structure Number:	04
Other Structure Name(s):	No records. (Other Structure Name(s))
Park:	Thomas Stone National Historic Site
Historic District:	No records. (Historic District)
Structure State:	Maryland
Structure County:	Charles
Region:	Northeast
Cluster:	Chesapeake
Administrative Unit:	George Washington Birthplace National Monument
LCS ID:	080063
UTM:	No records. (Zone, Easting, Northing, Source, Datum)

Historical Significance:

National Register	Entered - Undocumented

Status:

National Register Date: 10/15/1966

National Historic Landmark?: Yes

National Historic Landmark Date: 11/11/1971

Significance Level: National

Short Significance Description: Contributes to the historic continuum of land use at Habre de Venture. Representative of modest Maryland rural architecture.

Construction Period:

Construction Period: Historic

Chronology:

	Physical Event	Begin Year	Begin Year AD/BC	End Year	End Year AD/BC	Designer	Designer Occupation
1.	Built	1840	AD	1859	AD		
2.	Altered	1940	AD	1959	AD		

Function and Use:

Primary Historic Function: Single Family Dwelling

Primary Current Use: VACANT (NOT IN USE)

Structure Contains Museum Collections?: No

Other Functions or Uses:

	Other Function(s) or Use(s)	Historic or Current
No records.		

Physical Description:

Structure Type: Building

Volume: 2,000 - 20,000 cubic feet

Square Feet: 1313

Material(s):

	Structural Component(s)	Material(s)
1.	Walls	Weatherboard
2.	Foundation	Concrete
3.	Roof	Metal

Short Physical Description: 1 1/2-stories. Orig portion, 14'3"x26', S addition, 14'6"x14'6", W addition, 10'4"x10'4". Porch 10'x26'. Gabled roof. Structure may have been moved to site in early 20th C., may have been slave quarters.

Condition and Impacts:

Structure Condition: Poor

Year Condition Assessed: 2002

Impact Level: Severe

Primary Impact: Animal/Pest Infestation

Other Impacts:

	Other Impact Type
1.	Weather
2.	Structural Deterioration

Management - Legal:

Legal Interest: Fee Simple

Management - Category:

Management Category: Must Be Preserved and Maintained

Management Category Date: 05/14/1992

Management - Treatment:

Ultimate Structure Treatment: Restoration

Ultimate Treatment Document: General Management Plan

Ultimate Treatment Document Date: 03/06/1990

Was Ultimate Treatment Approved?:	No
Was Ultimate Treatment Completed?:	No
Ultimate Treatment Responsibility:	National Park Service
Ultimate Treatment Cost:	80000
Ultimate Treatment Cost Estimate Date:	02/01/1990
Estimate Level:	Similar Facilities
Estimator:	Denver Service Center
Interim Treatment Responsibility:	National Park Service
Interim Treatment Cost:	0
Routine Maintenance Responsibility:	National Park Service
Cyclic Maintenance Responsibility:	National Park Service

Management - Description:

Short Management Text: Structure condition evaluated in FY97 & updated. Re-Assessed July 2002. Wind damage to roof from Tornado of late April 2002. Porch floor rotting, missing chimney stack on North end of roof. Siding missing at lower north & west corners of house.

Documentation:

References:

	Source	Reference Number	Other Information	Sequence
1.	National Register Information System	71000372		1
2.	HABS	MD-470		2

3.	Cultural Landscape Report	402199	John Milner Architects	3
4.	Historic Resources Study	402194	Wearmouth, John M. Thomas Stone NHS Historic Resource Study	4


Documentation Level: Good



Last Updated By: Clark, Steve

Last Updated: 09/23/2002 09:16am

Graphics:

Graphics:

	Graphic	Caption	Graphic Date/Year	Sequence
1.				1
2.		Tenant House, view from SE	July 2002	2
3.		Tenant Hse, vw frm NW, note missing chimney	July 2002	3

				
4.		Damaged/missing siding, view from north	July 2002	4
5.		Wind damage to porch, rotting floor, vw frm N	July 2002	5

Certified By:

Certified By:

	Month	Year
1.	August	2002

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT

Identification

IDLCS: 80063 Structure Number: 04

Structure Name 1: TENANT HOUSE
Structure Name 2:
Structure Name 3:

Park Alpha Code: THST Name: THOMAS STONE NATIONAL HISTORIC SITE
ORGCODE: 4850 County: CHARLES State: MD
Regional Office: MID-ATLANTIC
Subunit ORGCODE: Name:
Alpha Code: County: CHARLES State: MD

Number of UTM's: 0 Zone/Easting/Northing

Significance

NR Status: ENTERED - UNDOCUMENTED Date: 10/15/66
Significance: LOCAL
NHL: YES Date: 11/11/71

Significance

Contributes to the historic continuum of land use at Habre de Venture. Representative of modest Maryland rural architecture.

Historical Information

Period of Construction: HISTORIC

Date: 1840-1859 (BU) Designer: ( )
Date: 1940-1959 (AL) Designer: ( )
Date: - ( ) Designer: ( )
Date: - ( ) Designer: ( )

Functions, Uses, Materials, Impacts, and Condition

Historic Functions
SINGLE FAMILY DWELLING

Current Uses
VACANT (NOT IN USE)

Buildings—Materials—Structures

Foundation: CONCRETE Sub-structure:
Framing:
Walls: WEATHERBOARD
Roof: CONCRETE Super-structure:
Other:
Volume: 2,001 - 20,000 CUBIC FT

Description

1 1/2-stories. Orig portion, 14'3"x26', S addition, 14'6"x14'6", W addition, 10'4"x10'4". Porch 10'x26'. Gabled roof. Structure may have been moved to site in early 20th C., may have been slave quarters.

Impact Level: MODERATE Impact Types: ANIMAL/PEST INFESTATION
WEATHER

Condition: FAIR

LIST OF CLASSIFIED STRUCTURES (LCS)
SINGLE ENTRY REPORT
Continued

IDLCS	Park	Structure Name	Number
80063	THST	TENANT HOUSE	04

Management Information

NPS Legal Interest: FEE
Life: Exp. Date: / /
Federal Owner:
Local Owner:

Management Category: MUST BE PRES. & MAINT
Management Agreement: NONE
Management Date: 05/14/92
Agrmt. Exp. Date: / /

Proposed Ultimate Treat: Doc: Date: / /
Approved Ultimate Treat: RESTORATION Doc: GMP Date: 03/06/90

Treatment Responsibilities

Interim Treatment: NPS
Ultimate Treatment: NPS
Routine Maintenance: NPS
Cyclic Maintenance: NPS

Treatment Costs

Interim: $0 Date: /
Ultimate: $80,000 Date: 02/90
Level of Estimate: SIMILAR FACILITIES
Estimator: DSC

Approved Ultimate Treatment Completed: NO

Management Text

Major Bibliographical References

Nat. Reg.: 71000372 CSI: Nat. Cat: NO

HABS: MD-470
HAER:

BRIDGES:
DAMS:
QTRS:

CLI	CRBIB	Other
1.	HRS 1.	1.
2.	HS ASSESS 2.	2.
3.	HSR 3.	3.
4.	CLR 4.	4.
5.	5.	

Documentation Level: FAIR

Date Entered/Updated: 03/17/94 Logger: MCL

Date of Report: 03/21/94



THST
80063

NEG #
LCS THST 001

Tenant House
West elevation
May 1992



THST
80063

NEG #
LCS THST 001

Tenant House
View from southwest
May 1992



THST
80063

NEG #
LCS THST 001

Tenant House
North elevation
May 1992



THST
80063

NEG #
LCS THST 001

Tenant House
View from southeast
May 1992



THST
80063

NEG #
LCS THST 001

Tenant House
View from southwest
May 1992



THST
80063

NEG #
LCS THST 001

Tenant House
View from southeast
May 1992

CLASSIFIED STRUCT

THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

--IDENTIFICATION----------

IDLCS: 80063 STRC#: 04

STRUCTURE NAME 1: TENANT'S HOUSE

STRUCTURE NAME 2:

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322010 /NORTHING 4266400

--SIGNIFICANCE----------

SIGNIFICANCE: U NR STATUS: 2 DATE: 111078 NHL: YES DATE: 11117

--HISTORICAL INFORMATION----------

PER. CONSTRUCTION: HI

DATE: 1840-1859 CODE: BU DESIGNER: CODE:

DATE: 1940-1959 CODE: AL DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

FUNCTION CODES: HISTORIC 01A. CURRENT 96

MATERIALS: (FOR BUILDINGS) FOUNDATION 65 WALLS 21 ROOF 65 OTHER 01

FRAMING

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) B

TEXT: ORAL TRADITION ASSERTS BUILDING WAS SLAVE QUARTERS.

--MANAGEMENT INFORMATION----------

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP. DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT. CATEGORY: A MGT. AGREEMENT:

(DATE): 111078 (OTHER):

CONDITION: F IMPACT LEVEL: M IMPACT TYPE: PIN WEA

(PROPOSED) TREAT: RR (PROPOSED) DOC: B APPROV. ULT. TREAT: APPROVAL DOC:

(DATE): 110887 (DATE):

TREATMENT RESPONSIBILITY: INTERIM TREATMENT NPS NPS or OTH

APPROVED ULTIMATE TREATMENT NPS NPS or OTH

ROUTINE MAINTENANCE NPS NPS or OTH

CYCLIC MAINTENANCE NPS NPS or OTH

INTERIM TREATMENT COST: 80,000 APPROVED TREATMENT COST:

(DATE): 0388 (DATE):

LEVEL OF ESTIMATE: C ESTIMATOR:

INTERIM TREATMENT COMPLETED ?: N APPROV. ULT. TREAT. COMPLETED ?:

TEXT:

--MAJOR BIBLIOGRAPHICAL REFERENCES----------

NR REFNUM: CSI: NAT. CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: P

--DESCRIPTION/TEXT----------

Two story frame house with two 1 ½-story, one-room additions. Possibly moved to site; Colonial Revival window sash probably from mid-20th century.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): TENANT HOUSE

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322110	4266400

8. ESTIMATED DATE(S) OF CONSTRUCTION: c. 1840-1860; remodeled c. 1940-1960

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

A REPRESENTATIVE EXAMPLE OF REGIONAL RURAL ARCHITECTURE; LIGHT FRAME CONSTRUCTION WITH ENCLOSED PORCH; EXTREMELY MODEST IN SCALE WITH 3 SMALL-PROPORTIONED ROOMS ON FIRST FLOOR; PROBABLY REMODELED AROUND 1950 WHEN THE 6 OVER 6 COLONIAL REVIVAL SASH WAS INSTALLED; VERY LIKELY THE BUILDING WAS MOVED TO THE SITE IN THIS PERIOD AND SET ON ITS PRESENT CONCRETE FOUNDATION; ADDITIONAL RESEARCH AND/OR ARCHAELOGICAL EXCAVATION NECESSARY TO DETERMINE IF BUILDING WAS ORIGINALLY SLAVE QUARTERS, AS ORAL TRADITION MAINTAINS, OR SIMPLY HOUSE FOR TENANT FARMERS.

10. RELATION TO SCENE:

THE BUILDING IS ABOUT 250 YARDS FROM THE MAIN HOUSE TO THE NORTHEAST, AND IS SCREENED BY A GROVE A TREES AND THE SMALL ROAD WHICH IT FRONTS; THE TENANT HOUSE IS IN AN EMPHATICALLY SUBORDINATE POSITION WITH RESPECT TO THE MAIN HOUSE, INDICATING ITS VERY LOW POSITION IN THE SOCIAL HIERARCHY OF THE FARM.

WORKSHEET 2 PARK: HABRE DE VENTURE STRUCTURE: TENANT HOUSE

11. STRUCTURE'S PRESENT CONDITION:

THE STRUCTURE IS IN GENERALLY FAIR CONDITION ALTHOUGH THE INTERIOR SHOWS INDICATIONS OF ANIMAL INFESTATION.

12. TREATMENT RECOMMENDED:

THE PORCH WOODWORK SHOULD BE REFURBISHED AND THE INTERIOR CLEANED.

EXTERIOR		INTERIOR	
X	STABILIZATION	X	STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION		ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: THE WOOD TRIM OF THE PORCH AND THE HOUSE ITSELF ARE IN NEED OF PAINTING.

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

See overall plan of site for location of the building. This building is already documented graphically by the HABS.

WORKSHEET 3 PARK: . HABRE DE .VENTURE . . STRUCTURE: . TENANT HOUSE . . . . . .

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ (see below). .

IT SHOULD BE CONSIDERED WHETHER OR NOT ADDITIONAL RESEARCH/ARCHAEOLOGY SHOULD BE UNDERTAKEN TO DETERMINE IF BUILDING WAS INDEED SLAVE QUARTERS. IF THIS WERE THE CASE, THE BUILDING WOULD BE PRESUMABLY MORE VALUABLE TO THE SITE, AND THE ONLY SURVIVING EVIDENCE OF ITS PRE-1865 SLAVE-BASED ECONOMY. IF NOT THE CASE, THE BUILDING WOULD BE LESS INTEGRAL TO THE SITE, AND WOULD ONLY BE OF IMPORTANCE IF THE NPS CHOSE TO EMPHASIZE THE WHOLE RANGE OF THE SITE'S HISTORY AS A WORKING FARM.

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: . GEORGE E. THOMAS . . . . . DATE: . 12-22-87 . . . . .













THOMAS STONE NATIONAL HISTORIC SITE ORG CODE 4850 CITY CODE 017 REG CODE MA

IDENTIFICATION

IDLCS: 80.063 STRC#: 04

STRUCTURE NAME 1: TENANT'S HOUSE

STRUCTURE NAME 2:

STRUCTURE NAME 3:

ALPHACODE: THST

PARK SUBUNIT: SUBUNIT ORGCODE:

UTM: ZONE 18 /EASTING 322010 /NORTHING 4266400

SIGNIFICANCE

SIGNIFICANCE: U NR STATUS: 2 DATE: 111078 NHL: YES DATE: 111171

HISTORICAL INFORMATION

PER.CONSTRUCTION: HI

DATE: 1840 - 1859 CODE: BU DESIGNER: CODE:

DATE: 1940 - 1959 CODE: AL DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

DATE: - CODE: DESIGNER: CODE:

FUNCTION CODES: HISTORIC 01A. CURRENT 96

MATERIALS:(FOR BUILDINGS) FOUNDATION 65 WALLS 21 ROOF 65 OTHER 01

FRAMING

(FOR STRUCTURES) SUB-STRUCTURE

SUPER-STRUCTURE

VOLUME: (IN CUBIC FEET) B

TEXT: ORAL TRADITION ASSERTS BUILDING WAS SLAVE QUARTERS.

MANAGEMENT INFORMATION

NPS LEGAL INTEREST: FEE IF FER LIFE: OR EXP.DATE:

IF NOF FEDOWNER:

IF NOL LOCOWNER:

MGT.CATEGORY: MGT.AGREEMENT:

(DATE): (OTHER):

CONDITION: F IMPACT LEVEL: IMPACT TYPE:

(PROPOSED) TREAT: (PROPOSED) DOC: APPROV.ULT.TREAT: APPROVAL DOC:

DATE: DATE:

TREATMENT RESPONSIBILITY:		
INTERIM TREATMENT	NPS	NPS or OTH
APPROVED ULTIMATE TREATMENT	NPS	NPS or OTH
ROUTINE MAINTENANCE	NPS	NPS or OTH
CYCLIC MAINTENANCE	NPS	NPS or OTH

INTERIM TREATMENT COST: APPROVED TREATMENT COST:

(DATE): (DATE):

LEVEL OF ESTIMATE: ESTIMATOR:

INTERIM TREATMENT COMPLETED? : APPROV.ULT.TREAT. COMPLETED? :

TEXT:

MAJOR BIBLIOGRAPHICAL REFERENCES

NR REFNUM: CSI: NAT.CAT:

HABS: HAER: BRIDGES:

ROADS: DAMS: QTRS:

CRBIB (HS ASSESS): (HSPG): (HSR): (OTH):

OTHER (1): (2):

(3): (4):

DOCUMENTATION LEVEL: P

DESCRIPTION/TEXT

Two story frame house with two 1 ½-story, one-room additions. Possibly moved to site; Colonial Revival window sash probably from mid-20th century.

DATE ENTERED/UPDATED: / /

NATIONAL PARK SERVICE, MID-ATLANTIC REGION

WORKSHEET: CLASSIFIED STRUCTURE FIELD INVENTORY REPORT

1. PARK: HABRE DE VENTURE

2. STRUCTURE'S NAME (HISTORIC): TENANT HOUSE

3. OWNER(S) BEFORE ACQUISITION: MRS. PETER VISCHER

4. H.P.O. NOS.: STATE: CH-5 5. LOCAL:

6. STRUCTURE'S ADDRESS: ROSE HILL ROAD
PORT TOBACCO, MD

7. UTM LOCATION(S): (Note: Linear Structures such as roads, long walls, etc. need at least two; sites of over 10 acres need four)

Zone	Easting	Northing
18	322011	4266400

8. ESTIMATED DATE(S) OF CONSTRUCTION: c. 1840-1860; remodeled c. 1940-1960

9. ARCHITECTURAL AND/OR HISTORICAL SIGNIFICANCE:

A REPRESENTATIVE EXAMPLE OF REGIONAL RURAL ARCHITECTURE; LIGHT FRAME CONSTRUCTION WITH ENCLOSED PORCH; EXTREMELY MODEST IN SCALE WITH 3 SMALL-PROPORTIONED ROOMS ON FIRST FLOOR; PROBABLY REMODELED AROUND 1950 WHEN THE 6 OVER 6 COLONIAL REVIVAL SASH WAS INSTALLED; VERY LIKELY THE BUILDING WAS MOVED TO THE SITE IN THIS PERIOD AND SET ON ITS PRESENT CONCRETE FOUNDATION; ADDITIONAL RESEARCH AND/OR ARCHAELOGICAL EXCAVATION NECESSARY TO DETERMINE IF BUILDING WAS ORIGINALLY SLAVE QUARTERS, AS ORAL TRADITION MAINTAINS, OR SIMPLY HOUSE FOR TENANT FARMERS.

10. RELATION TO SCENE:

THE BUILDING IS ABOUT 250 YARDS FROM THE MAIN HOUSE TO THE NORTHEAST, AND IS SCREENED BY A GROVE A TREES AND THE SMALL ROAD WHICH IT FRONTS; THE TENANT HOUSE IS IN AN EMPHATICALLY SUBORDINATE POSITION WITH RESPECT TO THE MAIN HOUSE, INDICATING ITS VERY LOW POSITION IN THE SOCIAL HIERARCHY OF THE FARM.

WORKSHEET 2 PARK: HABRE DE VENTURE STRUCTURE: TENANT HOUSE

11. STRUCTURE'S PRESENT CONDITION:

THE STRUCTURE IS IN GENERALLY FAIR CONDITION ALTHOUGH THE INTERIOR SHOWS INDICATIONS OF ANIMAL INFESTATION.

12. TREATMENT RECOMMENDED:

THE PORCH WOODWORK SHOULD BE REFURBISHED AND THE INTERIOR CLEANED.

EXTERIOR		INTERIOR	
X	STABILIZATION	X	STABILIZATION
	PRESERVATION		PRESERVATION
	RESTORATION		RESTORATION
	TOTAL RECONSTRUCTION		TOTAL RECONSTRUCTION
	PARTIAL RECONSTRUCTION		PARTIAL RECONSTRUCTION
	ADAPTIVE RESTORATION		ADAPTIVE RESTORATION
	NO WORK REQUIRED		NO WORK REQUIRED

13. PARTS NEEDING SPECIAL ATTENTION: THE WOOD TRIM OF THE PORCH AND THE HOUSE ITSELF ARE IN NEED OF PAINTING.

14. SKETCH PLAN: (Show approximate overall dimensions, north point, positions of camera, scale)

See overall plan of site for location of the building. This building is already documented graphically by the HABS.

WORKSHEET 3 PARK: . HABRE DE .VENTURE . . STRUCTURE: . TENANT HOUSE . . . . . .

15. WAS NATIONAL REGISTER FORM APPROVED? (Attach copy)

[X] YES [ ] NO

16. ADDITIONAL DATA FOR ITEM . . . ABOVE.

17. ESTIMATED COSTS:

For PLANNING STUDIES (Identify) . . . . . $ . . . . . .

For HISTORIC STRUCTURES REPORT . . . . . $ . . . . . .

[ ] PART 1 [ ] PART 2 [ ] PART 3

For EXTERIOR STABILIZATION . . . . . $ . . . . . .

For ADDITIONAL EXTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ADDITIONAL INTERIOR TREATMENT AS RECOMMENDED . . $ . . . . . .

For ANY OTHER WORK NOT COVERED ABOVE (Itemize) . . . $ (see below). .

IT SHOULD BE CONSIDERED WHETHER OR NOT ADDITIONAL RESEARCH/ARCHAEOLOGY SHOULD BE UNDERTAKEN TO DETERMINE IF BUILDING WAS INDEED SLAVE QUARTERS. IF THIS WERE THE CASE, THE BUILDING WOULD BE PRESUMABLY MORE VALUABLE TO THE SITE, AND THE ONLY SURVIVING EVIDENCE OF ITS PRE-1865 SLAVE-BASED ECONOMY. IF NOT THE CASE, THE BUILDING WOULD BE LESS INTEGRAL TO THE SITE, AND WOULD ONLY BE OF IMPORTANCE IF THE NPS CHOSE TO EMPHASIZE THE WHOLE RANGE OF THE SITE'S HISTORY AS A WORKING FARM.

For TOTAL COST OF TREATMENT, AS RECOMMENDED . . . . . $ . . . . . .

18. PREPARED BY: . GEORGE E. THOMAS . . . . . DATE: . 12-22-87 . . . . .



