Fort Vancouver National Historical Site
McLoughlin House
Furniture Collection Condition Assessment

Alan Levitan
Conservator of Wooden Artifacts
Harpers Ferry Center
National Park Service

September 2008

Introduction

At the request of park Curator, Theresa Langford, I traveled to Fort Vancouver NHS to conduct a condition survey of the furniture at the McLoughlin House. The house, built in 1846, was the home of John McLoughlin, an important figure in the early settlement of the Oregon territory. McLoughlin lived in the home until his death in 1857. Following his death, his family continued to occupy the house for an additional 10 years.

The house was recognized early on for its significance in Oregon history. In one of the first historic preservation projects west of the Mississippi, it was saved from demolition and moved to its current location in 1909. During the 1930's,the building was restored and opened as an historic house museum.

Most of the furniture dates to the period of the McLoughlin occupancy but only a few pieces are associated directly with the family. All the wooden and upholstered furniture in the home was included in this survey and special attention was given to those pieces that are thought to be associated with the McLoughlin family or the Hudson Bay Company.

The purpose of this report is to help in the planning for the conservation of the furniture collection by prioritizing treatment needs and providing a time estimate for treatment. Ninety objects were examined during the course of the survey and an individual survey form was prepared for each. The survey form includes a checklist of condition problems, a condition summary, treatment priority, notes identifying significant damage, and brief treatment recommendations. Additionally, a recommendation is made as to whether the object can be treated on-site or if the extent and complexity of treatment requires laboratory treatment.

Treatment estimates are provided in terms of hours rather than dollars because the cost of conservation treatment varies from region to region, and depends to an extent on the particular conservator. It is also likely that treatment will have to be accomplished in phases over the course of a number of years, during which the cost of treatment will probably increase.

The objects are, for the most part, marked with McLoughlin Memorial Association (MMA) numbers and do not yet have NPS catalogue numbers. The marking consists of two letters and three numerals. In general, the letter designations are abbreviations of the type of furniture (CH for chair, TA for table). The marking convention is not entirely consistent and not all pieces are marked. In cases where there is no identifying number I have simply provided a descriptive name on the survey form.

The Collection

Furniture in the home is quite varied in terms of style and fabrication techniques. There are examples of high styled pieces that appear to have been imported from cosmopolitan areas, some probably of European origin, as well as what appears to be locally made, rustic furniture. The collection includes both veneered and solid wood pieces. On the whole, veneered pieces are more sensitive to damage from poor environmental conditions. There are also a number of fully and partially upholstered pieces, many of which are covered with black horsehair fabric, a common upholstery material in the mid-19th Century.

A number of the pieces were manufactured for the Hudson Bay Company. In general, these are sturdy, well made pieces. The collection includes a large number of side chairs that have Company provenance. Although very similar in appearance, close examination indicates that they are actually from three different sets.

Since objects in the collection come from a variety of different sources, it is not surprising that they are currently in a wide range of conditions. Many of the pieces exhibit damage that appears to relate to their previous environment rather than conditions in the McCloughlin house itself. However, in some case the damage does appear to have occurred while on exhibit in the home. For example, quite of few of the pieces with light damage are more severely faded on the surfaces that face the windows in the home.

Almost all the furniture exhibits some degree of damage. For most, the damage is primarily cosmetic; however, a significant number of pieces are unstable and if left untreated will continue to deteriorate. Damage to the furniture in the collection is attributable to a variety of environmental conditions as well as past usage and handling. To insure long term preservation of the collection, conservation treatment of unstable pieces should be undertaken along with improvements in environmental conditions and curatorial housekeeping practices at the site.

Typical Condition Problems Found in the Collection

- **Light Damage**

Light damage such as fading, finish damage, and embrittlement was noted on quite a number of the pieces on display in the home. It appears that there is currently UV film on the windows. This type of film typically filters out over 99% of the ultra violet rays, the most harmful component of the light spectrum; however, it does not stop the damage from visible light which can also damage organic materials. The park should consider the application of window film that filters a percentage of visible light (20-30%) in addition to the elimination of UV light.

Light damage to chest of drawers in the guest bedroom
Light from the adjacent window strikes the front portion of the chest side

Light streaming through window has bleached the top of this bedside table

Both show upholstery and gimp are discolored from light damage
As seen in areas normally covered by gimp, show upholstery was originally light blue



Original black gimp trim on this horse hair rocker has faded to off white

- **Moisture/Water Damage**
  Moisture damage was found on quite a number of pieces. The source of the damage appears to include leaks as well as the placement of plants and other moist containers on the surface of the furniture. Shellac finishes, which were quite common in the mid-19th Century, are not resistant to water damage.



Water damage from placement of moist container on top of game table in dining room



Water damage on bedstand, guest bedroom

- **Damage from Wide Fluctuations and Inappropriate Relative Humidity**
  There is currently no humidity control in the home. Damage from inappropriate humidity conditions and wide fluctuations was noted on a number of pieces, particularly lacquered and veneered objects. Loss occurs when the solid wood substrate expands and contracts in response to changes in RH loosening the bond and deforming the surface material.

Lost and lifting lacquer on side of sewing machine
Lacquer cleaving off wood substrate as wood expands and contracts in response to changes in RH

Splits in rawhide seat-most likely due to shrinkage induced by low relative humidity

- **Failed Glue Joints**
  In th mid-19th Century protenacious glues, such as hide and fish glue, were used in the fabrication of furniture. These glues are soluble in water and are subject to failure in conditions of both extremely high and low relative humidity.



Separated glue joints at corner of armoire cornice



Failed glue joint on top surface of center table

- **Missing and Loose Veneer**
  Veneer is subject to separation from the substrate and loss from both poor environmental conditions as well as poor handling and mechanical action. Many of the veneered pieces in the collection exhibit areas of loss and lifting surface.

Area of missing veneer on foot of bookcase



Missing and lifting veneer on drawer blades of chest of drawers

- **Previous Repairs**
  A wide variety of repairs to the collections have been made. Some are of high quality, but most are either of poor quality or have not withstood the rigors of time. In particular, the dining chairs have received extensive repairs, most of which are to the upper portion of the seat posts. These chairs appear to have been heavily used; some have been repaired a number of occasions.



Inappropriate fill, poor attachment between crest rail and seat post



Recent split in veneered table top telegraphs through discolored veneer patch

- **Structural insecurity**
  The nature and extent of the structural problems vary widely. Some damage results from heavy usage, while some damage results from the "inherent vice" of poor initial fabrication methods and/or materials.



Partial separation between bed rail and headboard post

Insecure join between rear foot and rail of upholstered sofa
Previous repair with angle iron re-enforcement not effective

- **Damaged Upholstery**
  Much of the show upholstery and upholstery support materials are deteriorated. The damage has been caused by a number of factors including light, high relative humidity levels, insect activity, and wear. Some of the materials used in mid-19th Century upholstery, such as jute webbing, have a limited life span even under ideal environmental conditions.

Dust cloth and jute webbing on underside of chair are deteriorated
Pressure from coil springs has resulted in detachment along front seat rail

Horsehair show upholstery on slip seat exhibits fading and embrittlement
from light and tear at center of seat

- **Insect Damage**
  There is past insect damage to both fabric and wood in the collection. No evidence of active wood boring insect infestation was noted; however, protein consuming beetles do appear to be present. These beetles can potentially damage wool fabric as well as horsehair stuffing and fabric. The presence of insects, even those not considered museum pests, can lead to infestations of insects that will damage collections. Organic material, primarily pine needles, was found within a number of drawers and cabinets. This provides a potential food source for a variety of insect pests. The site should institute an Integrated Pest Management Program that will monitor and control insect pests.

Beetle larva and associated debris on floor
adjacent to upholstered couch

Pine needles in drawer

- **Housekeeping Concerns**
  Much of the furniture would benefit by additional curatorial housekeeping. Relatively simple measures can improve the appearance of the collection and help insure its long term preservation. Heavy materials should be removed from drawers and cabinets.



Rodent droppings and nest within mantle clock

Stack of newspapers within wardrobe drawer

Survey Overview

Ninety objects in total were examined during the course of this survey and individual survey forms prepared for each. Almost all the pieces examined require some degree of treatment, although most (51) require only minor treatment - less than eight hours. In many cases, the treatment involves primarily a thorough cleaning and the application of a protective coat of paste wax to finished wood surfaces. In some instances, as noted on the survey form, the cleaning can be done by park curatorial staff rather than a conservator. An additional twenty eight pieces require a moderate level of treatment of between nine and sixteen hours, while fourteen pieces require treatment estimated to take more than sixteen hours.

Of those objects needing treatment, thirty require shipment to a conservation lab while the rest can be treated on site if a suitable space at the site can be made available. The space will need good lighting, and adequate ventilation. The recommendation of on-site or laboratory treatment is based on complexity of treatment as well as cost and potential for damage during transit.

Sixty seven pieces require eventual treatment by a conservator while four were identified as requiring immediate treatment. The pieces in the eventual treatment category will require approximately 948 hours, while the four pieces in the immediate treatment category will require 230 hours. The two most time consuming pieces are the oriental lacquered sewing cabinets. These pieces are actively deteriorating with severe structural and cosmetic problems and will require extensive treatment in the near term.

Brief, general treatment recommendations are provided for almost all the objects surveyed. In most instances, no attempt is made to specify particular methods or materials. A detailed treatment proposal should be submitted for curatorial approval by the conservator after the piece is examined and prior to treatment.

Treatment time estimates are provided for each object. These are rough estimates and are provided to assist with overall collection conservation planning, and preparation of PMIS statements. Treatment times for individual object may vary as condition problems become evident in laboratory examination and while undergoing treatment. The time estimates provided do not include transportation costs for those objects that must be shipped, or travel, or per diem costs associated with on-site conservation treatment.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Chest of Drawers Date of Survey: August 2008

Cat.No.: CT 533 ☐ associated ☒ non-associated

Location: Master Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Refinished. Drawer pulls replaced and original holes filled.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

-Minor scattered nicks and abrasions

Recommendations:

-Clean

-Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Table, Center Date of Survey: August 2008

Cat.No.: TA 516 ☐ associated ☐ non-associated

Location: Master Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Refinished. Support batten screwed to underside of top.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☒ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 14

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

-Scattered nicks, scratches, and abrasions.

-Glue join between boards on top surface has failed due to shrinkage, batten on bottom now supports top, but holds two sides apart.

Recommendations:

- Clean.
- Re-adhere join on top.
- Tone in nicks, scratches, abrasions.
- Apply paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Side Chair, upholstered slip seat Date of Survey: **August 2008**

Cat.No.: CH 423 ☐ associated ☐ non-associated (Brought around horn, 1851)

(Mate to 422/421)

Location: Master Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☒ Other Horse hair

Previous repairs: Joints re-adhered. Refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☐ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☒ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Rear surface faded from exposure to light.
- Dust cover torn.
- Webbing (original) tearing from pressure of the coil springs.

Recommendations:

- Clean/wax wood furniture.
- Tie coil springs in such a manner as to prevent them from exerting pressure on webbing and show upholstery.
- Replace dust cover.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Side Chair, upholstered slip seat Date of Survey: August 2008

Cat.No.: CH 422 ☐ associated ☒ non-associated (Mate to CH 423 and CH 421.)

Location: Master Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Horse hair

Previous repairs: Joints re-adhered
Dust cover replaced

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☒ Opaque
- ☒ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
-Scattered nicks, scratches, abrasions

Recommendations:
- Clean
- Tone in nicks, scratches, abrasions
- Reduce opaque/darkened finished areas
- Apply protective coat of paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Side Chair Date of Survey: **August 2008**

Cat.No.: CH 421 ☐ associated ☒ non-associated (Mate to CH 422/ CH 423)

Location: Master Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Joints re-adhered, glue blocks replaced. Front seat rail nailed to legs.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☒ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Dust cover torn, original webbing partially torn as a result of pressure from coil springs.
- Scattered nicks, scratches, and abrasions.
- Screw hole plugs missing from rear stiles.

Recommendations:

- Clean/wax wood frames.
- Tie coil springs in such a manner as to prevent them from exerting pressure on webbing and show upholstery, replace dust cover.
- Tone in nicks, scratches, and abrasions.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Stool Date of Survey: **August 2008**

Cat.No.: 452 S ☐ associated ☒ non-associated

Location: Master Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☐ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 2

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Gimp and upholstery faded from exposure to light
- Surfaces soiled

Recommendations:

- Vacuum upholstery through screen
- Clean wood surfaces
- Apply protective coat of paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Washstand Date of Survey: August 2008

Cat.No.: 515 ☐ associated ☒ non-associated

Location: Master Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☒ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 7

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Scattered nicks, scratches, abrasions on skirt
- Faux paint finish on top surface damaged by water
- Holes in proper left front corner, probably from hook for towel

Recommendations:

- Clean
- Fill holes
- Tone in areas of water damage, nicks, scratches, and abrasions

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Wardrobe Date of Survey: August 2008

Cat.No.: 547 ☐ associated ☒ non-associated (With grandaughter)

Location: Master Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 20

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Pediment off- found within. Turned finial split.
- Lock proper left door-handle broken.
- Beading missing from edges of drawer fronts, minor veneer losses.
- Cornice split at proper right front cover.

Recommendations:

- Repair lock, cornice, and pediment.
- Clean.
- Amalgamate crazed finish surfaces.
- Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Cradle (on rockers) Date of Survey: August 2008

Cat.No.: 497 A ☐ associated ☒ non-associated

Location: Master Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Rocker re-adhered
Appears to have been re-finished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☒ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:
- Two bent slats broken cross grain
- Screw affixing hood hoops is loose
- Scattered nicks, scratches, and abrasions

Recommendations:
- Repair slats
- Secure screw
- Tone in abrasions, and scratches
- Clean/apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Bedstead Date of Survey: **August 2008**

Cat.No.: 494 ☐ associated ☒ non-associated

Location: Master Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☒ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered nicks, scratches, paint rubs
- Rail exhibit, moderate light fading

Recommendations:

- Clean
- Reduce paint rubs
- Tone in nicks and scratches
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Feinting Couch Date of Survey: August 2008

Cat.No.: 483 ☒ associated ☐ non-associated

Location: Master Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Re-upholstered

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Feet are only exposed wood
- Show upholstery is worn and faded, some fraying of fabric along edges
- May be active insect infestation within casings, debris on floor beneath

Recommendations:

- Vacuum thoroughly
- Clean wood surfaces, apply protective coat of paste wax
- Monitor for presence of insects

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Trundle Bed Date of Survey: August 2008

Cat.No.: CH 496-1 ☐ associated ☒ non-associated

Location: Master Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Rail/post joints somewhat loose
- Scattered nicks, scratches, and abrasions
-

Recommendations:

- Clean
- Tone in nicks, scratches, and abrasions
- Re-adhere loose joints
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Washstand Date of Survey: August 2008

Cat.No.: TA 511 ☐ associated ☒ non-associated (Ship's Furniture)

Location: British Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☒ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Door hinges loose, door m and t join loose-associated splits
- Turned drawer pull loose
- Numerous nicks, scratches, abrasions, appear to date to historical usage, some appear recent

Recommendations:

- Clean
- Stabilize door, re-secure drawer pull
- Adhere splits
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Table (bedside) Date of Survey: **August 2008**

Cat.No.: TA 505 ☐ associated ☒ non-associated

Location: British Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: May be "married" piece- top appears to be replacement

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☒ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Top surface extremely faded light, little finish remains

Recommendations:

- Clean
- Apply finish to top to better blend w/turned pedestal and base.
- Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Writing Desk Date of Survey: **August 2008**

Cat.No.: CH 543 ☐ associated ☒ non-associated

Location: American Bedroom

Material: ☒ Wood ☒ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Leather

Previous repairs:

Condition Problems

Structure:
- ☒ Generally unsound
- ☒ Loose joints
- ☒ Missing elements
- ☒ Broken elements
- ☒ Failed glue joints
- ☒ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☒ Unstable, inappropriate appearance

Treatment priority:
- ☒ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 42

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Leather writing surface torn along hinge, currently separated
- Much burl veneer lost (pieces remain within desk), much loose
- Interior partitions separated
- Bottom panel split, insecurely attached

Recommendations:

-Make structural repairs, re-secure separated elements
- Re-adhere loose veneer, separated veneer, fill losses
- Reattach torn leather
- Clean/wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Ladderback Chair Date of Survey: August 2008

Cat.No.: CH 417 ☐ associated ☒ non-associated

Location: American Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Rawhide seat

Previous repairs: Previously painted-paint removed

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☒ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Rawhide seat torn

Recommendations:
- Patch seat from underside
- Clean wood and rawhide surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Sofa Date of Survey: August 2008

Cat.No.: CH 484 ☒ associated ☐ non-associated

Location: Office

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Numerous old repairs to structure and surface elements, current show upholstery is probably a replacement

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☒ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 28

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Proper left rear foot partially separated/collapsed-has been repaired in past
- Extensive veneer loss, some lifting
- Show upholstery faded, embrittled from exposure to light

Recommendations:

- Patch areas of missing veneer, re-adhere loose veneer
- Re-secure proper left rear foot
- Reduce visibility of old poorly executed repairs
- Reattach separated show upholstery

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan
Object: Secretary Date of Survey: August 2008
Cat.No.: CT 556 ☐ associated ☐ non-associated
Location: Office
Material: ☒ Wood ☒ Veneer ☐ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Leather
Previous repairs: Numerous repairs to structure, surface and finish

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☒ Broken elements
- ☒ Failed glue joints
- ☒ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☒ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☒ Opaque
- ☒ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☒ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ▪ Major (17+)

Est. hrs.: 96

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:
- Extensive veneer losses, much lifting of veneer on edges
- Loose hinges and drawer pulls
- Much of finish is soiled, areas of crazing and puddling
- Base is unstable

Recommendations:
- Make structural repairs
- Re-adhere loose veneer, patch areas of missing veneer
- Amalgamate finish, tone in areas of finish loss
- Clean, repair leather writing surface

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 435 ☒ associated ☐ non-associated

Location: Office

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Current show upholstery, needle point (floral) on blue background/refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered nicks, scratches, and abrasions. Particularly numerous on feet
- Crest rail and front legs are particularly soiled
- Needlepoint is worn at center of seat.

Recommendations:

- Clean
- Tone in abrasions.
- Apply paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair (one of set) Date of Survey: **August 2008**

Cat.No.: CH 434 ☐ associated ☐ non-associated

Location: Office

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Current show upholstery needlepoint (floral) on blue background. Refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☒ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered nicks, scratches, abrasions-particularly numerous on feet
- Scattered paint rubs
- Crest rail and legs particularly soiled

Recommendations:

- Clean
- Tone in abrasions
- Apply paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Dining Chair (1 of set) Date of Survey: August 2008

Cat.No.: CH 416 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in horsehair. Appears to be re-finished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☒ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Split on proper left side of crest rail.
- Scattered abrasions and paint rubs.
- Horsehair upholstery is faded.

Recommendations:

- Clean.
- Repair split.
- Apply protective coat of paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 403 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric 1979. Refinished, glue blocks and seat rails re-adhered, crest rail patched

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly on feet

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 410 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric 1979. Refinished, glue blocks and seat rails re-adhered. Crest Rail patched.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly on feet.

Recommendations:

- Clean.
- Tone in abrasions.
- Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 408 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric. Crest rail patched, re-adhered, refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, areas of finish loss

Recommendations:

- Clean
- Tone in finish losses
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair (1 of a set) Date of Survey: August 2008

Cat.No.: CH 401 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in 1986 and 1938. Most recent is in black horsehair

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair (1 of a set) Date of Survey: **August 2008**

Cat.No.: CH 405 ☐ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in 1986 and 1938, most recent in black horsehair

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair Date of Survey: **August 2008**

Cat.No.: CH 413 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric in 1979. Refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☒ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ■ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly numerous on feet.
- Old powder post beetle damage on seat rails.
- Cob webs beneath seat.

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 412 ☐ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric in 1979. Refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☒ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly numerous on feet
- Old powder post beetle damage on seat rails
- Cob webs beneath seat

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax to finished surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair Date of Survey: **August 2008**

Cat.No.: CH 411 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric in 1979. Refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☒ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly numerous on feet
- Old powder post beetle damage on seat rails
- Cob webs beneath seat

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Game Table Date of Survey: August 2008

Cat.No.: TA 500 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☒ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☒ Accretions
- ☐ Loss
- ☒ Light damage
- ☒ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☒ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☒ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ■ Major (17+)

Est. hrs.: 38

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Pedestal, base, and feet extremely soiled
- Surface of top exhibits, staining, water damage, and light damage
- Base is faded, some losses and tears
- Loose and lifting veneer

Recommendations:

- Clean
- Patch veneer, re-adhere loose veneer
- Repair finish on top surface
- Stabilize base

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan
Object: Game Table (mate to TA 500) Date of Survey: August 2008
Cat.No.: TA 517 ☐ associated ☒ non-associated
Location: Dining Room
Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other
Previous repairs: Veneer has been patched. Base has been replaced.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☒ Loose separated elements
- ☒ Loose veneer
- ☒ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☒ Accretions
- ☐ Loss
- ☒ Light damage
- ☒ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☒ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 40

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:
- Pedestal base and feet extremely soiled
- Surface of top exhibits staining and light damage
- Areas of loose and lifting veneer, particularly on edges of top surfaces

Recommendations:
- Clean
- Patch missing veneer, re-adhere loose veneer
- Repair finish on top surface
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Arm Chair Date of Survey: August 2008

Cat.No.: CH 431 ☐ associated ☒ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric. Refinished join between read of crest rail and seat posts repaired

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☒ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ▪ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 12

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Rear surfaces extensively fade from light exposure
- Old repairs usually obvious

Recommendations:

- Clean
- Tone in rear surface to better match adjacent surfaces
- Reduce visibility of old repairs
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair Date of Survey: **August 2008**

Cat.No.: CH 404 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in horsehair. Appears to have been refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☒ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Moderately soiled.
- Finish on proper left rear legs is blistered-possibly from proximity to heat source.
- Scattered nicks, scratches, and abrasions.

Recommendations:

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair Date of Survey: **August 2008**

Cat.No.: CH 409 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric, 1986. Refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Front feet cut down approximately 1", side seat rails angle downward.
- Scattered abrasions.

Recommendations:

- Clean
- Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Tambor Desk Date of Survey: **August 2008**

Cat.No.: _____ ☐ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Porcelain Knobs

Previous repairs: Porcelain knobs are replacements. Varnish has been over coated.

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☒ Missing elements
- ☒ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☒ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☒ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☒ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ▩ Major (17+)

Est. hrs.: 80

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Scattered losses of banding and molding
- Casters on rear legs are broken
- Finish has crazed and puddled
- Velvet writing surface with some areas of lifting edges. Pulls for writing surface supports missing

Recommendations:

- Replace missing elements
- Amalgamate finish, tone in losses
- Repair casters
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 407 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in 1979 in black horsehair fabric. Crest rail repaired, refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Scattered abrasions
- Old repair to joins in crest rail is failing

Recommendations:

- Clean
- Tone in abrasions and areas of finish loss
- Make structure repair to crest rail
- Apply protective coat of paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 402 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in 1979 black horse hair fabric. Crest rail repaired, refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Scattered abrasions.
- Old repair to joins in crest rail is failing.

Recommendations:

- Clean.
- Tone in abrasions and areas of finish loss.
- Make structure repair to crest rail.
- Apply protective coat of paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair (1 of a set) Date of Survey: **August 2008**

Cat.No.: 414 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in black horsehair fabric. Refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☒ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions.
- Old powder post beetle damage to seat rails.

Recommendations:

- Clean.
- Tone in abrasions.
- Apply protective coat of paste wax to finished surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Tea Canister Date of Survey: **August 2008**

Cat.No.: CT 522 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Lacquer

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 16

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Lacquer surface dull, damage front exposure to light and fluctuating environmental conditions
- Lid is insecure, no longer attached to 1 (of 2) hinges
- Loss of lacquer on proper left rear corner

Recommendations:

- Clean, polish lacquer
- Re-secure hinge
- Flatten and re-secure lifting flakes

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Dining Table Date of Survey: August 2008

Cat.No.: TA 502 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Brass Casters

Previous repairs: Refinished. Leaves secured by batten on underside

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 12

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly numerous on legs and apron
- Casters soiled, oxidized, yokes loose on shaft

Recommendations:

- Clean
- Tone in losses and abrasions
- Clean casters, reduce oxidation, apply micro-crystalline wax
- Apply paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan
Object: Sideboard Date of Survey: August 2008
Cat.No.: CH 550 ☐ associated ☒ non-associated
Location: Dining Room
Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other
Previous repairs: Drawer guides replaced

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 14

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Secondary wood has shrunk in number of areas resulting in splits and irregular surfaces
- Numerous small areas of veneer and molding loss
- Drawer pull from proper left side separated (found in drawer in secretary in office) items found within drawers

Recommendations:
- Clean
- Fill splits in veneer on top surfaces with pigmented wax
- Reaffix separated drawer pull, tone in recent scratches/abrasions
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Banjo Clock Date of Survey: **August 2008**

Cat.No.: CT 590 ☐ associated ☒ non-associated

Location: Dining Room

Material: ☒ Wood ☒ Veneer ☒ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☐ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☒ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.:

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

Recommendations:

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Game Table Date of Survey: August 2008

Cat.No.: 501 ☐ associated ☒ non-associated

Location: Dining Room

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Veneer replacement

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☒ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Scattered recent abrasions
- Minor losses of veneer on front edge

Recommendations:
- Clean
- Fill splits, patch veneer
- Tone in recent abrasions, scratches, amalgamate finish on top surface
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Corner Cupboard Date of Survey: August 2008

Cat.No.: CT 555 ☐ associated ☒ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☒ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☒ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 5

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Accretion/drip top of proper right door
- Moderately soiled
- Escutcheon proper light door loose

Recommendations:

- Clean/remove drip
- Secure escutcheon
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Foot Stool Date of Survey: **August 2008**

Cat.No.: CH 451 ☐ associated ☒ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered. Glue blocks altered, top may be replacement.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Gimp faded, tack missing causing gimp to sag.
- Scattered recent abrasions.

Recommendations:

- Clean.
- Tone in recent abrasions.
- Tack gimp back in place.
- Apply paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Rocking Chair Date of Survey: **August 2008**

Cat.No.: CH 442 ☒ associated ☐ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Rawhide

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☒ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Rocker painted.

-Paint on rear surface is alligatored, some flaking and lifting-probably result of exposure to light thru window.

Recommendations:

- Clean

- Stabilize flaking paint.

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dresser w/mirror Date of Survey: **August 2008**

Cat.No.: 530 ☐ associated ☐ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Minor veneer loss
- Extensive light damage on proper right side

Recommendations:

- Clean
- Fill veneer losses
- Reduce appearance of light damage with application of dark pigmented paste wax to proper right side

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Rocking Chair Date of Survey: **August 2008**

Cat.No.: CH 443 R ☐ associated ☒ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Rush Seat

Previous repairs: Chairs appears to have been converted to a rocker: feet cut down, rockers screwed to sides

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Join between front leg and stretcher loose
- Some recent abrasions on rear of crest rail

Recommendations:
- Clean
- Re-adhere loose joins
- Tone in recent abrasions

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Armoire Date of Survey: **August 2008**

Cat.No.: _____ ☐ associated ☒ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Moderately soiled
- Minor veneer losses
- Scattered recent abrasions, and scratches

Recommendations:

- Clean
- Fill veneer losses
- Tone in recent abrasions, scratches
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Tilt top table Date of Survey: August 2008

Cat.No.: 508 ☒ associated ☐ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Altered so that top no longer tilts. Failed glue joins supported by gussets from beneath.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☒ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☒ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 16

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Faded surfaces from exposure to light
- Veneer on top apron buckled, loose, scattered losses
- Glue joins on top partially separated

Recommendations:

- Clean
- Adhere loose and buckled veneer, patch as necessary
- Re-adhere separated glue joins as possible
- Reduce appearance of fading. Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Bedside stand w/ Marble Top Date of Survey: August 2008

Cat.No.: _____ ☐ associated ☒ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Marble

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☒ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 16

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Scattered abrasions at base
- Finish on proper right side faded, damage from light
- Small sections of molding lost

Recommendations:

- Clean
- Repair finish on proper right side, refinish as necessary
- Replace missing molding
- Apply paste wax to finish wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan
Object: Bedstead Date of Survey: August 2008
Cat.No.: 492 ☐ associated ☒ non-associated
Location: Guest Bedroom
Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Fabric Tester
Previous repairs: Shellac fills, appears to have been refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 12

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Scattered scratches/abrasions
- Minor veneer losses on foot board (covered by coverlet)
- Connection between bed rail and footboard on proper left side is some what loose.

Recommendations:
- Clean
- Patch veneer
- Tone in scratches, and abrasions
- Secure connection between side rail/foot board. Apply paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Washstand Date of Survey: **August 2008**

Cat.No.: 512 ☐ associated ☒ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Gallery on proper left side nailed to top with modern wire nail, end of nail bent out

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered recent abrasions
- Some finished damage
- Inappropriate previous repair

Recommendations:

- Clean
- Tone in recent losses
- Remove modern nail, fill hole, adhere gallery to top
- Apply paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Table, Scalloped Edge Date of Survey: **August 2008**

Cat.No.: TA 508 ☐ associated ☐ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☒ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 18

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Finish soiled, dull in appearance
- Scattered abrasions
- Large chip missing from top skirt

Recommendations:

- Clean
- Patch loss on skirt
- Amalgamate finish
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Chest of Drawers Date of Survey: August 2008

Cat.No.: 545 ☐ associated ☒ non-associated

Location: Guest Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☒ Opaque
- ☒ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 20

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Secondary wood on both sides has split, telegraphing thru veneer
- Finish soiled, opaque dull appearance
- Drawer guide, 2nd drawer from top needs adjustment

Recommendations:

- Clean
- Amalgamate finish
- Adjust drawer guides
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Cradle Date of Survey: August 2008

Cat.No.: 495 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Overpainted

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 1

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Folk furniture, nailed construction
- Thick paint layer

Recommendations:

- Dust
- Clean

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Child's Chair Date of Survey: August 2008

Cat.No.: CH 424 ☐ associated ☐ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Rush Seat

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 3

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Joins between stretchers and legs, slats and rear posts are loose

Recommendations:

- Adhere loose joins

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Bed, Spool turned Date of Survey: **August 2008**

Cat.No.: 483 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☐ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☐ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 2

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Ferrous hardware that serves to attach bed rails to headboard is partially broken resulting in somewhat insecure connection, will remain stable so long as pressure is not applied

Recommendations:

- Clean
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Bed Warmer Date of Survey: August 2008

Cat.No.: 562 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☐ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 3

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Ferrous sheet metal oxidized in some areas

Recommendations:

- Clean
- Apply micro-crystalline wax to ferrous surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Ladderback Chair Date of Survey: **August 2008**

Cat.No.: CH 433A ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Rush Seat

Previous repairs: Woven rush seat appears to be replacement

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 3

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered wear and abrasions, all appear to date to historic usage
- Join between front stretcher and proper light front leg is loose

Recommendations:

- Clean
- Stabilize loose joins

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Dresser Date of Survey: August 2008

Cat.No.: 531 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☒ Buckled veneer
- ☒ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☒ Accretions
- ☐ Loss
- ☐ Light damage
- ☒ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Staining, accretions on top surface
- Veneer losses on proper left side, finish damage on proper left side-may be due to proximity of heating vent

Recommendations:

- Clean, reduce staining
- Replace missing veneer, adhere loose veneer
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Chest of Drawers Date of Survey: **August 2008**

Cat.No.: 532 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☒ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☒ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 52

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Drawer guides and tops worn and missing
- Extensive veneer loss on drawer blades
- Beading on drawer fronts missing in a number of locations
- Extensive wear and finish loss on base

Recommendations:

- Clean
- Replace lost veneer, beading and moldings
- Apply finish as necessary
- Repair drawer guides

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Washstand Date of Survey: **August 2008**

Cat.No.: 513 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Completely refinished/restored

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 2

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Small nicks along bottom edge

Recommendations:

- Tone in nicks and abrasions
- Clean
- Apply paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Side chair, horsehair upholstery. Date of Survey: **August 2008**

Cat.No.: CH 418 ☐ associated ☒ non-associated

Location: Children's Bedroom

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Rear seat rail joints re-adhered. New glue blocks installed, refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☒ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ▣ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 14

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:
- Refinished
- Rear surface faded from light exposure
- Tear in horsehair seating fabric

Recommendations:
- Clean
- Tone in abrasions
- Repair finish damage
- Apply paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Whatnot Stand Date of Survey: **August 2008**

Cat.No.: 578 ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☒ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Soiled, particularly along front edges
- Some turned supports loose
- Scattered abrasions

Recommendations:

- Clean
- Reduce staining
- Tone in abrasions
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Sofa Date of Survey: August 2008

Cat.No.: 480 ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☒ Loss
- ☒ Faded
- ☐ Staining
- ☒ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 32

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Upholstery faded and discolored, gimp lost, frayed in some areas
- Crest rail heavily soiled
- Finish worn in some areas
- Scattered abrasions, particularly numerous on seat rail

Recommendations:
- Clean wood and upholstered surfaces
- Replace gimp as needed
- Apply finish as necessary/tone in losses
- Apply paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Rocking Chair Date of Survey: August 2008

Cat.No.: CH 445 ☒ associated ☐ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☒ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Soiled
- Some loss of finish
- Upholstery is faded
- Seat has coil springs, webbing torn, seat sags on bottom

Recommendations:

- Clean
- Tone in losses
- Remove dust cover, reaffix webbing to underside of seat, replace w/new dust cover

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Melodeon Date of Survey: August 2008

Cat.No.: CT 558 ☒ associated ☐ non-associated

Location: Ladies Room

Material: ☒ Wood ☐ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Ivory

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☒ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☒ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☒ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☒ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 28

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Stretcher split through, rendering base unstable
- Molding lost from sides of lid
- Scattered veneer losses, drop finial missing from proper left side
- Base heavily soiled with numerous abrasions and scratches

Recommendations:

- Clean
- Stabilize stretcher
- Replace missing veneer and molding
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Mantel Clock (Seth Thomas) Date of Survey: August 2008

Cat.No.: 392 ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☒ Veneer ☒ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☒ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 2

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Some minor losses of faux painting on front surface
- Finish crazed on sides
- Mouse nesting material found within

Recommendations:

- Clean

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Center Table, tilt top Date of Survey: **August 2008**

Cat.No.: TA 509 ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Split in top repaired and filled. Discolored fills, primarily on base.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☒ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 16

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Carved feet heavily soiled.
- Glue join in top partially separated.
- Discolored fills visually obvious.

Recommendations:

- Clean.
- Reduce discolored fills.
- Attempt to re-adhere separated glue join.
- Apply protective coat of paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Side Chair, painted Date of Survey: August 2008

Cat.No.: CH 420 ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Cane Seating

Previous repairs: Cane seat replaced, side and rear stretchers appear to be replacements, join between proper right side crest rail and post re-inforced

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☒ Deteriorated
- ☒ Losses
- ☒ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Old repair to crest rail join now loose
- Paper label affixed to underside of seat torn, coming loose from substrate

Recommendations:

- Clean
- Stabilize old repair
- Remove label and stabilize or stabilize in place by re-adhering with methyl cellulose and covering with Mylar

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Side Chair painted Date of Survey: **August 2008**

Cat.No.: CH 419 ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Rush Seating

Previous repairs: Has been repainted. Metal brace affixed to rear of proper left leg.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 2

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Minor losses of paint
- Abrasions on rear of crest rail

Recommendations:

- Clean

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Sewing Machine Date of Survey: August 2008

Cat.No.: MC 214A ☐ associated ☒ non-associated

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Leather/Drive Belt

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☒ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions along top edge of lid
- Water stain on top surface
- Edge of top surface somewhat soiled

Recommendations:

- Clean wood and ferrous surfaces
- Tone in recent abrasions
- Reduce water staining
- Apply paste wax to finished wood surfaces. Apply microcrystalline wax to ferrous machine surfaces

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Oriental Lacquer Sewing Cabinet Date of Survey: **August 2008**

Cat.No.: TA 521 ☐ associated ☒ non-associated (Very similar to 520)

Location: Ladies Sitting Room

Material: ☒ Wood ☐ Veneer ☒ Metal ☒ Glass ☒ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Ivory

Previous repairs: Old fills, toning of wood substrate. Attempted stabilization of legs

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☒ Failed glue joints
- ☒ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☐ Damaged elements
- ☒ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☒ Unstable, inappropriate appearance

Treatment priority:
- ☒ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 90

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Much flaking, lifting lacquer, much loss of lacquer
- Proper left front leg split below join with chest-unstable
- Proper right door of cabinet separated from hinges
- Door with mirror within cabinet loose on hinges

Recommendations:

- Clean, polish lacquer
- Stabilize flaking lacquer
- Stabilize loose and separated doors
- Provide structured stabilization. Optional: Fill and tone in losses (+ 40 hours)

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Bookcase Date of Survey: **August 2008**

Cat.No.: 559 ☒ associated ☐ non-associated

Location: Upstairs Hall

Material: ☒ Wood ☐ Veneer ☐ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered nicks and scratches, particularly at base and upper rail of doors
- Bottom portion of proper right front foot missing
- Splits occur on both sides, side panels remain stable

Recommendations:

- Tone in nicks and scratches
- Replace missing section of proper right front foot
- Clean
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Sofa, upholstered horsehair fabric Date of Survey: **August 2008**

Cat.No.: 482 ☐ associated ☒ non-associated

Location: Upstairs Hall

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☒ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Patterned horsehair

Previous repairs: Veneer patched proper left seat rail at rear

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions particularly along bottom edge of seat rail.
- Molding missing from proper right front foot.
- Finish dull, somewhat opaque.

Recommendations:

- Clean wood and upholstery surfaces.
- Tone in abrasions, reduce visibility of old veneer patch.
- Apply protective coat of paste wax to finished wood surfaces.

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Hall stand Date of Survey: **August 2008**

Cat.No.: CT 577 ☐ associated ☒ non-associated

Location: Downstairs Hall

Material: ☒ Wood ☐ Veneer ☒ Metal ☒ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Metal support screwed onto rear join between proper right arm and center panel

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☒ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 12

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:
- Four hat pegs damage partially lost
- Finish damage and loss on lower portion
- Some loss and chipping along bottom edge

Recommendations:
- Repair loose join
- Tone in losses
- Clean/Wax
- Optional: Repair/Replace turned pegs

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Table, Marble Top Date of Survey: August 2008

Cat.No.: TA 503 ☒ associated ☐ non-associated

Location: Downstairs Hall

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Marble

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☒ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☒ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 16

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Originally fabric skirt hung down from top-indicated by ledge and tack holes
- Beading from perimeter of drawers missing
- Soiled, particularly at base
- Nicks, scratches, and abrasions-particularly at base

Recommendations:
- Clean/Wax
- Tone in nicks, scratches and abrasions
- Replace lost beading
- Optional: Replace fabric skirt

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Dining Chair (1 of set) Date of Survey: August 2008

Cat.No.: CH 437 ☒ associated ☐ non-associated

Location: Parlor

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions, particularly on feet
- Cob webs under seat

Recommendations:

- Clean
- Tone in finish losses/abrasions
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Desk Date of Survey: August 2008

Cat.No.: CT 551 ☐ associated ☒ non-associated (Brought around Cape Horn 1851)

Location: Parlor

Material: ☒ Wood ☒ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other Felt writing surface

Previous repairs: Numerous

Condition Problems

Structure:
- ☐ Generally unsound
- ☒ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☒ Failed glue joints
- ☒ Splits, unstable
- ☒ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☒ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☒ Paint spatters
- ☒ Accretions
- ☐ Loss
- ☐ Light damage
- ☒ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☒ Loss
- ☐ Faded
- ☐ Staining
- ☒ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☒ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ☒ Major (17+)

Est. hrs.: 32

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Stencil of manufacture proper right top drawer
- Structure appears to have been altered
- Slant top loose on hinges
- Proper left mortise and tenon join separated. Losses in felt writing surface

Recommendations:

- Make structural repairs
- Patch veneer
- Tone in losses of finish
- Clean/Wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Drop Leaf Table Date of Survey: August 2008

Cat.No.: TA 507 ☒ associated ☐ non-associated

Location: Parlor

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Finish on top faded from exposure to light
- Minor veneer losses on base

Recommendations:
- Clean
- Fill veneer losses
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Oriental Lacquer Sewing Cabinet Date of Survey: **August 2008**

Cat.No.: 520 ☒ associated ☐ non-associated

Location: Parlor

Material: ☒ Wood ☐ Veneer ☐ Metal ☒ Glass ☒ Lacquer ☐ Upholstery ☒ Gilt ☒ Other Ivory

Previous repairs: Old fills, toning of losses

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☒ Missing elements
- ☐ Damaged elements
- ☒ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☒ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☐ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☒ Unstable, inappropriate appearance

Treatment priority:
- ☒ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☐ Moderate (9-16)
- ▩ Major (17+)

Est. hrs.: 70

☐ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☒ Treatment should be performed in lab

Notes:

- Flaking lacquer surface
- Some losses of lacquer, particularly along upper edge of chest
- Mirrored door within cabinet unstable

Recommendations:

- Clean, polish lacquer
- Stabilize flaking lacquer
- Stabilize door
- Optional: fill and tone in losses (+40 hrs)

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Dining Chair Date of Survey: August 2008

Cat.No.: CH 436 ☒ associated ☐ non-associated

Location: Parlor

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been refinished. Glued repair to leg

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Scratches and abrasions on legs
- Crest rail soiled

Recommendations:
- Clean
- Tone in scratches and abrasions.
- Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Piano Date of Survey: August 2008

Cat.No.: CT 553 ☐ associated ☒ non-associated

Location: Parlor

Material: ☒ Wood ☒ Veneer ☒ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☒ Other ivory

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☒ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☒ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 14

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Scattered finish losses and abrasions.
- Water damage on top surf
- Minor veneer losses.

Recommendations:
- Treat on site
- Clean
- Repair water damage, tone in losses
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair (1 of set) Date of Survey: **August 2008**

Cat.No.: CH 400 ☒ associated ☐ non-associated

Location: Parlor

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Has been reupholstered with horsehair. Refinished.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☒ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☒ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 6

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Soiled, paint rubs and spatters
- Scattered abrasions, particularly numerous on feet

Recommendations:

- Clean
- Remove paint rubs and spatters mechanically
- Tone in finish losses and abrasions
- Apply paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Rocking Chair, horsehair upholstery Date of Survey: **August 2008**

Cat.No.: 441 R ☐ associated ☒ non-associated

Location: Parlor

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Appears to have been reupholstered. Panel installed beneath seat.

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☒ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☐ Dust
- ☐ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☐ Minor (1-8)
- ☒ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 10

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:
- Gimp trim faded
- Finish soiled
- Veneer loss on front seat rail
- Scattered nicks, scratches, and abrasions

Recommendations:
- Clean
- Tone in nicks, scratches, and abrasions
- Fill area of lost veneer-tone in
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Sofa, horsehair upholstery Date of Survey: **August 2008**

Cat.No.: CH 481 ☐ associated ☒ non-associated

Location: Parlor

Material: ☒ Wood ☒ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☐ Scratches
- ☐ Dents
- ☐ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☒ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 7

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Some small tears and areas of loss of upholstery
- Minor scattered nicks and abrasions

Recommendations:

- Stabilize upholstery
- Tone in nicks and abrasions
- Clean/Vacuum
- Apply protective coat of paste wax to finished wood surfaces

National Park Service
Harpers Ferry Center
P.O. Box 50
Harpers Ferry, WV 25425

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: Al Levitan

Object: Side Chair, horsehair upholstery Date of Survey: August 2008

Cat.No.: CH 400 ☒ associated ☐ non-associated (1 of a set)

Location: Parlor

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☒ Other horsehair

Previous repairs: Glue blocks replaced. Reupholstered 1979

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☒ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 3

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Minor scratches and abrasions.

Recommendations:

- Clean
- Tone in abrasions.
- Apply protective coat of paste wax.

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: Fort Vancouver National Historic Site, McLoughlin House Conservator: Al Levitan

Object: Tilt-Top Table Date of Survey: August 2008

Cat.No.: TA 500 ☐ associated ☒ non-associated

Location: Parlor

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☐ Upholstery ☐ Gilt ☐ Other

Previous repairs:

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☒ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☐ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☐ Dust
- ☐ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☒ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☐ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 8

☐ Treatment can be performed on site ☒ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Failed glue joint on top as a result of shrinkage across grain
- Scattered nicks, scratches, and abrasions

Recommendations:

- Clean
- Tone in nicks, scratches, and abrasions
- If possible re-adhere glue joint in top
- Apply protective coat of paste wax

National Park Service
Harpers Ferry Center
Media Assets - Wood & Furniture

Condition Survey

Park: **Fort Vancouver National Historic Site, McLoughlin House** Conservator: **Al Levitan**

Object: Dining Chair (one of a set) Date of Survey: **August 2008**

Cat.No.: CH 406 ☒ associated ☐ non-associated

Location: Dining Room

Material: ☒ Wood ☐ Veneer ☐ Metal ☐ Glass ☐ Lacquer ☒ Upholstery ☐ Gilt ☐ Other

Previous repairs: Reupholstered in 1986 and 1938, most recent in black horsehair

Condition Problems

Structure:
- ☐ Generally unsound
- ☐ Loose joints
- ☐ Missing elements
- ☐ Broken elements
- ☐ Failed glue joints
- ☐ Splits, unstable
- ☐ Splits, stable
- ☐ Warp, twist
- ☐ Insect damage (inactive)
- ☐ Active insect infestation

Other:

Surface Elements:
- ☐ Missing elements
- ☐ Damaged elements
- ☐ Loose separated elements
- ☐ Loose veneer
- ☐ Buckled veneer
- ☐ Missing veneer
- ☒ Scratches
- ☒ Dents
- ☒ Abrasions

Other:

Paper Label
- ☐ Deteriorated
- ☐ Losses
- ☐ Separated from substrate

Finish:
- ☒ Dust
- ☒ Soiled
- ☐ Paint spatters
- ☐ Accretions
- ☐ Loss
- ☐ Light damage
- ☐ Staining
- ☐ Crazing
- ☐ Bloom
- ☐ Sticky
- ☐ Opaque
- ☐ Darkened
- ☐ Linseed oil accretions
- ☐ Water Damage

Other:

Upholstery:
- ☒ Dust
- ☒ Soiled
- ☐ Loss
- ☐ Faded
- ☐ Staining
- ☐ Tears
- ☐ Insect damage
- ☐ Sub-structure deteriorated
- ☐ Light damage

Hardware
- ☐ Inappropriate replacement
- ☐ Broken, loose, missing elements
- ☐ Abraded
- ☐ Oxidized
- ☐ Polish residue

Other:

Condition Summary

- ☒ Stable, appearance appropriate to historic period
- ☐ Stable, inappropriate appearance
- ☐ Damaged/missing elements, appropriate to historic period
- ☐ Some unstable elements
- ☐ Unstable, acceptable appearance
- ☐ Unstable, inappropriate appearance

Treatment priority:
- ☐ Immediate treatment by conservator, lack of treatment will result in further damage
- ☐ Eventual treatment by conservator
- ☐ Treatment should be performed by curatorial staff
- ☒ Treatment can be performed by conservator or curatorial staff
- ☐ No treatment required

Treatment Estimates:
- ☒ Minor (1-8)
- ☐ Moderate (9-16)
- ☐ Major (17+)

Est. hrs.: 4

☒ Treatment can be performed on site ☐ Treatment can be performed on site OR in lab ☐ Treatment should be performed in lab

Notes:

- Scattered abrasions

Recommendations:

- Clean
- Tone in abrasions
- Apply protective coat of paste wax