۲.	1/220	• •	Pretes	· · ·	•		
LC	5 #42 ROMO		NO PHOT	O AVAILABL			
A		CLASSIFIED ST		FIELD INVE 5" B&W Pho			
	REGION RMR	PARK/AREA				NPS ORGANI	
	STRUCTURE NAME	under Lake Patr	<u>ol Cabin</u>		S'	TRUCTURE NO	239
	ORDER OF SIGNIFICAN	CE: National		Stat	:e 🔲	Local	X
	TREATMENT RECOMMEND	ED: Est.	Cost of	Treatment	Recommend	ed: \$2000	
	<ul> <li>Preservation</li> <li>Restoration</li> <li>Reconstruction</li> <li>Partial Reconst</li> <li>Adaptive Restor</li> </ul>	Date Est. ruction	of this Interim	Estimate:_ Cost (othe	er than ro	utine maintene mended Treatme \$	
	LOCATION OF STRUCTU	RE: Wild Basi	n 1		T TV 22AT	AND ACREAGE (i	f not
	A 1 3 4 4 5 Zone E a s t i USGS map: Isolatic	$\frac{1   8   0}{1   9   9   9   1   1   1   1   1   1   $		410 F		complex or dis	
	STUDIES REQUIRED:				CEY:		
	N Historical Stud	ies Plan			t needed	<del></del>	
	🗶 Historic Resour	ce Study			rogrammed		
	Historic Struct	-			mpleted		
	N Historic Furnis		o · 1		nderway		
	A Historic Struct	ule lleselvacio	ii Guide	N - 16	quirea, D	ut not yet sch	leuureu
	STRUCTURE: Type of	, and compositi	07.				
	SIRUCIORE: Type Of	., and compositi		abin, log_			
	Physical Description cabin. It is a pice gabled roof. It dat side-wall fireplace port the gabled root porch cover.	turesque little tes to 1930. F chimney. The	log cab oundatio logs are	in; one-ro n is rubbl chinked w	om, approx estone mas ith cement	sonry, as <b>is</b> the Pole rafter	vith ne out- rs sup-
	Significance: Cri	erion (c)		·····		· ····································	
	The structure is style. The saddl the corner notchi NPS-Rustic style	e notched log c	onstruct: e roof a	ion, with nd rubbles	<u>log crowns</u> tone found	extending bevo	one
					·····		
				(cont:	inue on re	verse if neces	ssary)
	PRESENT CONDITION:	Excellent Unaltered X	Alter	Good X	Fair	Deteriorat Site X Moved	ted
	Report prepared by	: Lance R. Will	i <b>a</b> ms				
	Paula R 11	elliame					۱.
	<u>Signature</u>		11 11 1	5 1937 -	June 30	فبسويج بمسجوب والمتحدين وموجر والمتحد والمتحد	1 <b>97</b> <u>6</u>
	Signatur	5	JUN	5 (SO)		Date	NT: 8323-75

United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_ Page \_\_\_\_\_

Thunder Lake Patrol Cabin Bounder Co., COLORADO

(Rocky Mountain National Park MPS) 87001124

ADDITIONAL DOCUMENTATION APPROVAL

12/24/92 autonicon flee

NPS Form 10-900a (Rev. 8/86) NPS/WHS Word Processor Format (Approved 03/88)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section number \_\_\_\_\_ Page \_\_\_\_ Addendum For HS-239

3

## INTERIOR DESCRIPTION

This is a small, log walled patrol cabin, used sporadically during the summer as a ranger station and shelter for rangers on patrol in the back country of Wild Basin. It is not used during the winter and can not be reached because of snow drifts. The interior is one multi-purpose room. The interior has a plywood floor, with log walls, no ceiling and exposed log rafters and roofing boards. There is one wood stove/fireplace with chimney of uncoursed fieldstone and mortar in the corner of the cabin. The exterior is of square notched log walls with a gable roof that has exposed rafter tips and is covered with wood shingles. The exterior and interior have been maintained over the years, but the materials and techniques used in the maintenance are in keeping with the Rustic architectural character of the cabin.

RELIVEN

NOV 09 1992

NPS Form 10-900a (Rev. 8/86) NPS/WHS Word Processor Format (Approved 03/88)

United States Department of the Interior NATIONAL National Park Service

National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section number 8 Page 1 Addendum for HS-239

## INTERIOR SIGNIFICANCE

This cabin, originally built in 1930, stands as a good example of the National Park Service Rustic design philosophy as it was practiced at Rocky Mountain National Park during the 1930s. Howard R. Baker of the NPS Design Staff and Thomas C. Vint, a landscape architect, were responsible for the development of facilities at Rocky Mountain National Park and this building, along with others clearly shows the influences of the Rustic design philosophy that those two individuals employed for the projects there. Since its construction the building. has experienced a number of routine maintenance activities. However, these have not effected the Rustic character of the building, either on the inside or the outside. The present exterior and interior bear a striking resemblance to the original and exhibit the key characteristics of the Rustic architecture school. The building has already been listed in the National Register of Historic Places for its Rustic exterior. The interior is considered to be a significant example of the NPS Rustic design philosophy. The interior displays a Rustic flavor with key elements such as the exposed interior roof framing, log walls and stone fireplace/chimney. These are typical Rustic interior treatments as described in the context. As a result the interior is felt to be a significant example of Rustic architecture at Rocky Mountain National Park.







Thunder Lake Patrol Cabin MS-239 Rocky Mountain NP Nancy Pritchard 06/23/91 Negative on file Rocky Mountain Regional Office, NPS to w Interior



Thunder Lake Patrol Cabin HS-239 Rocky Mountain NP Nancy Pritchard 06/22/91 Negative ou file Rocky Mountain Regional Office, NPS

Front 314 to NW

