

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME ROMO PARK NUMBER 1520
STRUCTURE NAME Mess Hall and Residence STRUCTURE NUMBER HS-220
LOCATION OF STRUCTURE Milner Pass Road Camp PARK LOCATION CODE PG
NATIONAL REGISTER 0 DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO

Check all of the following categories for which NPS has treatment responsibility:

Stabilization Cyclic Maintenance Routine Maintenance Approved Ultimate Treatment

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

| | | |
|----------------------------|---------------------------|------------------------------|
| Preservation (PP) | Restoration (RR) | Reconstruction (CC) |
| Adaptive Preservation (AP) | Adaptive Restoration (AR) | Adaptive Reconstruction (AC) |
| Neglect (NG) | Remove (RM) | No Approved Treatment (NO) |

Approval Document _____ () Document Date: / /
Estimated Treatment Costs _____

| | | |
|------------------------------|------------------|---------------------------------|
| Stabilization: \$ _____ | Date: <u>/ /</u> | Level of Estimate: (A) (B) (C) |
| Approved Treatment: \$ _____ | Date: <u>/ /</u> | Estimator: (Region) (DSC) (A&E) |

STATEMENT OF SIGNIFICANCE:

Date of Construction: / / 1926 Date of Alterations: / /
Architect/Designer: Landscape Eng. Div. Historical Theme(s): NPS Rustic Architecture
History of Structure: Structure #220 was built in 1926 at an estimated cost of \$3,000. Plans were designed by personnel of the Los Angeles Landscape Engineering Division, under the supervision of Daniel P. Hull, Landscape Engineer. The building is currently used for NPS employee quarters.

Evaluation of Structure: Historic Theme Contributing X Non-Contributing _____
National Register Criteria: A B C X D (Include integrity statement)
This log structure is one of the earliest structures in the park to demonstrate the "NPS Rustic" style of architecture and contributes to the historical and environmental character of ROMO. Unaltered exterior. Integrity intact.
Bibliography: ROMO Building Maintenance Files: "Superintendent's Annual Reports 1915-1930."
Representation in Other Surveys: LCS David Adams 1/14/82

If structure has been removed, how? N/A Date: / /

Report prepared by: Carl and Karen McWilliams Date: 8 /20 /1985

LOCATION: Section 6 State CO USE: *CURRENT INTERIOR USE (NPS 28 CODE)* NO
Township 5N County Larimer Original Use Mess Hall and NPS Quarters
Range 75W Intermediate Uses Same
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: U.S. Govt. DRAWING NO. RM-44; RM 60031
Original Owner: U.S. Govt. NEGATIVE NO. _____
Intermediate Owner(s): None

Roll 22 Negative 1

PHYSICAL DESCRIPTION

TYPE OF STRUCTURE (NPS 28 CODE): BU

ARCHITECTURAL CHARACTER (STYLE): NPS Rustic
Architecture

SITE (INCLUDE ORIENTATION OF STRUCTURE): Open, native pines, firs, grasses and soils. Facade to NE.

OVERALL BUILDING PLAN (FOOTPRINT): Rectangular.
Bays: 3 by 1; Piles: 2
OVERALL DIMENSIONS: 35'0" by 18'0"

COMPOSITION (NPS 28 CODE): WD

STORIES: 1½

FOUNDATION: Low to medium, 0'0" to 3'4", of uncoursed fieldstone.

WALLS: Brown. Logs, with saddle notching at corners.

ROOF: Gable. Green wood shingles doubled every fifth course, with exposed log rafter ends. Roof is badly deteriorated. Structure still retains historic character.

CHIMNEYS: One - of red brick, on the interior of the SW ele Brick is crumbling. Two - Metal vent pipes.

PORCHES: Seven wood steps on NW elev.

WINDOWS: Six - 6 beside 6 sliders. Rectangular, green wood frames and screens, flat arches.

DOORS: Three - Single, brown, board and batten, two on facade, one on NW. elev. One - Single, brown, wood paneled on NW elev.

ADDITIONS: One - 5' by 9', shed roof, on SW. elev. Shower

INTERIOR PLAN: Three rooms used as NPS Employee's Quarters.

INTERIOR FINISHES: Walls and ceiling: Exposed log frame.
Floor: Tongue and groove wood flooring.

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



NAME: Mess Hall and Residence (HS-220)
LOCATION: Rocky Mountain National Park, Colorado
VIEW: Northeast
LOCATION OF NEGATIVE: National Park Service,
Rocky Mountain Regional Office, Denver, CO
DATE: Summer 1985
PHOTOGRAPHER: McWilliams