
CONTINUATIO	ON FROM FRONT SHEET - STRU	JCTURE NAME HS-2	28 Timberline Cabin	
OCATION:	Section 31	State CO	USE: CURRENT INTERIOR USE (NPS 28 CODE) 00	
Y	Township 6N	County Larimer	Original Use NPS Quarters	
	Range 75W		Intermediate Uses Same	
	•		PERIOD OF CONSTRUCTION (NPS 28 CODE) HI	
OWNERSHIP:	Present Owner: U.S.	Govt.	DRAWING NO. RM 1; RM 3067A; RM 5199	
	Original Owner: U.S.	Govt.	NEGATIVE NO. Roll 17 Negative Coll	
	Intermediate Owner(s):	None		
	en e	***PHYSICAL DI	ESCRIPTION***	
TYPE OF STE	RUCTURE (NPS 28 CODE):	BU	CHIMNEYS: One - Of uncoursed fieldstone, on W. elev.,	
ARCHITECTUR	RAL CHARACTER (STYLE):	,	interior.	
	DE ORIENTATION OF STRUCTO Facade and decline to S		PORCHES: Four stone and poured concrete steps, on facade.	
OVERALL BUI Bays: OVERALL DIM	LDING PLAN (FOOTPRINT): 5 by 3; Pile: 1 MENSIONS: 32'4" by	_	WINDOWS: Ten window openings are all boarded over with plywood. Concrete lintels and sills.	
COMPOSITION	(NPS 28 CODE): ST			
STORIES: One			DOORS: Two - Single, brown, vertical wood boards with interior batts. One on facade, the other on E. elev.	
FOUNDATION: Stone walls are level with grade.			· · · · · · · · · · · · · · · · · · ·	
			ADDITIONS: None	
WALLS: Co	ncrete with uncoursed fie	ldstone veneer.		
	•		INTERIOR PLAN: Two rooms currently vacant.	
ROOF: Gable. Rolled asphalt with exposed ridgepole, plate logs, and closely spaced purlins. Log lattice work on top of rolled asphalt.			INTERIOR FINISHES: Perimeter walls: Concrete. Partition walls: Wood frame. Ceiling: Exposed log frame. Floor: Wood boards.	

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT (Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME ROMO PARK NUMBER 1520				
STRUCTURE NAME Timberline Cabin STRUCTURE NUMBER HS-28				
LOCATION OF STRUCTURE Fall River Road PARK LOCATION CODE FP				
Determined Eligible NATIONAL REGISTER SHPO (5) DATE: 8 / //5 MANAGEMENT CATEGORY: (A) (B) (C)				
PS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: NO				
Check all of the following categories for which NPS has treatment responsibility:				
Stabilization 💢 Cyclic Maintenance 🌣 Routine Maintenance 🌣 Approved Ultimate Treatment 🌣				
(ROCKY MOUNTAIN REGION USE ONLY)				
APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:				
Preservation (PP) Restoration (RR) Reconstruction (CC) Adaptive Preservation (AP) Adaptive Restoration (AR) Adaptive Reconstruction (AC) Neglect (NG) Remove (RM) No Approved Treatment (NO)				
Approval Document Date: //				
Estimated Treatment Costs				
Stabilization: \$ Date: // Estimate: (A) (B) (C) Approved Treatment: \$ Date: // Estimator: (Region) (DSC) (A&E)				
STATEMENT OF SIGNIFICANCE:				
Date of Construction: / /1925 Date of Alterations: / /				
Architect/Designer: Landscape Eng. Div. Historical Theme(s): NPS Rustic Architecture				
History of Structure: Built in 1925, at an estimated cost of \$2,400, Building #28				
originally served as quarters for crews working on the Fall River Road. The huild- ing also served as a natrol cabin and a caretaker's cabin for the Fall River Road.				
It currently is vacant. Designs for the structure were prepared by members of the				
Landscape Engineering Division, Los Angeles Office, under the supervision of				
T. C. Vint, Assistant Landscape Engineer.				
Evaluation of Structure: Historic Theme Contributing X Non-Contributing National Register Criteria: Ax B CxD (Include integrity statement)				
This stone structure illustrates the development of the "NPS Rustic" style of				
architecture, and greatly contributes to the historical and architectural				
character of the park. There are no records of any alterations. Bibliography: ROMO Building Maintenance Files. "Supt. Annual Reports.				
1915-1930." National Register Nomination 7/29/75. Representation in Other Surveys: LCS. Lance Williams, 6/28/1976				
If structure has been removed, how? N/A Date: //				
Report prepared by: Carl and Karen McWilliams Date: 8 / 1 /1985				





NAME: Timberline Cabin (HS-28)

LOCATION: Rocky Mountain National Park, Colorado

VIEW: Southeast

LOCATION OF NEGATIVE: National Park Service,

Rocky Mountain Regional Office, Denver, CO

DATE: Summer 1985

PHOTOGRAPHER: McWilliams