

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME ROMO PARK NUMBER 1520
STRUCTURE NAME Residence STRUCTURE NUMBER HS32
LOCATION OF STRUCTURE Wild Basin PARK LOCATION CODE WB
NATIONAL REGISTER 0 DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT: No

Check all of the following categories for which NPS has treatment responsibility:
Stabilization () Cyclic Maintenance () Routine Maintenance () Approved Ultimate Treatment ()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /
Estimated Treatment Costs _____
Stabilization: \$ _____ Date: / / Level of Estimate: (A) (B) (C)
Approved Treatment: \$ _____ Date: / / Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: / /1931 Date of Alterations: / /
Architect/Designer: _____ Historical Theme(s): NPS Rustic Architecture
History of Structure: Constructed by the National Park Service at an estimated original cost of \$2,500 in 1931. Plans approved by Vint were drawn by the Branch of Plans and Design.

Evaluation of Structure: Historic Theme Contributing Non-Contributing _____
National Register Criteria: A B D (Include integrity statement)
The architecture of this structure is typical of early built NPS Rustic Architecture in Rocky Mountain National Park. Characteristic elements of the structure include painted brown logs which extend beyond the corner notching and wood shingle roof with exposed
Bibliography: ROMO Maintenance Files rafter ends.

Representation in Other Surveys: LCS, David Adams 1/14/82
If structure has been removed, how? N/A Date: / /
Report prepared by: Carl and Karen McWilliams Date: 8 /20/85

JUN 5 1987

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME 32 Residence

LOCATION: Section 22 State CO
Township 3N County Boulder
Range 73W

USE: CURRENT INTERIOR USE (NPS 28 CODE) NQ
Original Use _____
Intermediate Uses _____
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: U.S. Govt
Original Owner: _____
Intermediate Owner(s): _____

DRAWING NO. RM 1000
NEGATIVE NO. Rel 2 - Negative 20

PHYSICAL DESCRIPTION

TYPE OF STRUCTURE (NPS 28 CODE): BU
ARCHITECTURAL CHARACTER (STYLE): NPS Rustic Architecture

CHIMNEYS: one--of uncoursed fieldstone, interior, on SE elev.
two--metal vent pipes

SITE (INCLUDE ORIENTATION OF STRUCTURE): Pine forest,
native aspens, grasses and soils. Facade to NW

PORCHES: one--poured concrete stoop, on facade
six--wood steps with 2" by 4" railing on NE elev.

OVERALL BUILDING PLAN (FOOTPRINT): Rectangular
Bays:3 by 2; piles: 2
OVERALL DIMENSIONS: 31'0" by 23'0"

WINDOWS: 12--single or 2-ganged, 4 or 6-light casements.
rectangular, gold wood frames and screens, flat arches

COMPOSITION (NPS 28 CODE): WD

DOORS: two--single, gold, board and batten, with wood screen
doors, one on facade, the other on the NE elev

STORIES: one
FOUNDATION: low, 0'0" to 3'4". of uncoursed fieldstone,
buttressed at corners

ADDITIONS: none


WALLS: Brown logs, with saddle notching at corners

INTERIOR PLAN: three rooms used as NPS employee's quarters

ROOF: Gable. Brown wood shingles with exposed log rafter
ends, purlins, ridgepole and plate logs

INTERIOR FINISHES: Walls and ceiling: plasterboard.
Floors: linoleum and tongue and groove wood flooring.

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



NAME: Wild Basin Residence (HS-32)
LOCATION: Rocky Mountain National Park, Colorado
VIEW: West
LOCATION OF NEGATIVE: National Park Service,
Rocky Mountain Regional Office, Denver, CO
DATE: Summer 1985
PHOTOGRAPHER: McWilliams