
(Attach 4" x 5" Black and White Photograph)

REGION	RMR	PARK/AREA NAME	ROMO	PARK N	UMBER	1520	
STRUCTUR	E NAME	Willow Park Stab	le	STRUCTURE N	UMBER	HS-258	
LOCATION		E <u>Fall River Pass</u> ermined	سری مرکز میکرونی م	PARK, LOCATION	CODE	FP	
NATIONAL	REGISTER eli	gible SHPO ⁽⁵⁾ DATI	E: <u>8/ /7</u>	MANAGEMENT CAT	EGORY:	(A) (B)	(C) (D)
NPS LEGA	L INTEREST	Fee		MANAGEMENT AGR	EEMENT:	No	
Check al	l of the fol	lowing categories	for which N	PS has treatmen	t respo	nsibility	r:
Stabiliz.	ation() Cycl	ic Maintenance() 1	Routine Mair	tenance() Appro	ved Ult	imate Tre	atment (X)
(ROCKY M	OUNTAIN REGI	ON USE ONLY)					
APPROVED	ULTIMATE TR	EATMENT OR RESOUR	CE MANAGEMEN	T PLAN, CULTURA	L COMPO	NENT DESI	GNATION:
	Preservatio	(PP) Restoration n (AP) Adaptive I (NG) Remove		<pre>(RR) Reconstru (AR) Adaptive (RM) No Approv</pre>	Reconst	ruction ((CC) (AC) (NO)
• •	Document d Treatment	Costs		()Document Dat Level of	e: _/		
Stabiliz Approved	ation: Treatment:	\$Date \$Date	the second s	Estimate: (Estimator:		• •	(A&E)
STATEMEN	T OF SIGNIFI	CANCE:				-	
Architec History to accom Road Camp use since	for the use e L932 when Landscape En	Daniel P. Hull	the Willow oin. The tw ing the Fall bened. Plan	Theme(s): NPS R Park Stable, was b served origina River Road. Th s were designed	constru Ily as t e stable by membe	icted in 1 The Willow has seen ins of the	l926 ⊽ Park ⊽ little ⊽ Los
National The Will craftsma ends cor	Register Cr ow Park Stab Inship eviden Itribute to t	ure: Historic The iteria: A_B_CX le is an excellent ced in the double- he historical and a	D_ (Include example of saddle notch architectura	e integrity stat early NPS Rustic ing, with saplin 1 character of t	ement) Archite g chinki he NPS F	ecture. I ng and sa Sustic the	awn leg
Bibliogr Register Represen	of Historic	Maintenance Files; <u>Places Nomination</u> her Surveys:	, Ferrel Atk				-
If struc	ture has bee	en removed, how?	N/A		Date:		-
Report p	repared by:	Carl and Karen	McWilliams		Date:	8/ 20/ 85	_

			illow Park Stable			
LOCATION:	Section 6	State CO County Larimer	USE: CURRENT INTERIOR USE (NPS 28 CODE) 00			
•	Township 5W		Original Use Stable			
	Range 74W		Intermediate Uses			
			PERIOD OF CONSTRUCTION (NPS 28 CODE) HI			
OWNERSHIP:	Present Owner: U.S. Go	v't	DRAWING NO. RM-44; RM-60031			
	Original Owner: H.G. Go	<u>v! </u>	NEGATIVE NO.			
	Intermediate Owner(s):	None				
			Roll 25 Negative 15			
	,	***Physical	L DESCRIPTION***			
TYPE OF ST	RUCTURE (NPS 28 CODE):	BU	CHIMNEYS: None			
ARCHITECTU	RAL CHARACTER (STYLE): NP	S rustic architectu	re			
	UDE ORIENTATION OF STRUCTU asses and soils. Log corra		PORCHES: None			
	ILDING PLAN (FOOTPRINT): y l; Pile: 1 MENSIONS: 24'0" by 12'0"	Rectangular	WINDOWS: None			
COMPOSITION	W (NPS 28 CODE): WD		-			
STORIES: Or	ne		DOORS: Facade is open, consisting of three bays			
FOUNDATION: Stone piers, level with grade			· · ·			
			ADDITIONS: None			
WALLS: L	arge brown logs with saddle	notching at corners	s INTERIOR PLAN: One open room, consisting of three stalls			
ROOF: Salt	box, brown wood shingles do	ubled every fifth a				
	sed log rafter ends and rid	-	INTERIOR FINISHES: Walls and cieling: Exposed log frame Floor: earth			


SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



NAME: Fall River Pass - Willow Park Stable (HS-258)

LOCATION: Rocky Mountain National Park, Colorado VIEW: Southeast

LOCATION OF NEGATIVE: National Park Service, Rocky Mountain Regional Office, Denver, CO DATE: Summer 1985 PHOTOGRAPHER: McWilliams



NAME: Willow Park Stable (HS-58) LOCATION: Rocky Mountain National Park, Colorado VIEW: East

LOCATION OF NEGATIVE: National Park Service, Rocky Mountain Regional Office, Denver, CO DATE: Summer 1985 PHOTOGRAPHER: McWilliams