

Singer's Lake Crescent Tavern (Lake Crescent Lodge),
Cabins 3-21 (Bldg. Nos. 668-674)
Barnes Point, Lake Crescent
Olympic National Park
Port Angeles Vicinity
Clallam County
Washington

HABS N. WA-186-E

HABS
WASH.
5-POAN.V,
1-E-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL PARK SERVICE
PACIFIC NORTHWEST REGION
DEPARTMENT OF INTERIOR
SEATTLE, WASHINGTON

PNR-100 6/82

**PNRO
INVENTORY**National Park Service
Pacific Northwest Region
Cultural Resources DivisionWestin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO.		2. NAME(S) OF STRUCTURE		5. ORIGINAL USE		7. CLASSIFICATION		9. RATING	
		668 CABIN 3 & 4 (Singer's Tavern)		Resort Cabins				10. DATE 1915	
3. SITE ADDRESS (STREET & NO.)		6. PRESENT USE		8. UTM ZONE		EASTING		NORTHING	
Barnes Point; Lake Crescent; Highway 101		Seasonal Resort Cabins		11. REGION		SCALE 1:24 (1:625)		QUAD NAME Lake Crescent	
4. CITY/VICINITY		COUNTY		STATE		UTM ZONE		EASTING	
Approx. 20 miles S.W. of Port Angeles, Clallam, Washington						10 440550		5322750	

12. OWNER/ADMIN ADDRESS
Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Cabin 3 & 4 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact.

U-shape in plan; each unit measures 12' x 14' with 4' wide porch extending across the main facade; 1 story; wood-frame wall construction with shingle siding; roof consists of two gables with connecting cross gable; wood shingle roof; post and pier foundation; multi-light single-leaf casement windows frame multi-pane glass and wood door on main (north) elevation; multi-light projected casement windows on south elevation; shed roof over front porch supported by posts supporting plate. Alterations: none apparent. Siting: in row arrangement with other cabins; approx. 25 yards from Lake Crescent in a grove of trees; part of the Singer's Tavern building group.

14. CONDITION					15. DANGER OF DEMOLITION? (SPECIFY THREAT)		
☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	☒ YES	☐ NO	☐ UNKNOWN


16. SIGNIFICANCE

This building contributes to the integrity of design, workmanship, setting, and sense of time and place of Singer's Tavern Group.

Singer's Lake Crescent Tavern (Lake Crescent Lodge), Cabins 3-21 (Bldg. Nos. 668-674)
HABS No. WA-186-E
(Page 1)

HABS
WASH.
5-POAH.
1-E-

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 2:11

18. LOCATED IN AN HISTORIC DISTRICT?		☐ YES	☒ NO	☐ NAME
19. PUBLIC ACCESSIBILITY		☒ YES, LIMITED	☐ YES, UNLIMITED	
		☐ NO	☐ UNKNOWN	
20. EXISTING SURVEY		☐ NH	☐ NHL	☐ KABS
		☐ COUNTY	☐ LOCAL	☐ OTHER
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER		☐ HAER-I	☐ HAER	☒ NPS
				☐ STATE

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge."
National Park Service, Pacific Northwest Region.

22. INVENTORIED BY	Leslie Helm/Gail E.H. Evans	AFFILIATION	National Park Service	DATE	9/82, 1984
--------------------	-----------------------------	-------------	-----------------------	------	------------

PNR-100 6/82

PNRO INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division

Westin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO. 		2. NAME(S) OF STRUCTURE 669 CABIN 5, 6 & 7 (Singer's Tavern)		3. ORIGINAL USE Resort Cabin	4. CLASSIFICATION	5. RATING
3. SITE ADDRESS (STREET & NO.) Barnes Point; Lake Crescent; Highway 101		6. PRESENT USE Seasonal Resort Cabin		7. DATE 1915		8. REGION PNR
4. CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		5. STATE WA		6. SCALE 1:24 (1825)		7. QUAD NAME Lake Crescent

12. OWNER/ADMIN ADDRESS
Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Cabin 5, 6 & 7 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin, and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble, it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact.


Irregular in shape; overall measurement 58' x 14' with 4' wide porch on north elevation; 1 story; wood-frame wall construction; shingle siding; 3 gables with 1 cross gable; shingle roofing material; post and pier foundation; multi-light casement windows frame multi-light glass and wood doors on main facade; projected casement windows on south elevation; shed roof porch supported by square posts under plate. Alterations: none apparent. Siting: approx. 25 yards from Lake Crescent in row arrangement with other cabins; part of the Singer's Tavern building group.

14. CONDITION	☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	☒ YES	☐ NO	☐ UNKNOWN
---------------	------------------------------------	-------------------------------	--	---------------------------------------	--------------------------------	---	---	-----------------------------	----------------------------------

16. SIGNIFICANCE

This building contributes to the integrity of design, workmanship, setting, and sense of time and place of Singer's Tavern Group.

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 2-23 (Also see Building No. 668)

18. LOCATED IN AN HISTORIC DISTRICT? ☐ YES ☒ NO ☐ NAME

19. PUBLIC ACCESSIBILITY ☒ YES, LIMITED ☐ YES, UNLIMITED ☐ NO ☐ UNKNOWN

20. EXISTING SURVEY ☐ NPS ☐ NHL ☐ HABS ☐ HAER-1 ☐ HAER ☒ NPS ☐ STATE ☐ COUNTY ☐ LOCAL ☐ OTHER

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge,"
National Park Service, Pacific Northwest Region.

22. INVENTORIED BY Leslie Helm/Gail E.H. Evans AFFILIATION National Park Service DATE 9/82, 1984

PNR-100 6/82

PNRO INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division

Westin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO. 		2. NAME(S) OF STRUCTURE 670 CABIN 8 & 9 (Singer's Tavern)		3. ORIGINAL USE Resort Cabin	4. CLASSIFICATION	5. RATING
3. SITE ADDRESS (STREET & NO.) Barnes Point; Lake Crescent; Highway 101		6. PRESENT USE Seasonal Resort Cabin		7. DATE 1915		
4. CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		5. COUNTY Clallam		6. STATE Washington		
12. OWNER/ADMIN ADDRESS Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362		8. UTM ZONE 10		9. EASTING 440575		10. NORTHING 5322750
		SCALE 1:24 OTHER (1:625)		QUAD NAME Lake Crescent		11. REGION PNR

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Cabin 8 & 9 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin, and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble, it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact.


U-shape in plan; each unit measures 12' x 14' with 4' wide porch extending across the main facade; 1 story; wood-frame wall construction with shingle siding; roof consists of two gables with connecting cross gable; wood shingle roof; post and pier foundation; multi-light, single-leaf casement windows frame multi-pane glass and wood door on main (north) elevation; multi-light projected casement windows on south elevation; shed roof over front porch supported by posts supporting plate. Alterations: none apparent. Siting: in row arrangement with other cabins, approx. 25 yards from Lake Crescent in a grove of trees; part of the Singer's Tavern building group.

14. CONDITION	☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	☒ YES	☐ NO	☐ UNKNOWN
---------------	------------------------------------	-------------------------------	--	---------------------------------------	--------------------------------	---	---	-----------------------------	----------------------------------

16. SIGNIFICANCE

This building contributes to the integrity of design, workmanship, setting and sense of time and place of Singer's Tavern group.

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 37:7

18. LOCATED IN AN HISTORIC DISTRICT?		☐ YES	☒ NO	☐ NAME
19. PUBLIC ACCESSIBILITY		☒ YES, LIMITED	☐ YES, UNLIMITED	
		☐ NO	☐ UNKNOWN	
20. EXISTING SURVEYS		☐ NR	☐ NHL	☐ HABS
		☐ COUNTY	☐ LOCAL	☐ OTHER
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER		☐ HAER-1	☐ HAER	☒ NPS
				☐ STATE

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge." National Park Service, Pacific Northwest Region.

22. INVENTORIED BY	AFFILIATION	DATE
Leslie Helm/Gail E. H. Evans	National Park Service	9/82, 1984

PNR-100 6/82

PNRO INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division

Westin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1 SITE I.D. NO		2 NAME(S) OF STRUCTURE 671 CABIN 10, 11 & 12 (Singer's Tavern)		5. ORIGINAL USE Resort Cabin		7. CLASSIFICATION		9. RATING	
3 SITE ADDRESS (STREET & NO.) Barnes Point; Lake Crescent; Highway 101		6. PRESENT USE Seasonal Resort Cabin						10. DATE 1915	
4 CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		COUNTY STATE		8 UTM ZONE EASTING NORTHING		11. REGION PNR			
				SCALE 1:24 (1:625) OTHER		QUAD NAME Lake Crescent			

12 OWNER/ADMIN ADDRESS

Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362

13 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Cabin 10, 11 & 12 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin, and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble, it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact.


Irregular in shape; overall measurement 58' x 14' with 4' wide porch on north elevation; 1 story; wood-frame wall construction; shingle siding; 3 gables with 1 cross gable; shingle roofing material; post and pier foundation; multi-light casement windows frame multi-light glass and wood doors on main facade; projected casement windows on south elevation; shed roof porch supported by square posts under plate. Alterations: none apparent. Siting: approx. 25 yards from Lake Crescent in row arrangement with other cabins: part of the Singer's Tavern building group.

14. CONDITION					15. DANGER OF DEMOLITION? (SPECIFY THREAT)				
☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	☒ YES	☐ NO	☐ UNKNOWN		

16. SIGNIFICANCE

This building contributes to the integrity of design, workmanship, setting, and sense of time and place of Singer's Tavern Group.

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 37:9

18. LOCATED IN AN HISTORIC DISTRICT?		☐ YES	☒ NO	☐ NAME
19. PUBLIC ACCESSIBILITY		☒ YES, LIMITED	☐ YES, UNLIMITED	
		☐ NO	☐ UNKNOWN	
20. EXISTING SURVEYS		☐ NPS	☐ NHL	☐ HABS
		☐ COUNTY	☐ LOCAL	☐ OTHER
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER		☐ HAER-1	☐ HAER	☒ NPS
				☐ STATE

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge."
National Park Service, Pacific Northwest Region.


22. INVENTORIED BY	Leslie Helm/Gail E.H. Evans	AFFILIATION	National Park Service	DATE	9/82, 1984
--------------------	-----------------------------	-------------	-----------------------	------	------------

PNR-100 6/82

**PNRO
INVENTORY**National Park Service
Pacific Northwest Region
Cultural Resources DivisionWestin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO. 		2. NAME(S) OF STRUCTURE 672 CABINS 14 & 15 (Singer's Tavern)		5. ORIGINAL USE Resort Cabin	7. CLASSIFICATION	9. RATING
3. SITE ADDRESS (STREET & NO.) Barnes Point; Lake Crescent; Highway 101		6. PRESENT USE Seasonal Resort Cabin		10. DATE 1915		
4. CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		COUNTY		STATE		
12. OWNER/ADMIN ADDRESS Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362		13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Cabin 14 & 15 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin, and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble, it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact. U-shape in plan; each unit measures 12' x 14' with 4' wide porch extending across the main facade; 1 story; wood-frame wall construction with shingle siding; roof consists of two gables with connecting cross gable; wood shingle roof; post and pier foundation; multi-light, single leaf casement windows frame multi-pane glass and wood door on main (north) elevation; multi-light projected casement windows on south elevation; shed roof over front porch supported by posts supporting plate. Alterations: none apparent. Siting: in row arrangement with other cabins, approx. 25 yards from Lake Crescent in a grove of trees; part of the Singer's Tavern building group.		11. REGION PNR		
14. CONDITION ☐ EXCELLENT ☐ GOOD ☒ FAIR ☐ DETERIORATED ☐ RUINS		15. DANGER OF DEMOLITION? (SPECIFY THREAT)		16. SIGNIFICANCE This building contributes to the integrity of design, workmanship, setting, and sense of time and place of Singer's Tavern Group.		

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 37:10

18. LOCATED IN AN HISTORIC DISTRICT?		☐ YES	☒ NO	☐ NAME
19. PUBLIC ACCESSIBILITY		☒ YES, LIMITED	☐ YES, UNLIMITED	
		☐ NO	☐ UNKNOWN	
20. EXISTING SURVEY		☐ NR	☐ NHL	☐ HABS
		☐ COUNTY	☐ LOCAL	☐ OTHER
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER		☐ HAER-1	☐ HAER	☒ NPS
				☐ STATE

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge."
National Park Service, Pacific Northwest Region.

22. INVENTORIED BY	Leslie Helm/Gail E. H. Evans	AFFILIATION	National Park Service	DATE	9/82, 1984
--------------------	------------------------------	-------------	-----------------------	------	------------

PNR-100 6/82

**PNRO
INVENTORY**National Park Service
Pacific Northwest Region
Cultural Resources DivisionWestin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO. 		2. NAME(S) OF STRUCTURE 673 CABIN 16, 17 & 18 (Singer's Tavern)		3. ORIGINAL USE Resort Cabin	4. CLASSIFICATION	5. RATING
3. SITE ADDRESS (STREET & NO.) Barnes Point; Lake Crescent; Highway 101		6. PRESENT USE Seasonal Resort Cabin		7. DATE 1915		
4. CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		COUNTY STATE		8. UTM ZONE EASTING NORTHING		9. REGION PNR
12. OWNER/ADMIN ADDRESS Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362		SCALE 1:24 (1:625) OTHER		QUAD NAME Lake Crescent		

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.


Cabin 16, 17 & 18 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin, and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble, it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact.

Irregular in shape; overall measurement 58' x 14' with 4' wide porch on north elevation; 1 story; wood-frame wall construction; shingle siding; 3 gables with 1 cross gable; shingle roofing material; post and pier foundation; multi-light casement windows frame multi-light glass and wood doors on main facade; projected casement windows on south elevation; shed roof porch supported by square posts under plate. Alterations: none apparent. Siting: approx. 25 yards from Lake Crescent in row arrangement with other cabins; part of the Singer's Tavern building group.

14. CONDITION	☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	☒ YES	☐ NO	☐ UNKNOWN
---------------	------------------------------------	-------------------------------	--	---------------------------------------	--------------------------------	---	---	-----------------------------	----------------------------------

16. SIGNIFICANCE
This building contributes to the integrity of design, workmanship, setting, and sense of time and place of Singer's Tavern Group.

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 37:11

18. LOCATED IN AN HISTORIC DISTRICT? ☐ YES ☒ NO ☐ NAME		20. EXISTING SURVEYS ☐ NR ☐ NHL ☐ HABS ☐ HAER-1 ☐ HAER ☒ NPS ☐ STATE	
19. PUBLIC ACCESSIBILITY ☒ YES, LIMITED ☐ YES, UNLIMITED ☐ NO ☐ UNKNOWN		☐ COUNTY ☐ LOCAL ☐ OTHER	
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER			

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge." National Park Service, Pacific Northwest Region.

22. INVENTORIED BY: Leslie Helm/Gail E.H. Evans	AFFILIATION: National Park Service	DATE: 9/82, 1984
---	------------------------------------	------------------

PNR-100 6/82

**PNRO
INVENTORY**National Park Service
Pacific Northwest Region
Cultural Resources DivisionWestin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO		2. NAME(S) OF STRUCTURE 674 CABIN 20 & 21 (Singer's Tavern)		5. ORIGINAL USE Resort Cabin		7. CLASSIFICATION		9. RATING	
3. SITE ADDRESS (STREET & NO.) Barnes Point; Lake Crescent; Highway 101		6. PRESENT USE Seasonal Resort Cabin						10. DATE 1915	
4. CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		STATE Washington		8. UTM ZONE 10		EASTING 440575		NORTHING 5322800	
				SCALE 1:24 OTHER		QUAD NAME Lake Crescent		11. REGION PNR	

12. OWNER/ADMIN ADDRESS
Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTANT EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Cabin 20 and 21 was erected in 1915, the first year of operation of Singer's Lake Crescent Tavern. This cabin, and others adjoining it in a row to the east of the main lodge, was among the first twenty sleeping cabins built at the resort. Although little is known of the social history of the cabin, as part of the Singer's resort building ensemble, it played a significant role in the early resort development of Lake Crescent and the north Olympic Peninsula. Even though several cabins in the row of eight have been remodeled on the interior and have received new foundation supports, new roofs, and new porches, the integrity of scale, design, materials, and setting of the entire row has remained largely intact.


Rectangular in shape; measures 14' x 23'6" with 4' wide porch; 1 story; wood-frame wall construction; shingle siding; 2 adjoining gable roofs with wood shingle roofing material; multi-light projected casement windows frame doorway on north elevation; small light windows on upper portion of door; post and pier foundation; shed roof over porch supported by square posts under horizontal plate. Alterations: removal of cabin unit attached to south wall of building since 1952 (?). Siting: approx. 20 yards from Lake Crescent shoreline in partially shaded area; part of Singer's Tavern building ensemble.

14. CONDITION					15. DANGER OF DENOLITION? (SPECIFY THREAT)				
☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	☒ YES	☐ NO	☐ UNKNOWN		

16. SIGNIFICANCE

This building contributes to the integrity of design, workmanship, setting, and sense of time and place of Singer's Tavern Group.

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 37:13

18. LOCATED IN AN HISTORIC DISTRICT?		☐ YES ☒ NO ☐ NAME		20. EXISTING SURVEYS		☐ NR ☐ NHL ☐ HABS ☐ HAER-1 ☐ HAER ☒ NPS ☐ STATE	
19. PUBLIC ACCESSIBILITY		☒ YES, LIMITED ☐ YES, UNLIMITED ☐ NO ☐ UNKNOWN		☐ COUNTY ☐ LOCAL ☐ OTHER			
21. REFERENCES--HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER							

Florence, Hank, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge." National Park Service, Pacific Northwest Region.

22. INVENTORIED BY	Gail E. H. Evans	AFFILIATION	National Park Service	DATE	9/82, 1984
--------------------	------------------	-------------	-----------------------	------	------------

HABS
WASH,
S-POAN.V,
1-E-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

Singer's Lake Crescent Tavern (Lake Crescent Lodge),
Cabins 3-21 (Bldg. Nos. 668-674)
Barnes Point, Lake Crescent
Olympic National Park
Port Angeles Vicinity
Clallam County
Washington

HABS No. WA-186-E

Marty Stupich, Photographer Summer 1983

NOTE: These photographs are full-frame 4" x 5" enlargements from 2-1/4" x 2-1/4" negatives.

WA-186-E-1 GENERAL VIEW OF CABIN GROUP, LOOKING WEST

WA-186-E-2 GENERAL VIEW OF CABIN GROUP, LOOKING SOUTH

WA-186-E-3 LAKE CRESCENT LODGE CABIN 668, DETAIL OF REAR, LOOKING WEST

WA-186-E-4 LAKE CRESCENT LODGE CABIN 669, WEST FACADE, LOOKING NORTHEAST

WA-186-E-5 LAKE CRESCENT LODGE CABIN 670, WEST ELEVATION, LOOKING EAST

WA-186-E-6 LAKE CRESCENT LODGE CABIN 671, WEST FACADE, LOOKING SOUTHEAST

WA-186-E-7 LAKE CRESCENT LODGE CABIN 672, WEST ELEVATION, LOOKING EAST

WA-186-E-8 LAKE CRESCENT LODGE CABIN 673, WEST ELEVATION, LOOKING EAST

WA-186-E-9 LAKE CRESCENT LODGE CABIN 674, WEST ELEVATION, LOOKING EAST

NOTE: For additional written historical and descriptive data, please see the main entry for Singer's Lake Crescent Tavern (Lake Crescent Lodge), HABS No. WA-186.

OLYM 668-673



HABS NO. WA-186-E-1

10444/ OLYN 668-673



HABS NO. WA-186-E-2

OLYM 668-~~568~~ VIEW 2



HABS NO. WA-186-E-3



OLYM 669 VIEW 1

HABS NO. WA-186-E-4

OLYN 670 VIEW 1

KODAK SAFETY FILM 6057



HABS No. WA-136-E-5

→10

OLYM 674 VIEW 1



HABS NO. WA-186-E-6

OLYM 672 VIEW 1



HAB. NO. 100-137-2

OLYM 673

VIEW 1



HABS No. WA-184-E-6

OLYM 674 VIEW 1



HABS NO. WA-186-E-9