

Singer's Lake Crescent Tavern (Lake Crescent Lodge),
Storage Building (Generator/Tool Shed, Bldg. No., 682)
Barnes Point, Lake Crescent
Olympic National Park
Port Angeles Vicinity
Clallam County
Washington

HABS No. WA-186-L

HABS
WASH.
S-POAN.V,
1-L-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL PARK SERVICE
PACIFIC NORTHWEST REGION
DEPARTMENT OF INTERIOR
SEATTLE, WASHINGTON

PNR-100 6/82

**PNRO
INVENTORY**National Park Service
Pacific Northwest Region
Cultural Resources DivisionWestin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

1. SITE I.D. NO. 		5. ORIGINAL USE Storage		7. CLASSIFICATION		9. RATING	
2. NAME(S) OF STRUCTURE 682 TOOL SHED/(GENERATOR STORAGE) (Singer's Tavern)		6. PRESENT USE Storage				10. DATE c. 1922	
3. SITE ADDRESS (STREET & NO.) Barnes Point, Lake Crescent, Highway 101				11. REGION PNR			
4. CITY/VICINITY Approx. 20 miles S.W. of Port Angeles, Clallam, Washington		STATE Washington		SCALE 1:24 (1:525)		QUAD NAME Lake Crescent	
12. OWNER/ADMIN ADDRESS Department of the Interior, National Park Service, Olympic National Park, 600 East Park Ave., Port Angeles, WA 98362							

13. DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, EXISTING EQUIPMENT, AND IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

According to OLYM building inventory files, the Tool Shed was constructed in the early 1920s, making it one of more than two dozen buildings erected under Avery and Julia Singer's proprietorship. In design and materials, the building resembles other early Singer resort buildings. Since 1951 wood shingle roofing material has been replaced with rolled roofing material. Little is known of the social history of the Tool Shed. Architecturally, the building is compatible with other early buildings in the Singer's Lake Crescent Tavern building ensemble.

Rectangular in shape; measures 8' x 10'; 1 story; wood-frame wall construction; horizontal rough sawn siding with corner boards. Gable roof with exposed rafters, sheathed with composition rolled roofing material; foundation not visible; 1 small, 4-light window with wide, plain board surrounds; small wood door with cross bracing. Altered: 1 window covered; possible resheathing of exterior walls. Siting: approx. 25' from the west end of the main lodge; near another storage building; part of the Singer's Tavern Group.

14. CONDITION	☐ EXCELLENT	☐ GOOD	☒ FAIR	☐ DETERIORATED	☐ RUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	☐ YES	☐ NO	☒ UNKNOWN
---------------	------------------------------------	-------------------------------	--	---------------------------------------	--------------------------------	---	------------------------------	-----------------------------	---



16. SIGNIFICANCE

This building contributes to the integrity of design, workmanship, setting and sense of time and place of Singer's Tavern Group.

Singer's Lake Crescent Tavern (Lake Crescent Lodge),
Storage Building (Generator/Tool Shed, Bldg. No. 682)
HABS No. WA-186-L
(Page 1)

HABS
WASH
5-POAN
1-L

17. PHOTOS AND SKETCH MAP OF LOCATION



NEG. 37:6

18. LOCATED IN AN HISTORIC DISTRICT? ☐ YES ☒ NO ☐ NAME

19. PUBLIC ACCESSIBILITY ☐ YES, LIMITED ☐ YES, UNLIMITED ☒ NO ☐ UNKNOWN

20. EXISTING SURVEYS ☐ NR ☐ NHL ☐ HABS ☐ HAER-1 ☐ HAER ☒ NPS ☐ STATE ☐ COUNTY ☐ LOCAL ☐ OTHER

21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Eastman, Leslie W. 1951. Appraisal for United States Department of the Interior, National Park Service, Port Angeles Washington: Lake Crescent Lodge, Land and Improvements, Clallum [sic], Washington.
 Florence, Henry, Cathy Gilbert and Gail Evans. 1984. "Historic Structures Report: Lake Crescent Lodge."
 National Park Service, Pacific Northwest Region.

22. INVENTORIED BY Gail E. H. Evans/Leslie Helm AFFILIATION National Park Service DATE 9/82, 1984

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
WASH,
5-POAN.V
1-L-

Singer's Lake Crescent Tavern (Lake Crescent Lodge),
Storage Building (Generator/Tool Shed, Bldg. No. 682)
Barnes Point, Lake Crescent
Olympic National Park
Port Angeles Vicinity
Clallam County
Washington

HABS No. WA-186-L

Marty Stupich, Photographer Summer 1983

NOTE: These photographs are full-frame 4" x 5" enlargements from 2-1/4" x 2-1/4" negatives.

WA-186-L-1 SOUTHEAST FACADE, LOOKING SOUTHWEST

NOTE: For additional written historical and descriptive data, please see the main entry for Singer's Lake Crescent Tavern (Lake Crescent Lodge), HABS No. WA-186.

OLYM 682



HABS No. WA-186-L-1